


NASA TECHNICAL NOTE



NASA TN D-2201

C.1

LOAN COPY: RET
AFWL (WLL-
KIRTLAND AFB,
0154589



TECH LIBRARY KAFB, NM

NASA TN D-2201

**LONGITUDINAL AERODYNAMIC
CHARACTERISTICS OF BLUNTED CONES
AT MACH NUMBERS OF 3.5, 4.2, AND 6.0**

by J. Wayne Keyes

*Langley Research Center
Langley Station, Hampton, Va.*

TECH LIBRARY KAFB, NM



0154589

**LONGITUDINAL AERODYNAMIC CHARACTERISTICS OF BLUNTED CONES
AT MACH NUMBERS OF 3.5, 4.2, AND 6.0**

By J. Wayne Keyes

**Langley Research Center
Langley Station, Hampton, Va.**

NATIONAL AERONAUTICS AND SPACE ADMINISTRATION

**For sale by the Office of Technical Services, Department of Commerce,
Washington, D.C. 20230 -- Price \$1.75**

LONGITUDINAL AERODYNAMIC CHARACTERISTICS OF BLUNTED CONES

AT MACH NUMBERS OF 3.5, 4.2, AND 6.0

By J. Wayne Keyes

SUMMARY

Force and moment data were obtained for a family of low-fineness-ratio blunted-cone configurations. Each configuration had a nose bluntness ratio of 0 (spherical cap), 0.50, or 0.75, fineness ratio of 0.50, 0.75, or 1.00, cone half-angle of 10°, 15°, or 20°, and flat, convex (23.58° and 40°), concave, or conical (66.42° and 50° half-angle) base shape. The test Reynolds number varied from 2.3×10^6 to 5.5×10^6 , based on a 4-inch model base diameter.

The results of the investigation indicate that nose bluntness had little effect on the stability characteristics at angles of attack α of 0° and 180°. An increase in fineness ratio or a decrease in cone half-angle resulted in a decrease in stability near $\alpha = 0^\circ$ and had no effect at $\alpha = 180^\circ$. Of the base shapes studied only the 50° half-angle conical base was unstable at $\alpha = 180^\circ$ for the forebody configuration having a spherical-cap nose, fineness ratio of 1.00, and 15° cone half-angle. Estimated variations of the aerodynamic characteristics with angle of attack obtained by means of modified Newtonian theory were in good agreement with the measured results.

INTRODUCTION

An investigation of the nature of the atmospheres of near Earth planets (Mars and Venus) is of great importance to the space research program. A desirable method of obtaining direct measurements of the properties of a planetary atmosphere would be the passage of a probe vehicle through the atmosphere. In order to insure that the vehicle is oriented properly, it should be designed so that aerodynamic forces maintain a nose-forward attitude throughout the trajectory (see ref. 1).

As part of an overall research program at the Langley Research Center, an investigation was conducted in the Langley 20-inch variable Mach number tunnel on a complete family of low-fineness-ratio blunted-cone configurations, some of which could be used as possible planetary probe vehicles. The purpose of the investigation was to establish the aerodynamic characteristics of this family of blunted-cone configurations over an angle-of-attack range from 0° to 180°, while varying such geometric parameters as nose bluntness ratio, fineness ratio, cone half-angle, and base shape, and in particular to find a base shape that

would be unstable at 180° . The tests were conducted at Mach numbers of 3.5, 4.2, and 6.0. Similar configurations have been tested at Mach numbers from 0.65 to 15 and are discussed in references 2 to 11.

This paper presents the results of the experimental investigation and of a comparison of the measured data with estimations obtained by modified Newtonian theory.

SYMBOLS

a	diameter of front face of cone frustum, in.
b	diameter of flat face of model nose, in.
C_A	body axial-force coefficient, $F_A/q_\infty S$
C_D	drag coefficient, $D/q_\infty S$
C_L	lift coefficient, $L/q_\infty S$
C_m	pitching-moment coefficient, $M/q_\infty Sd$
C_N	body normal-force coefficient, $F_N/q_\infty S$
D	drag, lb
d	diameter of model base, in.
F_A	axial force, lb
F_N	normal force, lb
K	nose bluntness, b/a (see fig. 2(a))
L	lift, lb
ℓ	length of model forebody, in.
M_∞	free-stream Mach number
M	pitching moment, in-lb
q_∞	free-stream dynamic pressure, lb/sq in. abs
r	nose-edge radius, in. (see fig. 2(b))
S	base area of model, sq in.
α	angle of attack of model center line, deg
α_i	angle between model center line and sting center line, deg

θ cone half-angle, deg

λ fineness ratio, l/d

APPARATUS, TESTS, AND MODELS

Tunnels

This investigation was conducted in the Langley 20-inch variable Mach number tunnel and the Langley 20-inch Mach 6 tunnel both of which are the intermittent type exhausting into the atmosphere. The variable Mach number tunnel can operate at Mach numbers from 3 to 5 and stagnation pressures from 5 to 20 atmospheres depending on the Mach number. The Mach 6 tunnel can operate at stagnation pressures from 18 to 35 atmospheres and stagnation temperatures up to 600° F. A more complete description of these tunnels is given in reference 12.

Sting and Support System

The support system in the variable Mach number tunnel operates in the vertical plane with a support angle-of-attack range from about -20° to 20°, whereas the Mach 6 tunnel has a gooseneck type of support system which operates in the horizontal plane with a support angle-of-attack range from about -15° to 30°. In order to cover the complete model angle-of-attack range with minimum sting effects, two stings were used in conjunction with the three model mounting positions shown in figure 1. Model and sting positions for each tunnel are given in the following table:

Angle-of-attack range, deg	Sting angle, deg	Model position, α_i , deg
Variable Mach number tunnel		
-5 to 20	0	0
17 to 50	30 (bent)	0
45 to 79	30 (bent)	90
75 to 110	0	90
107 to 140	30 (bent)	90
135 to 169	30 (bent)	180
165 to 185	0	180
Mach 6 tunnel		
-5 to 30	0	0
15 to 60	30 (bent)	0
60 to 105	0	90
75 to 120	0	90
120 to 165	30 (bent)	180
150 to 185	0	180

Tests

The tests were conducted at Mach numbers of 3.5, 4.2, and 6.0 with stagnation pressures of about 6, 12.5, and 25 atmospheres, respectively, and Reynolds numbers based on a 4-inch model base diameter of 3.7×10^6 , 5.5×10^6 , and 2.3×10^6 , respectively. Tunnel stagnation temperature was ambient temperature for $M_\infty = 3.5$ and 4.2 and $400^\circ F$ for $M_\infty = 6.0$. The model angle of attack varied from -5° to 185° .

Models

The models were designed to form a systematic variation in the following geometric parameters: nose bluntness K , fineness ratio λ , cone half-angle θ , and base shape. Each configuration was designated by a four-digit code which is defined in the following table:

Digit	Code	Parameter			Base shape
		K	λ	θ	
First	1	0 (spherical cap)			
	2	0.50			
	3	.75			
Second	1		0.50		
	2		.75		
	3		1.00		
Third	1			10	
	2			15	
	3			20	
Fourth	1				Flat
	2				23.58° convex
	3				Concave
	4				66.42° half-angle cone
	5				40° convex
	6				50° half-angle cone

For example, model 1221 has a spherical-cap nose, fineness ratio of 0.75, cone half-angle of 15° , and flat base.

A sketch of a model showing design dimensions, nose shapes, and base shapes is presented in figure 2. Bases 2 and 4 were similar in that both had the same tangent angle (23.58°) at the point of intersection of the model forebody and the base. Bases 5 and 6 also had the same tangent angle (40°). Bases 2 and 3 had the same spherical radius of 1.25 base diameters, whereas base 5 had a spherical radius of 0.778 base diameter. All dimensions were based on a model

base diameter of 4 inches except those for the models with a fineness ratio of 0.50 mounted in the $\alpha_1 = 90^\circ$ position (fig. 1) and these dimensions were based on a base diameter of 6 inches. Photographs of model 1221 mounted in the variable Mach number tunnel are shown as figure 3.

MEASUREMENTS AND ACCURACY

Aerodynamic forces and moments were measured by a six-component strain-gage balance. The force and moment coefficients are referred to the body-axis system shown in figure 1. For all models the moment center was located at a point one-third of the forebody length forward of the maximum model diameter. The axial-force coefficient has not been corrected for base pressure effects. All measured data (C_N , C_A , and C_m) are presented in table I along with calculated values of C_L and C_D .

On the basis of calibrations and repeatability of data it is estimated that the measured quantities are accurate within the following limits:

	$M_\infty = 3.5$	$M_\infty = 4.2$	$M_\infty = 6.0$
C_A	± 0.014	± 0.012	± 0.024
C_N	$\pm .016$	$\pm .014$	$\pm .029$
C_m	$\pm .008$	$\pm .007$	$\pm .015$

The accuracy of angle of attack and of free-stream Mach number is estimated to be within ± 0.10 and ± 0.03 , respectively.

Examination of the tabulated data indicates that there are offset discontinuities in the variation of the coefficients with angle of attack at which changes are made in the mounting position of the model to the sting. Apparently there are varying influences of the sting on the model characteristics depending on where the sting is attached to the model. Therefore, in order to use the tabulated data for any given configuration, the data should be first plotted and faired over the complete angle-of-attack range.

RESULTS AND DISCUSSION

The method of presenting the plotted data consists of choosing configurations from table I to show the effect of Mach number (fig. 4), nose bluntness (fig. 5), fineness ratio (fig. 6), cone half-angle (fig. 7), and base shape (fig. 8) on the longitudinal aerodynamic characteristics. The effects of the last four variations are presented by holding three of the geometric parameters constant and then varying the fourth. For example, figure 5 shows the effect of nose bluntness by using configurations 1221, 2221, and 3221. Theoretical estimations of the variation of the aerodynamic characteristics with angle of

attack are presented for comparison with the measured data in figures 5 to 9. Modified Newtonian theory was used to calculate these estimations based on the methods of references 6 and 13 by using the stagnation pressure behind a normal shock. In general, values obtained from use of modified Newtonian theory give a good indication of the trend of the experimental data, as shown in references 3, 5, and 6.

Mach Number

It can be seen from figure 4 that the effect of Mach number is small and does not affect the overall trend of the data. The same is true for any given configuration listed in table I. Therefore, only data for $M_\infty = 6.0$ are presented in the figures for geometric variations of the model.

Nose Bluntness

Figure 5(a) shows that nose bluntness has little effect on the stability characteristics of configurations 1221, 2221, and 3221 at $\alpha = 0^\circ$ or $\alpha = 180^\circ$. Modified Newtonian theory did not indicate that the trim point at $\alpha = 180^\circ$ would be stable. However, the theory did give a good indication of the trend of the variation of the measured coefficients with angle of attack.

Fineness Ratio

The trend of decreasing stability with an increase in fineness ratio at the lower angles of attack is shown in figure 6(a). This trend was also observed in references 10 and 11. The configurations with fineness ratios of 0.50 and 0.75 are stable, whereas the configuration with a fineness ratio of 1.00 is unstable at $\alpha = 0^\circ$, as was also observed in reference 11. In addition, figure 6(a) shows that the variation of fineness ratio has no effect on the stable trim point at $\alpha = 180^\circ$ for the flat-base model. As the fineness ratio increases, the spherical-cap portion of each configuration is reduced with a resulting decrease in axial-force coefficient near $\alpha = 0^\circ$.

Cone Half-Angle

In figure 7(a) a decrease in stability is indicated near $\alpha = 0^\circ$ for a decrease in cone half-angle. Also, the stable trim point at $\alpha = 180^\circ$ remains unchanged with increases in cone half-angle. A decrease in axial-force coefficient occurs with an increase in cone half-angle at the low angles of attack but to a lesser degree than that observed for an increase in fineness ratio.

Base Shape

Varying the base shape had a negligible effect on the aerodynamic characteristics up to an angle of attack where the base is no longer shielded from

the flow. Beyond this angle of attack there is a pronounced effect on C_m and C_A . (See fig. 8(a).) However, not one of the three base shapes (flat, 23.58° convex, or concave) could eliminate the stable trim point at $\alpha = 180^\circ$. Both the 66.42° half-angle conical and the 40° convex bases were stable at 180° , whereas the 50° half-angle conical base was unstable for the moment-center location and forebody configuration chosen (fig. 9(a)). Modified Newtonian theory gives a good estimation of the trend of the data near $\alpha = 180^\circ$ for all base shapes except the flat and concave bases. The movement of the moment center to the center of volume of the configuration of figure 9(a) had no effect on the pitching-moment characteristics near $\alpha = 180^\circ$, as shown in figure 9(b).

CONCLUSIONS

The results of an investigation of a family of low-fineness-ratio blunted-cone configurations with varying nose bluntness, fineness ratio, cone half-angle, and base shape at Mach numbers of 3.5, 4.2, and 6.0 indicate the following conclusions:

1. Nose bluntness had little effect on the stability characteristics at angles of attack of 0° and 180° .
2. An increase in fineness ratio or a decrease in forebody cone half-angle resulted in a decrease in stability characteristics near 0° angle of attack and had no effect at 180° .
3. Of the base shapes tested only the 50° half-angle conical base was unstable at 180° angle of attack for the forebody configuration having a spherical-cap nose, fineness ratio of 1.00, and 15° cone half-angle.
4. Generally, modified Newtonian theory estimations were in good agreement with the measured aerodynamic coefficients.

Langley Research Center,
National Aeronautics and Space Administration,
Langley Station, Hampton, Va., November 26, 1963.

REFERENCES

1. Peterson, Victor L.: Motions of a Short 10° Blunted Cone Entering a Martian Atmosphere at Arbitrary Angles of Attack and Arbitrary Pitching Rates. NASA TN D-1326, 1962.
2. Wehrend, William R., Jr.: Wind-Tunnel Investigation of the Static and Dynamic Stability Characteristics of a 10° Semivertex Angle Blunted Cone. NASA TN D-1202, 1962.
3. Treon, Stuart L.: Static Aerodynamic Characteristics of Short Blunt Cones With Various Nose and Base Cone Angles at Mach Numbers From 0.6 to 5.5 and Angles of Attack to 180° . NASA TN D-1327, 1962.
4. Intrieri, Peter F.: Free-Flight Measurements of the Static and Dynamic Stability and Drag of a 10° Blunted Cone at Mach Numbers 3.5 and 8.5. NASA TN D-1299, 1962.
5. Fohrman, Melvin J.: Static Aerodynamic Characteristics of a Short Blunt 10° Semivertex Angle Cone at a Mach Number of 15 in Helium. NASA TN D-1648, 1963.
6. Neal, Luther, Jr.: Aerodynamic Characteristics at a Mach Number of 6.77 of a 9° Cone Configuration, With and Without Spherical Afterbodies, at Angles of Attack up to 180° With Various Degrees of Nose Blunting. NASA TN D-1606, 1963.
7. Letko, William: Experimental Investigation at a Mach Number of 3.11 of the Lift, Drag, and Pitching-Moment Characteristics of a Number of Blunt Low-Fineness-Ratio Bodies. NASA MEMO 1-18-59L, 1959.
8. McDearman, Russell W., and Lawson, Warren A.: Investigation of the Normal-Force, Axial-Force, and Pitching-Moment Characteristics of Blunt Low-Fineness-Ratio Bodies of Revolution at a Mach Number of 3.55. NASA TM X-467, 1961.
9. Wehrend, William R., Jr., and Reese, David E., Jr.: Wind-Tunnel Tests of the Static and Dynamic Stability Characteristics of Four Ballistic Re-Entry Bodies. NASA TM X-369, 1960.
10. Brooks, Cuyler W., Jr., and Trescot, Charles D., Jr.: Transonic Investigation of the Effects of Nose Bluntness, Fineness Ratio, Cone Angle, and Base Shape on the Static Aerodynamic Characteristics of Short, Blunt Cones at Angles of Attack to 180° . NASA TN D-1926, 1963.
11. Shaw, David S., Fuller, Dennis E., and Babb, C. Donald: Effects of Nose Bluntness, Fineness Ratio, Cone Angle, and Model Base on the Static Aerodynamic Characteristics of Blunt Bodies at Mach Numbers of 1.57, 1.80, and 2.16 and Angles of Attack up to 180° . NASA TN D-1781, 1963.

12. Sterrett, James R., and Emery, James C.: Extension of Boundary-Layer-Separation Criteria to a Mach Number of 6.5 by Utilizing Flat Plates With Forward-Facing Steps. NASA TN D-618, 1960.
13. Wells, William R., and Armstrong, William O.: Tables of Aerodynamic Coefficients Obtained From Developed Newtonian Expressions for Complete and Partial Conic and Spheric Bodies at Combined Angles of Attack and Sideslip With Some Comparisons With Hypersonic Experimental Data. NASA TR R-127, 1962.

TABLE I--AERODYNAMIC CHARACTERISTICS OF MODELS

 $M_{\infty} = 3.5$ $M_{\infty} = 4.2$

Configuration	α_s deg	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D
1111	-5.00	-0.0641	.8881	.0110	.0135	.8903	-0.0595	.8850	.0098	.0178	.8868
	-3.00	-.0340	.8907	.0059	.0130	.8993	-.0279	.8895	.0044	.0187	.8898
	-1.00	-.0031	.8968	.0006	.0125	.8968	.0033	.8917	-.0011	.0189	.8915
	.00	.0118	.9035	-.0024	.0118	.9035	.0179	.8927	-.0038	.0179	.8927
	1.00	.0257	.9027	-.0047	.0099	.9030	.0309	.8924	-.0062	.0153	.8928
	3.00	.0541	.9017	-.0096	.0068	.9033	.0590	.8898	-.0105	.0123	.8917
	5.00	.0828	.8997	-.0143	.0001	.9035	.0878	.8883	-.0152	.0101	.8926
	10.00	.1527	.8911	-.0256	-.0043	.9041	.1603	.8839	-.0268	.0044	.8983
	15.00	.2236	.8853	-.0371	-.0131	.9130	.2304	.8721	-.0383	-.0032	.9020
	20.00	.2963	.8760	-.0490	-.0212	.9245	.2996	.8538	-.0498	-.0105	.9048
	16.00	.2466	.8902	-.0418	-.0084	.9237	.2360	.8667	-.0392	-.0120	.8982
	20.00	.3037	.8832	-.0514	-.0167	.9358	.2896	.8537	-.0478	-.0199	.9012
	25.00	.3653	.8587	-.0617	-.0301	.9290	.3534	.8303	-.0584	-.0306	.9019
	30.00	.4266	.8306	-.0719	-.0459	.9326	.4135	.8025	-.0682	-.0432	.9018
	35.00	.4841	.7998	-.0816	-.0621	.9329	.4657	.7680	-.0771	-.0590	.8962
	40.00	.5353	.7712	-.0902	-.0856	.9349	.5139	.7321	-.0854	-.0769	.8911
	45.00	.5727	.7246	-.0965	-.1074	.9174	.5520	.6880	-.0913	-.0962	.8768
	50.00	.5944	.6750	-.0991	-.1350	.8892	.5755	.6115	-.0952	-.1215	.8532
	45.00	.5512	.7128	-.0913	-.1142	.8938	.5371	.7007	-.0880	-.1157	.8753
	50.00	.5741	.6719	-.0948	-.1457	.8717	.5594	.6514	-.0917	-.1394	.8472
	55.00	.5842	.6120	-.0968	-.1662	.8295	.5766	.6039	-.0946	-.1640	.8187
	60.00	.5874	.5748	-.0982	-.2041	.7961	.5761	.5562	-.0952	-.1936	.7770
	65.00	.5824	.5192	-.0979	-.2245	.7472	.5722	.5027	-.0949	-.2138	.7311
	70.00	.5690	.4610	-.0970	-.2386	.6924	.5591	.4469	-.0934	-.2287	.6782
	75.00	.5508	.3995	-.0947	-.2433	.6554	.5437	.3897	-.0915	-.2357	.6261
	75.00	.5342	.3974	-.0936	-.2456	.6189	.5279	.3792	-.0913	-.2297	.6080
	80.00	.5168	.3384	-.0910	-.2436	.5677	.5108	.3225	-.0882	-.2289	.5590
	85.00	.4937	.2723	-.0867	-.2283	.5155	.4829	.2590	-.0830	-.2159	.5037
	90.00	.4668	.1993	-.0809	-.1993	.4668	.4617	.1958	-.0781	-.1958	.4617
	95.00	.4442	.1128	-.0757	-.1511	.4327	.4355	.1192	-.0723	-.1567	.4234
	100.00	.4244	.0209	-.0717	-.0943	.4144	.4072	.0312	-.0670	-.1014	.3956
	105.00	.3993	-.0952	-.0675	-.0113	.4103	.3788	-.0772	-.0613	-.0234	.3859
	110.00	.3742	.2478	-.0624	-.1049	.4364	.3511	-.2232	-.0587	.0896	.4062
	105.00	.3828	.1241	-.0658	-.0208	.4019	.3747	-.1036	-.0621	.0031	.3887
	110.00	.3545	.2916	-.0608	-.1528	.4328	.3443	-.2515	-.0575	.1185	.4095
	115.00	.3278	.4580	-.0539	-.2766	.4907	.3161	-.4164	-.0506	.2438	.4625
	120.00	.2971	.6150	-.0445	-.4100	.5798	.2840	-.6045	-.0428	.3805	.5500
	125.00	.2678	.8435	-.0332	.5374	.7032	.2532	-.8097	-.0321	.5181	.6718
	130.00	.2302	-.1.0371	-.0189	.6465	.8429	.2144	-.1.0056	-.0180	.6525	.8106
	135.00	.1857	-.1.2214	-.0036	.7324	.9950	.1701	-.1.2051	-.0024	.7318	.9724
	135.00	.1534	-.1.2603	-.0008	.7827	.9997	.1443	-.1.2103	-.0001	.7538	.9578
	140.00	.1133	-.1.3842	-.0134	.8029	1.1332	.1106	-.1.3502	-.0111	.7832	1.1054
	145.00	.0786	-.1.4852	-.0221	.7875	1.2617	.0784	-.1.4557	-.0230	.7708	1.2374
	150.00	.0502	-.1.5426	-.0249	.7278	1.3610	.0545	-.1.5352	-.0276	.7204	1.3568
	155.00	.0295	-.1.6024	-.0259	.6505	1.4648	.0339	-.1.6009	-.0297	.6459	1.4652
	160.00	.0100	-.1.6508	-.0235	.5552	1.5546	.0152	-.1.6402	-.0275	.5467	1.5465
	165.00	.0007	-.1.6897	-.0185	.4366	1.6323	.0060	-.1.6749	-.0235	.4277	1.6194
	169.00	-.0018	-.1.7134	-.0120	.3287	1.6816	.0021	-.1.6955	-.0184	.3214	1.6648
	165.00	-.0024	-.1.6269	-.0227	.4186	1.5722	.0065	-.1.6581	-.0235	.4228	1.6033
	170.00	-.0011	-.1.6604	-.0163	.2894	1.6350	.0021	-.1.6722	-.0170	.2883	1.6472
	175.00	-.0004	-.1.6597	-.0100	.1451	1.6534	.0035	-.1.6963	-.0094	.1443	1.6902
	177.00	-.0003	-.1.6767	-.0073	.0861	1.6744	.0035	-.1.7009	-.0071	.0855	1.6988
	179.00	-.0022	-.1.6843	-.0055	.0316	1.6840	.0048	-.1.7042	-.0034	.0249	1.7040
	180.00	-.0002	-.1.6891	-.0041	.0002	1.6891	.0048	-.1.7046	-.0013	.0048	1.7046
	181.00	.0032	-.1.6930	-.0014	-.0327	1.6926	.0049	-.1.7060	-.0011	.0347	1.7056
	183.00	.0052	-.1.6938	-.0005	-.0393	1.6912	.0055	-.1.7018	-.0039	-.0946	1.6992
	185.00	.0026	-.1.6953	-.0037	-.1504	1.6887	.0044	-.1.7025	-.0069	-.1.528	1.6956
1211	-5.00	-.0944	.7493	-.0007	-.0287	.7547	-.0936	.7475	-.0008	-.0280	.7529
	-3.00	-.0562	.7547	-.0017	-.0166	.7566	-.0553	.7522	-.0008	-.0158	.7541
	-1.00	-.0229	.7603	-.0020	-.0096	.7606	-.0214	.7548	-.0016	-.0082	.7551
	.00	-.0046	.7626	-.0026	-.0046	.7626	-.0038	.7551	-.0020	-.0038	.7551
	1.00	.0138	.7663	-.0034	-.0004	.7664	-.0144	.7551	-.0029	-.0012	.7553
	3.00	.0493	.7675	-.0045	-.0090	.7690	-.0493	.7600	-.0035	-.0094	.7616
	5.00	.0826	.7686	-.0051	-.0153	.7729	-.0848	.7523	-.0043	-.0189	.7568
	10.00	.1743	.7709	-.0071	-.0378	.7895	.1719	.7567	-.0057	-.0379	.7751
	15.00	.2624	.7735	-.0097	-.0533	.8150	.2608	.7548	-.0080	-.0565	.7966
	20.00	.3558	.7715	-.0125	.0704	.8467	.3517	.7472	-.0110	.0749	.8224
	17.00	.3155	.7683	-.0084	.0771	.8269	.3007	.7209	-.0059	.0768	.7773
	20.00	.3715	.7576	-.0107	.0900	.8390	.3586	.7260	-.0081	.0887	.8048
	25.00	.4712	.7558	-.0148	.1077	.8841	.4532	.7175	-.0125	.1075	.8418
	30.00	.5669	.7415	-.0202	.1201	.9257	.5407	.7038	-.0169	.1164	.8799
	35.00	.6561	.7259	-.0259	.1210	.9709	.6344	.6895	-.0236	.1242	.9287
	40.00	.7511	.7107	-.0323	.1140	1.0233	.7068	.6714	-.0255	.1098	.9866
	45.00	.8203	.6871	-.0363	.0941	1.0659	.7921	.6459	-.0348	.1034	1.0168
	50.00	.8789	.6595	-.0393	.0597	1.0972	.8502	.6192	-.0390	.0722	1.0493
	45.00	.7935	.6292	-.0416	.1162	1.0660	.7648	.6181	-.0390	.1037	.9779
	50.00	.8520	.6007	-.0447	.0875	1.0388	.8279	.5959	-.0409	.0757	1.0172
	55.00	.8870	.5663	-.0465	.0449	1.0514	.8659	.5715	-.0429	.0286	1.0371
	60.00	.9048	.5369	-.0481	-.0126	1.0521	.8898	.5358	-.0455	-.0191	1.0385
	65.00	.9125	.4989	-.0521	-.0666	1.0378	.8951	.4990	-.0490	-.0739	1.0221
	70.00	.9079	.4521	-.0545	-.1143	1.0077	.8914	.4547	-.0516	-.1224	.9931
	75.00	.8999	.3997	-.0598	-.1532	.9727	.8805	.4033	-.0562	-.1617	.9549
	79.00	.8842	.3550	-.0674	-.1798	.9357	.8641	.3606	-.0595	-.1891	.9170

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_\infty = 3.5$										$M_\infty = 4.2$									
Config-	deg	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D			
1211	75.00	.8428	.3824	-.0618	-.1513	.9131	.8574	.3968	-.0581	-.1614	.9309	.8574	.3404	-.0612	-.1899	.8834	.0214		
	80.00	.8251	.3278	-.0652	-.1795	.8695	.8370	.3404	-.0612	-.1899	.8834								
1212	85.00	.8026	.2688	-.0676	-.1978	.8230	.8111	.2787	-.0638	-.2069	.8323	.8574	.3404	-.0612	-.1899	.8834	.0214		
	90.00	.7787	.1984	-.0685	-.1984	.7787	.7833	.2133	-.0650	-.2133	.7833								
	95.00	.7586	.1223	-.0689	-.1879	.7450	.7528	.1372	-.0649	-.2023	.7379								
	100.00	.7280	.0263	-.0684	-.1523	.7123	.7168	.0495	-.0650	-.1732	.6973								
	105.00	.6965	-.0902	-.0680	-.0932	.6961	.6808	-.0604	-.0653	-.1179	.6732								
	110.00	.6639	-.2361	-.0664	-.0052	.7047	.6429	-.2014	-.0647	-.0306	.6730								
	107.00	.6952	-.1216	-.0676	-.0870	.7004	.6547	-.1022	-.0650	-.0937	.6560								
	110.00	.6724	-.2158	-.0667	-.0272	.7056	.6300	-.2009	-.0641	-.0267	.6607								
	115.00	.6292	-.4084	-.0612	.1042	.7429	.5743	.3777	-.0592	-.0996	.6801								
	120.00	.5764	-.6002	-.0502	.2316	.7993	.5391	.5660	-.0496	.2206	.7499								
	125.00	.5255	-.7983	-.0392	.3525	.8884	.4824	-.7668	-.0378	.3514	.8350								
	130.00	.4611	-.9975	-.0197	.4677	.9944	.4114	.9646	-.0203	.4727	.9372								
	135.00	.3879	-.1744	-.0022	.5562	1.1046	.3478	-.1547	-.0021	.5706	1.0624								
	140.00	.3177	-.1370	.0138	.6032	1.2131	.2788	-.2843	.0115	.6119	1.1630								
	135.00	.3307	-.1959	-.0096	.6118	1.0794	.3140	-.1631	-.0097	.6004	1.0444								
	140.00	.2520	-.13480	.0061	.6735	1.1946	.2444	-.1318	.0071	.6573	1.1635								
	145.00	.1866	-.14466	.0169	.6768	1.2920	.1823	-.1403	.0201	.6711	1.2762								
	150.00	.1348	-.15190	.0176	.6428	1.3829	.1334	-.15091	.0194	.6391	1.3736								
	155.00	.0997	-.15810	.0247	.5778	1.1750	.0973	-.15661	.0263	.5737	1.4605								
	160.00	.0648	-.16312	.0247	.4970	1.5550	.0657	-.16211	.0267	.4927	1.5458								
	165.00	.0354	-.16762	.0204	.3996	1.6283	.0389	-.16570	.0230	.3913	1.6106								
	169.00	.0149	-.16963	.0139	.3091	1.6679	.0216	-.16717	.0191	.2978	1.6451								
	165.00	.0279	-.16195	.0203	.3923	1.5715	.0321	-.16344	.0212	.3920	1.5870								
	170.00	.0034	-.16474	.0141	.2828	1.6230	.0124	-.16609	.0159	.2762	1.6379								
	175.00	-.0097	-.16536	.0088	.1538	1.6465	-.0005	-.16772	.0089	.1467	1.6708								
	177.00	-.0121	-.16595	.0055	.0990	1.6566	-.0017	-.16831	.0065	.0898	1.6807								
	179.00	-.0127	-.16681	.0035	.0418	1.6676	-.0015	-.17018	.0029	.0312	1.7015								
	180.00	-.0115	-.16860	.0021	.0115	1.6860	.0032	-.17050	.0002	-.0032	1.7050								
	181.00	-.0029	-.16748	.0003	.0263	1.6746	.0077	-.16887	-.0017	.0372	1.6883								
	183.00	-.0052	-.16890	-.0039	.0936	1.6864	.0078	-.16871	-.0055	-.0961	1.6844								
	185.00	.0038	-.16774	-.0065	.1500	1.6707	.0045	-.16995	-.0134	.1526	1.6926								
1212	45.00	.7991	.6343	-.0411	.1166	1.0136	.7732	.6263	-.0380	.1038	.9896	.8574	.3404	-.0408	.0772	1.0291	.0214		
	50.00	.8665	.6096	-.0437	.0887	1.0540	.8380	.6024	-.0408	.0772	1.0291								
1213	55.00	.8953	.5758	-.0454	.0418	1.0637	.8767	.5741	-.0440	.0326	1.0474	.8574	.3404	-.0455	.0178	1.0407	.0224		
	60.00	.9136	.5418	-.0482	.0124	1.0621	.8924	.5358	-.0455	.0178	1.0407								
	65.00	.9192	.4989	-.0502	.0637	1.0439	.8985	.4923	-.0478	.0265	1.0224								
	70.00	.9165	.4499	-.0517	.1093	1.0151	.8958	.4452	-.0496	.1119	.9941								
	75.00	.9084	.3927	-.0521	.1442	.9791	.8935	.3956	-.0507	.1508	.9655								
	79.00	.8890	.3447	-.0524	.1669	.9483	.8744	.3456	-.0513	.1725	.9242								
	75.00	.8524	.3750	-.0565	.1416	.9205	.8617	.3835	-.0531	.1474	.9316								
	80.00	.8355	.3193	-.0560	.1693	.8782	.8430	.3254	-.0526	.1741	.8867								
	85.00	.8208	.2525	-.0541	.1800	.8397	.8260	.2604	-.0509	.1874	.8456								
	90.00	.8081	.1766	-.0507	.1766	.8081	.8075	.1888	-.0486	.1888	.8075								
	95.00	.7902	.0902	-.0450	.1588	.7793	.7825	.1054	-.0440	.1732	.7703								
	100.00	.7736	-.0104	-.0366	.1241	.7636	.7590	.0689	-.0360	.1386	.7463								
	105.00	.7526	-.1178	-.0263	.0810	.7575	.7369	-.0992	-.0261	.0949	.7375								
	110.00	.7316	-.2111	-.0147	.0236	.7700	.7104	-.2230	-.0138	.0334	.7439								
	115.00	.7293	-.2320	-.0118	.0314	.7464	.6872	-.2215	-.0110	.0269	.7216								
	120.00	.6986	-.3663	-.0011	.0368	.7879	.6567	-.3498	.0016	.0395	.7430								
	125.00	.6471	-.4981	.0120	.1078	.8095	.6015	-.4791	.0136	.1141	.7605								
	130.00	.5957	-.6293	.0230	.1738	.8490	.5469	-.6135	.0257	.1888	.7999								
	135.00	.5169	-.7688	-.0341	.2566	.8902	.4715	-.7526	.0367	.2734	.8450								
	140.00	.4360	-.9099	-.0443	.3351	.9517	.3974	-.8878	.0451	.3468	.9088								
	145.00	.3696	-.9223	-.0398	.3909	.9135	.3610	-.8742	.0428	.3629	.8735								
	150.00	.2982	-.1403	-.0437	.4532	1.0039	.2926	-.1010	.0479	.4252	.9619								
	155.00	.2326	-.1799	-.0439	.4863	1.0999	.2314	-.1376	.0478	.4629	1.0646								
	160.00	.1342	-.3823	-.0376	.4626	1.3095	.1904	-.13514	.0415	.4439	1.2841								
	165.00	.0976	-.14597	-.0322	.4075	1.4051	.1041	-.14390	.0360	.3944	1.3878								
	170.00	.0371	-.15725	-.0021	.0220	.5724	.0078	-.15764	.0023	.0197	1.5763								
	175.00	.0018	-.15613	-.0065	.0799	.5593	.0146	-.15729	.0055	.0677	1.5715								
	179.00	.0054	-.15725	-.0005															

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg.	$M_{\infty} = 3.5$					$M_{\infty} = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
1213	75.00	.8524	.3799	-.0683	-.1464	.9217	.8615	.3902	-.0642	-.1539	.9331
	80.00	.8413	.3196	-.0772	-.1686	.8840	.8471	.3323	-.0718	-.1802	.8919
	85.00	.8247	.2515	-.0873	-.1786	.8435	.8276	.2644	-.0804	-.1913	.8475
	90.00	.8042	.1752	-.0954	-.1752	.8042	.8048	.1934	-.0878	-.1934	.8048
	95.00	.7858	.0917	-.1031	-.1599	.7748	.7759	.1148	-.0944	-.1820	.7630
	100.00	.7624	-.0075	-.1142	-.1250	.7521	.7464	.0219	-.1048	-.1512	.7313
	105.00	.7440	-.1382	-.1306	-.0591	.7545	.7293	-.1058	-.1245	-.0866	.7319
	110.00	.7199	-.3166	-.1487	-.0513	.7848	.7086	-.2936	-.1981	-.0345	.7663
	107.00	.7440	-.1993	-.1397	-.0269	.7698	.7010	-.1693	-.1334	-.0431	.7199
	110.00	.7274	-.3081	-.1497	.0407	.7889	.6860	-.2911	-.1448	-.0389	.7442
	115.00	.6892	-.5220	-.1539	.1818	.8452	.6657	-.5179	.1680	.1881	.8222
	120.00	.6677	-.8081	-.1788	.3659	.9823	.6533	-.8211	.2104	.3844	.9764
	125.00	.6277	-.1.0665	-.1785	.5136	1.1259	.5854	-.1.0346	.1.1851	.5117	1.0729
	130.00	.5842	-.1.2778	-.1340	.6302	1.2349	.5037	-.1.2352	.1.127	.6224	1.1799
	135.00	.4419	-.1.4250	-.0705	.6951	1.3201	.4067	-.1.3073	.0853	.6934	1.2686
	140.00	.3427	-.1.4994	-.0106	.7013	1.3689	.3059	-.1.4724	.0236	.7123	1.3247
	135.00	.3736	-.1.4439	-.0700	.7568	1.2852	.3786	-.1.4129	.0952	.7314	1.2668
	140.00	.2711	-.1.4914	-.0117	.7510	1.3168	.2728	-.1.4974	.0290	.7535	1.3225
	145.00	.1871	-.1.5446	-.0128	.7327	1.3726	.1890	-.1.5355	.0112	.7259	1.3662
	150.00	.1308	-.1.5862	-.0223	.6798	1.4391	.1267	-.1.5780	.0235	.6793	1.4300
	155.00	.0988	-.1.6290	-.0275	.6079	1.5139	.0879	-.1.6202	.0292	.6050	1.5055
	160.00	.0552	-.1.6752	-.0314	.5211	1.5931	.0546	-.1.6587	.0316	.5160	1.5774
	165.00	.0284	-.1.7119	-.0224	.4157	1.6610	.0280	-.1.6872	.0266	.4097	1.6369
	169.00	.0084	-.1.7299	-.0144	.3219	1.6997	.0097	-.1.6986	.0190	.3146	1.6693
	165.00	.0187	-.1.6480	-.0252	.4084	1.5967	.0247	-.1.6616	.0257	.4062	1.6114
	170.00	-.0040	-.1.6683	-.0182	.2936	1.6423	.0067	-.1.6854	.0190	.2861	1.6610
	175.00	-.0138	-.1.6849	-.0119	.1606	1.6773	.0034	-.1.6996	.0107	.1515	1.6928
	177.00	-.0157	-.1.6907	-.0091	.1042	1.6876	.0039	-.1.7070	.0070	.0932	1.7045
	179.00	-.0124	-.1.6965	-.0063	.0420	1.6960	.0021	-.1.7106	.0035	.0319	1.7103
	180.00	-.0084	-.1.7019	-.0046	.0094	1.7019	.0043	-.1.7215	.0014	-.0043	1.7215
	181.00	-.0021	-.1.7036	-.0024	.0276	1.7033	.0073	-.1.7202	.0013	-.0373	1.7198
	183.00	-.0053	-.1.7041	-.0010	.0945	1.7015	.0132	-.1.7199	.0075	-.1032	1.7168
	185.00	.0087	-.1.7105	-.0043	.1578	1.7032	.0121	-.1.7196	.0115	-.1620	1.7120
2211	-5.00	-.0806	.7741	-.0011	-.0128	.7782	-.0766	.7782	-.0008	-.0085	.7819
	-4.00	-.0461	.7782	-.0012	-.0053	.7795	-.0435	.7822	-.0015	-.0025	.7834
	-1.00	-.0127	.7833	-.0016	.0010	.7834	-.0093	.7851	-.0015	-.0044	.7852
	.00	.0054	.7869	-.0015	.0054	.7869	-.0067	.7858	-.0018	-.0067	.7858
	1.00	.0195	.7892	-.0016	.0057	.7894	.0221	.7865	-.0021	-.0084	.7868
	3.00	.0549	.7908	-.0021	.0134	.7926	.0533	.7870	-.0021	.0120	.7887
	5.00	.0867	.7927	-.0023	.0173	.7973	.0853	.7872	-.0021	.0164	.7916
	10.00	.1739	.7991	-.0028	.0325	.8172	.1660	.7880	-.0026	.0267	.8048
	15.00	.2609	.8065	-.0040	.0433	.8465	.2503	.7901	-.0028	.0373	.8280
	20.00	.3573	.8132	-.0050	.0577	.8864	.3409	.7893	-.0044	.0503	.8583
	17.00	.3016	.8100	-.0020	.0516	.8628	.2866	.7766	-.0016	.0470	.8265
	20.00	.3624	.8082	-.0046	.0641	.8834	.3431	.7778	-.0021	.0564	.8482
	25.00	.4705	.8084	-.0061	.0848	.9315	.4475	.7798	-.0052	.0760	.8958
	30.00	.5772	.8101	-.0081	.0948	.9902	.5488	.7737	-.0070	.0884	.9444
	35.00	.6817	.8006	-.0080	.0992	1.0468	.6524	.7641	-.0076	.0961	1.0001
	40.00	.7816	.7912	-.0069	.0901	1.1085	.7479	.7463	-.0079	.0932	1.0524
	45.00	.8657	.7556	-.0077	.0778	1.1465	.8303	.7108	-.0075	.0845	1.0897
	50.00	.9229	.7062	-.0046	.0522	1.1609	.8899	.6591	-.0052	.0671	1.1054
	45.00	.8450	.6838	-.0137	.1140	1.0810	.8097	.6783	-.0126	.0929	1.0521
	50.00	.9070	.6345	-.0117	.0969	1.1027	.8805	.6348	-.0110	.0797	1.0825
	55.00	.9403	.5775	-.0098	.0662	1.1014	.9174	.5765	-.0087	.0540	1.0822
	60.00	.9616	.5270	-.0109	.0244	1.0963	.9519	.5295	-.0091	.0174	1.0892
	65.00	.9673	.4791	-.0112	.0254	1.0792	.9606	.4780	-.0103	.0272	1.0726
	70.00	.9711	.4275	-.0146	.0696	1.0587	.9632	.4291	-.0130	.0738	1.0519
	75.00	.9690	.3669	-.0199	.1036	1.0310	.9584	.3750	-.0171	.1141	1.0228
	75.00	.9804	.3197	-.0236	.1305	1.0038	.9406	.3300	-.0205	.1444	.9863
	80.00	.9239	.3555	-.0229	.1043	.9844	.9335	.3656	-.0182	.1115	.9961
	85.00	.9127	.3004	-.0270	.1373	.9510	.9202	.3080	-.0230	.1435	.9597
	90.00	.8968	.2360	-.0316	.1569	.9140	.9043	.2462	-.0273	.1665	.9224
	95.00	.8854	.1676	-.0342	.1676	.8854	.8861	.1826	-.0299	.1826	.8861
	100.00	.8432	.0029	-.0360	.1493	.8299	.8302	.0277	-.0319	.1715	.8128
	105.00	.8205	-.1112	-.0361	.1050	.8213	.8040	-.0750	-.0343	.1357	.7960
	110.00	.7896	-.2560	-.0355	.0295	.8296	.7646	-.2250	-.0349	-.0501	.7955
	107.00	.8073	-.1389	-.0367	.1032	.8126	.7596	-.1157	-.0342	-.1115	.9961
	110.00	.7895	-.2260	-.0355	.0576	.8192	.7393	-.2125	-.0338	-.0532	.7674
	115.00	.7420	-.4048	-.0312	.0533	.8436	.6903	-.3827	-.0291	-.0551	.7873
	120.00	.6872	-.6039	-.0234	.1794	.8971	.6382	-.5657	-.0237	.1708	.8356
	125.00	.6262	-.7943	-.0143	.2915	.9686	.5748	-.7651	-.0149	.2970	.9096
	130.00	.5494	-.9935	-.0002	.4080	1.0595	.4993	-.9654	-.0010	.4186	1.0030
	135.00	.4646	-.1.1696	.0162	.4985	1.1555	.4162	-.1.1456	.0138	.5158	1.1044
	140.00	.3846	-.1.3170	-.0297	.5520	1.2561	.3363	-.1.2888	.0252	.5708	1.2035

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_{\infty} = 3.5$											$M_{\infty} = 4.2$											
Config-	Configuration	α_s	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D
2212		45.00	.8493	.6911	-.0132	.1118	1.0892	.7989	.6806	-.0109	.0836	1.0462										
		50.00	.9097	.6398	-.0123	.0946	1.1082	.8676	.6397	-.0083	.0677	1.0758										
		55.00	.9400	.5848	-.0092	.0602	1.1054	.9138	.5858	-.0068	.0442	1.0845										
		60.00	.9590	.5293	-.0108	.0211	1.0952	.9048	.5372	-.0062	.0052	1.0834										
		65.00	.9662	.4766	-.0119	-.0236	1.0771	.9503	.4845	-.0074	.0375	1.0660										
		70.00	.9704	.4209	-.0120	-.0636	1.0559	.9525	.4350	-.0076	.0830	1.0439										
		75.00	.9694	.3644	-.0140	-.1011	1.0307	.9477	.3789	-.0103	.1207	1.0135										
		79.00	.9661	.3079	-.0151	-.1179	1.0072	.9441	.3303	-.0123	.1441	.9898										
		75.00	.9247	.3578	-.0145	-.1063	.9858	.9294	.3582	-.0127	.1055	.9904										
		80.00	.9091	.2991	-.0148	-.1367	.9472	.9218	.2991	-.0134	.1345	.9597										
		85.00	.9102	.2313	-.0149	-.1511	.9269	.9109	.2328	-.0133	.1525	.9277										
		90.00	.8967	.1559	-.0128	-.1559	.8967	.8997	.1654	-.0124	.1654	.8997										
		95.00	.8870	.0690	-.0090	-.1460	.8776	.8828	.0828	-.0094	.1594	.8722										
		100.00	.8789	-.0271	-.0015	-.1259	.8702	.8663	-.0117	-.0028	.1389	.8551										
		105.00	.8730	-.1360	.0081	-.0945	.8785	.8488	-.1152	.0070	.1084	.8497										
		110.00	.8530	-.2525	.0187	-.0544	.8880	.8236	-.2327	.0179	.0630	.8535										
		107.00	.8625	-.1723	.0111	-.0874	.8752	.8189	-.1551	.0106	.0911	.8284										
		110.00	.8409	-.2476	.0179	-.0549	.8749	.8045	-.2300	.0181	.0587	.8337										
		115.00	.8020	-.3714	.0281	-.0023	.8839	.7598	-.3570	.0289	.0025	.8395										
		120.00	.7560	-.5035	.0383	.0580	.9065	.7028	-.4831	.0388	.0670	.8502										
		125.00	.6880	-.6312	.0462	.1224	.9256	.6332	-.6102	.0473	.1366	.8687										
		130.00	.5983	-.7658	.0546	.2020	.9505	.5519	-.7530	.0564	.2220	.9068										
		135.00	.5124	-.9118	.0615	.2824	.1070	.4641	-.8877	.0617	.2995	.9559										
		140.00	.4226	-1.0340	.0645	.3409	1.0637	.3821	-1.0121	.0636	.3579	1.0209										
2213		45.00	.8517	.6892	-.0161	.1149	1.0895	.8032	.6778	-.0137	.0887	1.0473										
		50.00	.9088	.6425	-.0126	.0922	1.1091	.8739	.6523	-.0120	.0773	1.0758										
		55.00	.9423	.5861	-.0112	.0604	1.1081	.9192	.5794	-.0100	.0526	1.0853										
		60.00	.9654	.5365	-.0123	.0171	1.026	.9479	.5285	-.0099	.0163	1.0852										
		65.00	.9706	.4829	-.0139	-.0275	1.0838	.9596	.4778	-.0113	.0275	1.0716										
		70.00	.9751	.4283	-.0183	-.0690	1.0628	.9615	.4281	-.0143	.0734	1.0499										
		75.00	.9830	.3708	-.0277	-.1038	1.0455	.9624	.3725	-.0222	.1107	1.0260										
		79.00	.9786	.3149	-.0358	-.1224	L.0207	.9529	.3243	-.0288	.1365	.9973										
		75.00	.9255	.3628	-.0263	-.1109	.9879	.9309	.3613	-.0238	.1081	.9927										
		80.00	.9225	.3022	-.0365	-.1374	.9610	.9260	.3013	-.0331	.1359	.9642										
		85.00	.9136	.2322	-.0487	-.1517	.9303	.9141	.2346	-.0433	.1540	.9310										
		90.00	.9059	.1569	-.0582	-.1569	.9059	.9000	.1679	-.0522	.1679	.9000										
		95.00	.8916	.0762	-.0677	-.1536	.8816	.8764	.0944	-.0601	.1704	.8649										
		100.00	.8733	-.0206	-.0795	-.1313	.8636	.8601	.0097	-.0712	.1590	.8453										
		105.00	.8608	-.1493	-.0975	-.0786	.8701	.8396	-.1163	-.0918	.1050	.8611										
		110.00	.8450	-.3255	-.1176	.0169	.9053	.8209	-.3009	-.1184	.0020	.8743										
		107.00	.8537	-.2129	-.1084	-.0460	.8786	.8128	-.1770	-.1023	.0683	.8290										
		110.00	.8405	.3155	-.1197	.0090	.8977	.7985	-.2994	-.1163	.0882	.8527										
		115.00	.7992	.6315	-.1286	.1439	.9489	.7673	-.5218	-.1394	.1478	.9177										
		120.00	.7669	-.8054	-.1527	.3140	1.0669	.7458	-.8121	-.1811	.3304	1.0520										
		125.00	.7150	-.1054	-.1526	.4577	1.1934	.6754	-.10376	-.1633	.4626	1.1484										
		130.00	.6214	-.2692	-.1129	.5729	1.2918	.5812	-.1235	-.1235	.5713	1.2381										
		135.00	.5134	-.4147	-.0539	.6381	1.3641	.4766	-.13985	-.0702	.6519	1.3259										
		140.00	.4032	-1.4912	.0047	.6496	1.4015	.3608	-.14681	-.0100	.6673	1.3565										
3211		-5.00	-.0775	.8230	-.0023	-.0055	.8267	-.0758	.8292	-.0006	.0032	.8326										
		-3.00	-.0458	.8199	-.0027	-.0028	.8212	-.0440	.8327	-.0012	.0003	.8339										
		-1.00	-.0117	.8248	-.0025	-.0027	.8249	-.0159	.8405	-.0015	.0012	.8407										
		0.00	.0013	.8263	-.0026	-.0013	.8263	.0005	.8413	-.0016	.0005	.8413										
		1.00	.0197	.8295	-.0028	-.0052	.8297	.0147	.8413	-.0017	.0000	.8415										
		3.00	.0503	.8320	-.0034	.0067	.8335	.0453	.8416	-.0022	.0012	.8428										
		5.00	.0818	.8341	-.0031	.0088	.8380	.0756	.8418	-.0022	.0019	.8452										
		10.00	.1627	.8425	-.0030	.0139	.8580	.1521	.8484	-.0021	.0311	.8584										
		15.00	.2192	.8580	-.0037	.0186	.8933	.2349	.8502	-.0029	.0069	.8920										
		20.00	.3453	.8670	-.0040	.0280	.9328	.3283	.8567	-.0037	.0155	.9173										
		25.00	.4678	.8780	-.0038	.0352	.9371	.3293	.8390	-.0041	.0224	.9010										
		30.00	.5840	.8877	-.0049	.0619	1.0608	.5460	.8479	-.0045	.0415	.9519										
		35.00	.6923	.8877	-.0083	.0631	1.1169	.6549	.8418	-.0079	.0537	1.0652										
		40.00	.7922	.8655	-.0135	.0506	1.1722	.7530	.8218	-.0129	.0486	1.1135										
		45.00	.8775	.8294	-.0171	.0340	1.2070	.8423	.7784	-.0162	.0452	1.1460										
		50.00	.9396	.7715	-.0232	.0130	1.2157	.8999	.7151	-.0221	.0306	1.1491										
		45.00	.8674	.7421	-.0017	.0886	1.1380	.8220	.7342	-.0036	.0620	1.1004										
		50.00	.9240	.6861	-.0072	.0683	1.1488	.8904	.6771	-.0080	.0536	1.1173										
		55.00	.9539	.6174	-.0101	.0414	1.1355	.9333	.6065	-.0125	.0385	1.1124										
		60.00	.9685	.5466	-.0104	.0109	1.1120	.9559	.5416	-.0127	.0090	.9986										
		65.00	.9942	.4833	-.0099	-.0178	1.1054	.9752	.4762	-.0115	-.0195	1.0851										
		70.00	.9949	.4162	-.0040	-.0501	1.0791	.9842	.4186	-.0087	-.0568	1.0680										
		75.00	.9976	.3582	-.0015	-.0878	1.0563	.9832														

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

M _∞ = 3.5										M _∞ = 4.2									
Config- uration	α, deg	C _N	C _A	C _m	C _L	C _D	C _N	C _A	C _m	C _L	C _D	C _N	C _A	C _m	C _L	C _D			
3211	107.00	.8680	-.1404	-.0145	-.1195	.8711	.8198	-.1150	-.0125	-.1297	.8176	3212	3212	3213	3213	3211	3212	3213	
	110.00	.8438	-.2342	-.0135	-.0685	.8730	.7954	-.2086	-.0128	-.0760	.8187								
	115.00	.7922	-.4010	-.0101	.0286	.8875	.7440	-.3733	-.0101	.0239	.8321								
	120.00	.7309	-.5937	-.0047	.1487	.9299	.6820	-.5617	-.0058	.1480	.8730								
	125.00	.6662	-.7881	.0024	.2635	.9977	.6137	-.7569	.0001	.2680	.9368								
	130.00	.5862	-.9906	.0150	.3820	1.0858	.5322	-.9544	.0114	.3890	1.0212								
	135.00	.5016	-.11727	.0291	.4745	1.1839	.4472	-.11326	.0248	.4847	1.1171								
	140.00	.4100	-.12999	.0410	.5215	1.2593	.3613	-.12752	.0350	.5429	1.2091								
3212	45.00	.8473	.7356	.0032	.0789	1.1193	.8170	.7353	.0032	.0578	1.0976								
	50.00	.9168	.6936	.0082	.0580	1.1481	.8845	.6770	.0084	.0499	1.1128								
	55.00	.9482	.6161	.0101	.0392	1.1301	.9262	.6082	.0118	.0330	1.1076								
	60.00	.9740	.5508	.0110	.0100	1.1789	.9489	.5359	.0123	.0104	1.0898								
	65.00	.9824	.4804	.0108	-.0202	1.0934	.9695	.4683	.0115	.0147	1.0766								
	70.00	.9925	.4128	.0084	-.0084	1.0738	.9795	.4105	.0107	.0507	1.0608								
	75.00	.9937	.3573	.0087	-.0079	1.0523	.9776	.3539	.0091	.0888	1.0359								
	79.00	.9949	.2993	.0070	-.0136	1.0357	.9707	.3045	.0080	.1137	1.0110								
	75.00	.9448	.3175	.0063	-.0912	1.0025	.9601	.3453	.0077	.0850	1.0168								
	80.00	.9415	.2839	.0055	-.1161	.9765	.9557	.2822	.0071	.1119	.9902								
	85.00	.9413	.2162	.0052	-.1334	.9565	.9525	.2176	.0065	.1338	.9679								
	90.00	.9415	.1409	.0075	-.1409	.9415	.9366	.1487	.0075	.1487	.9366								
	95.00	.9366	.0573	.0115	-.1387	.9280	.9325	.0710	.0112	.1520	.9228								
	100.00	.9257	-.0364	.0192	-.1249	.9179	.9189	.1076	.0174	.1423	.9080								
	105.00	.9256	-.1429	.0289	-.1016	.9311	.9040	.1209	.0272	.1172	.9045								
	110.00	.9055	-.2581	.0388	-.0672	.9392	.8781	.2379	.0377	.0767	.9065								
	107.00	.9209	-.1697	.0325	-.1069	.9303	.8774	.1522	.0309	.1110	.8836								
	110.00	.9039	-.2434	.0397	-.0805	.9326	.8609	.2252	.0378	.0828	.8860								
	115.00	.8665	.3622	.0478	.0371	.9366	.8137	.3472	.0473	.0292	.8842								
	120.00	.8041	-.4921	.0558	.0241	.9425	.7495	.4733	.0563	.0351	.8858								
	125.00	.7311	-.6218	.0633	.0882	.9580	.6767	.6008	.0622	.1040	.8989								
	130.00	.6422	-.7531	.0695	.1641	.9761	.5862	.7340	.0691	.1855	.9209								
	135.00	.5462	-.8960	.0738	.2488	1.0184	.4922	.8703	.0725	.2674	.9634								
	140.00	.4518	-.1019	.0754	.3107	1.0731	.4036	.9921	.0729	.3285	1.0194								
3213	45.00	.8679	.7393	.0004	.0909	1.1365	.8209	.7316	.0018	.0632	1.0978								
	50.00	.9157	.6821	.0055	.0661	1.1399	.8889	.6736	.0061	.0554	1.1159								
	55.00	.9545	.6145	.0083	.0441	1.1344	.9315	.6041	.0095	.0395	1.1095								
	60.00	.9680	.5620	.0080	.0146	1.1093	.9514	.5344	.0108	.0129	1.0911								
	65.00	.9794	.4710	.0068	-.0130	1.0867	.9705	.4700	.0091	.0158	1.0782								
	70.00	.9958	.4121	.0025	-.0466	1.0766	.9833	.4094	.0060	.0484	1.0640								
	75.00	1.0005	.3490	.0043	-.0782	1.0567	.9848	.3557	.0014	.0887	1.0433								
	79.00	1.0043	.2909	.0153	-.0940	1.0414	.9808	.3034	.0092	.1107	1.0207								
	75.00	.9598	.3555	.0034	-.0950	1.0191	.9744	.3500	.0022	.0859	1.0318								
	80.00	.9565	.2925	.0136	-.1220	.9928	.9703	.2878	.0112	.1149	1.0056								
	85.00	.9546	.2209	.0253	-.1369	.9703	.9610	.2212	.0228	.1364	.9796								
	90.00	.9497	.1459	.0361	-.1459	.9497	.9468	.1551	.0309	.1551	.9468								
	95.00	.9398	.0660	.0452	-.1476	.9304	.9285	.0856	.0389	.1662	.9175								
	100.00	.9257	-.0271	.0571	-.1340	.9163	.9059	-.0021	.0505	.1552	.8925								
	105.00	.9151	-.1556	.0752	-.0865	.9242	.8893	.1210	.0706	.1133	.8903								
	110.00	.8988	-.2116	.0855	-.0633	.9310	.8639	.1781	.0798	.0823	.8782								
	115.00	.8973	.3286	.0978	.0019	.9556	.8464	.2973	.0927	.0101	.8971								
	120.00	.8533	.5257	.1045	.1158	.9956	.8170	.5219	.1200	.1277	.9611								
	125.00	.8152	.7984	.1338	.2838	1.1052	.7923	.8109	.1656	.3061	1.0916								
	130.00	.7610	-.1062	.1363	.1361	1.2394	.7153	-.10260	.1464	.4301	1.1744								
	135.00	.6604	-.12649	.0965	.5445	1.3190	.6163	.12258	.1083	.5428	1.2600								
	140.00	.5465	-.14152	.0386	.6143	1.3871	.5049	-.13799	.0565	.6187	1.3327								
1311	-5.00	-.1003	.6079	-.0096	-.0469	.6143	-.0988	.5954	-.0085	-.0465	.6017								
	-3.00	-.0614	.6124	-.0062	-.0292	.6148	-.0602	.6037	-.0054	-.0285	.6061								
	-1.00	-.0206	.6192	-.0028	-.0098	.6195	-.0199	.6027	-.0032	-.0094	.6029								
	0.00	-.0019	.6223	-.0012	-.0019	.6223	-.0014	.6095	-.0015	-.0014	.6095								
	1.00	.0195	.6232	-.0000	-.0086	.6234	.0173	.6094	.0001	.0067	.6096								
	3.00	.0582	.6239	.0019	.0254	.6260	.0575	.6100	.0024	.0255	.6122								
	5.00	.09																	

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α_1 deg	$M_\infty = 3.5$						$M_\infty = 4.2$					
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D		
1311	75.00	1.1558	.4335	-.0075	-.1196	1.2286	1.1537	.4195	-.0078	-.1066	1.2230		
	80.00	1.1411	.3841	-.0172	-.1801	1.1905	1.1389	.3723	-.0166	-.1688	1.1862		
	85.00	1.1217	.3294	-.0256	-.2303	1.1461	1.1191	.3166	-.0237	-.2179	1.1424		
	90.00	1.1041	.2586	-.0336	-.2586	1.1041	1.0935	.2548	-.0332	-.2548	1.0935		
	95.00	1.0763	.1862	-.0385	-.2793	1.0560	1.0607	.1850	-.0388	-.2768	1.0406		
	100.00	1.0451	.0984	-.0425	-.2780	1.0102	1.0070	.1032	-.0422	-.2765	.9738		
	105.00	1.0001	-.0219	-.0465	-.2376	.9717	.9683	.0016	-.0465	-.2521	.9349		
	110.00	.9475	-.1698	-.0484	-.1645	.9485	.9157	-.1448	-.0486	-.1771	.9100		
	107.00	.9775	-.0812	-.0522	-.2081	.9585	.9235	-.0624	-.0476	-.2103	.9013		
	110.00	.9466	-.1783	-.0526	-.1563	.9505	.8867	-.1609	-.0482	-.1521	.8882		
	115.00	.8875	-.3625	-.0190	-.0466	.9576	.8306	-.3417	-.0462	-.0413	.8972		
	120.00	.8136	-.5620	-.0412	-.0799	.9856	.7546	-.5365	-.0411	.0873	.9218		
	125.00	.7361	-.7680	-.0324	-.2069	1.0435	.6767	-.7333	-.0318	.2126	.9749		
	130.00	.6433	-.9704	-.0171	.3299	1.1166	.5798	-.9282	-.0164	.3383	1.0407		
	135.00	.5428	-.1491	-.0010	.4287	1.1963	.4845	-.1156	.0008	.4463	1.1315		
	140.00	.4421	-.1296	+.0193	.4944	1.2771	.3907	-.12773	.0170	.5217	1.2296		
	135.00	.4679	-.1627	-.0077	.4913	1.1531	.4524	-.1136	-.0065	.4675	1.1073		
	140.00	.3692	-.3165	-.0093	.5634	1.2458	.3536	-.12778	.0089	.5505	1.2061		
	145.00	.2768	-.4250	-.0188	.5907	1.3261	.2683	-.1391	.0195	.5827	1.3000		
	150.00	.2028	-.5008	-.0226	.5749	1.4010	.1943	-.14918	.0211	.5776	1.3891		
	155.00	.1561	-.5643	-.0246	.5196	1.4837	.1492	-.15529	.0261	.5211	1.4705		
	160.00	.1129	-.6224	-.0239	.4488	1.5632	.1125	-.16159	.0264	.4470	1.5569		
	165.00	.0764	-.6639	-.0210	.3569	1.6270	.0797	-.16533	.0244	.3509	1.6176		
	169.00	.0510	-.7015	-.0166	.2746	1.6799	.0583	-.1766	.0197	.2627	1.6569		
	170.00	.0240	-.6513	-.0175	.2631	1.6704	.0654	-.16470	.0246	.3631	1.6078		
	175.00	.0076	-.6757	-.0105	.1385	1.6700	.0362	-.17676	.0183	.2560	1.6604		
	177.00	.0083	-.6820	-.0069	.0797	1.6801	.0163	-.17013	.0062	.0727	1.6999		
	179.00	-.0023	-.6887	-.0035	.0318	1.6884	.0049	-.17034	.0018	.0248	1.7032		
	180.00	-.0072	-.6901	-.0016	.0072	1.6901	-.0002	-.17043	-.0001	.0002	1.7043		
	181.00	-.0127	-.6926	-.0001	-.0168	1.6925	-.0065	-.17048	-.0027	-.0232	1.7046		
	183.00	-.0232	-.6985	-.0041	-.0657	1.6974	-.0161	-.17056	-.0065	-.0732	1.7041		
	185.00	-.0345	-.7010	-.0078	.1139	1.6975	-.0271	-.17071	-.0105	-.1218	1.7030		
1121	-5.00	-.0756	.8673	.0135	.0003	.8706	-.0742	.8562	.0126	.0007	.8594		
	-3.00	-.0443	.8720	.0084	.0014	.8731	-.0429	.8607	.0070	.0022	.8617		
	-1.00	-.0146	.8767	.0027	.0007	.8769	-.0108	.8632	.0013	.0043	.8633		
	.00	-.0003	.8779	.0002	-.0003	.8779	-.0035	.8635	-.0013	.0035	.8635		
	1.00	.0147	.8780	-.0022	-.0006	.8782	.0183	.8630	-.0039	.0032	.8632		
	3.00	.0430	.8763	-.0075	-.0030	.8774	.0464	.8615	-.0087	.0012	.8627		
	5.00	.0701	.8742	-.0119	-.0064	.8770	.0751	.8605	-.0133	-.0002	.8637		
	10.00	.1427	.8740	-.0234	-.0113	.8855	.1482	.8562	-.0252	-.0028	.8689		
	15.00	.2143	.8696	-.0353	-.0181	.8955	.2172	.8473	-.0367	-.0095	.8746		
	20.00	.2859	.8571	-.0477	-.0244	.9032	.2891	.8330	-.0487	-.0132	.8817		
	20.00	.3071	.8598	-.0515	-.0055	.9129	.2897	.8289	-.0473	-.0113	.8780		
	25.00	.3782	.8617	-.0636	-.0129	.9226	.3586	.8104	-.0588	-.0175	.8861		
	30.00	.4398	.8617	-.0744	-.0250	.9228	.4221	.7863	-.0699	-.0277	.8921		
	35.00	.5070	.7918	-.0863	-.0389	.9394	.4816	.7595	-.0805	-.0411	.8983		
	40.00	.5553	.7681	-.0948	-.0683	.9453	.5305	.7296	-.0889	-.0626	.8999		
	45.00	.5896	.7275	-.0999	-.0975	.9313	.5653	.6882	-.0945	-.0669	.8843		
	50.00	.6085	.6795	-.1024	-.1294	.9029	.5826	.6418	-.0971	-.1171	.8588		
	45.00	.5542	.7119	-.0934	-.1115	.8953	.5411	.6893	-.0906	-.1048	.8700		
	50.00	.5735	.6658	-.0970	-.1114	.8673	.5640	.6470	-.0942	-.1331	.8479		
	55.00	.5806	.6125	-.0985	-.1687	.8269	.5731	.5978	-.0960	-.1610	.8124		
	60.00	.5820	.5736	-.0995	-.2057	.7908	.5737	.5562	-.0968	-.1948	.7749		
	65.00	.5730	.5216	-.0993	-.2305	.7397	.5664	.5071	-.0966	-.2202	.7276		
	70.00	.5589	.4643	-.0985	-.2451	.6840	.5548	.4527	-.0959	-.2356	.6761		
	75.00	.5430	.4052	-.0968	-.2509	.6294	.6324	.3938	-.0934	-.2426	.6162		
	75.00	.5297	.3918	-.0958	-.2414	.6131	.5297	.3852	-.0935	-.2350	.6114		
	80.00	.5089	.3312	-.0926	-.2378	.5587	.5074	.3265	-.0899	-.2334	.5564		
	85.00	.4855	.2675	-.0884	-.2242	.5070	.4833	.2654	-.0854	-.2223	.5046		
	90.00	.4626	.1970	-.0834	-.1970	.4626	.4574	.1999	-.0802	-.1999	.4574		
	95.00	.4398	.1127	-.0785	-.1506	.4283	.4338	.1241	-.0752	-.1611	.4214		
	100.00	.4168	.0186	-.0742	-.0907	.4073	.4035	.0381	-.0701	-.1076	.3908		
	105.00	.3920	-.1009	-.0703	-.0040	.3477	.3774	-.0765	-.0670	-.0238	.3843		
	110.00	.3645	-.2541	-.0643	.1141	.4294	.3471	-.2255	-.0614	.0932	.4033		
	105.00	.3796	-.1211	-.0692	.0188	.3980	.3697	-.0980	-.0659	-.0010	.3825		
	110.00	.3507	-.2783	-.0638	.1416	.4247	.3413	-.2428	-.0605	.1115	.4037		
	115.00	.3218	-.4452	-.0558	.2675	.4799	.3113	-.4073	-.0533	.2375	.4542		
	120.00	.2902	-.6336	-.0460	.4036	.5681	.2776	-.6015	-.0442	.3821	.5412		
	125.00	.2559	-.8441	-.0334	.5446	.6938	.2388	-.8048	-.0318	.5223	.6572		
	130.00	.2123	-.10474	-.0171	.6659	.8359	.1939	-.10015	-.0165	.6426	.7923		
	135.00	.1675	-.12277	-.0019	.7497	.9865	.1509	-.1895	-.0016	.7344	.9178		
	130.00	.1305	-.12559	-.0005	.7958	.9804	.1254	-.2008	-.0002	.7600	.9378		
	140.00	.0944	-.13765	.0121	.8125	1.1152	.0938	-.13430	.0140	.7914	1.0891		
	145.00	.0643	-.14642	.0197	.7871	1.2363	.0698	-.14481	.0239	.7734	1.2262		
	150.00	.0387	-.15483	.0236	.7407	1.3603	.0468	-.15279	.0266	.7234	1.3465		
	155.00	.0192	-.15976	.0243	.6578	1.4560	.0290	-.15963	.0288	.6483	1.4590		
	160.00	.0019	-.16414	.0215	.5596	1.5430	.0140	-.16448	.0275	.5494	1.5504		
	165.00	-.0048	-.16773	.0171	.4387	1.6190	.0032	-.16817	.0222	.4322	1.6252		
	169.00	-.0058	-.17003	.0111	.3301	1.6680	.0011	-.17002	.0162	.3233	1.6692		

TABLE I--AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

M _∞ = 3.5												M _∞ = 4.2															
Config-	α,	C _N	C _A	C _m	C _L	C _D	C _N	C _A	C _m	C _L	C _D	Config-	α,	C _N	C _A	C _m	C _L	C _D	Config-	α,	C _N	C _A	C _m	C _L	C _D		
uration	deg											uration	deg						uration	deg							
1121	165.00	-.0091	-1.6399	.0185	.4332	1.5816	.0055	-1.6736	.0233	.4279	1.6180	1121	165.00	-.0091	-1.6399	.0185	.4332	1.5816	1121	165.00	-.0091	-1.6399	.0185	.4332	1.5816	1.6180	
	170.00	-.0116	-1.6715	.0116	.3017	1.6441	.0034	-1.6988	.0168	.2917	1.6736		170.00	-.0116	-1.6715	.0116	.3017	1.6441		170.00	-.0116	-1.6715	.0116	.3017	1.6441	1.6736	
	175.00	-.0101	-1.6696	.0059	.1556	1.6624	.0030	-1.7114	.0089	.1462	1.7052		175.00	-.0101	-1.6696	.0059	.1556	1.6624		175.00	-.0101	-1.6696	.0059	.1556	1.6624	1.7052	
	177.00	-.0108	-1.6867	.0036	.0991	1.6838	.0020	-1.7121	.0062	.0876	1.7099		177.00	-.0108	-1.6867	.0036	.0991	1.6838		177.00	-.0108	-1.6867	.0036	.0991	1.6838	1.7099	
	179.00	-.0115	-1.6951	.0011	.0411	1.6946	.0026	-1.7193	.0029	.0274	1.7190		179.00	-.0115	-1.6951	.0011	.0411	1.6946		179.00	-.0115	-1.6951	.0011	.0411	1.6946	1.7190	
	180.00	-.0094	-1.7013	-.0003	.0094	1.7013	.0038	-1.7192	.0011	-.0038	1.7192		180.00	-.0094	-1.7013	-.0003	.0094	1.7013		180.00	-.0094	-1.7013	-.0003	.0094	1.7013	1.7192	
	181.00	-.0060	-1.7037	-.0021	-.0237	1.7035	.0039	-1.7170	-.0017	-.0339	1.7166		181.00	-.0060	-1.7037	-.0021	-.0237	1.7035		181.00	-.0060	-1.7037	-.0021	-.0237	1.7035	1.7166	
	183.00	-.0053	-1.7044	-.0049	-.0839	1.7024	.0027	-1.7155	-.0049	-.0925	1.7130		183.00	-.0053	-1.7044	-.0049	-.0839	1.7024		183.00	-.0053	-1.7044	-.0049	-.0839	1.7024	1.7130	
	185.00	-.0059	-1.7074	-.0067	-.1429	1.7014	.0016	-1.7153	-.0077	-.1511	1.7087		185.00	-.0059	-1.7074	-.0067	-.1429	1.7014		185.00	-.0059	-1.7074	-.0067	-.1429	1.7014	1.7087	
1122	45.00	.5563	.7067	-.0932	-.1063	.8931	.5455	.6900	-.0905	-.1022	.8736	1122	45.00	.5563	.7067	-.0932	-.1063	.8931	1122	45.00	.5563	.7067	-.0932	-.1063	.8931	.8736	
	50.00	.5807	.6670	-.0976	-.1376	.8735	.5689	.6490	-.0945	-.1315	.8530		50.00	.5807	.6670	-.0976	-.1376	.8735		50.00	.5807	.6670	-.0976	-.1376	.8735	.8530	
	55.00	.5854	.6100	-.0984	-.1639	.8294	.5805	.6014	-.0963	-.1596	.8205		55.00	.5854	.6100	-.0984	-.1639	.8294		55.00	.5854	.6100	-.0984	-.1639	.8294	.8205	
	60.00	.5901	.5688	-.0995	-.1975	.7954	.5821	.5547	-.0967	-.1893	.7815		60.00	.5901	.5688	-.0995	-.1975	.7954		60.00	.5901	.5688	-.0995	-.1975	.7954	.7815	
	65.00	.5815	.5094	-.0979	-.2159	.7423	.5746	.4988	-.0954	-.2093	.7316		65.00	.5815	.5094	-.0979	-.2159	.7423		65.00	.5815	.5094	-.0979	-.2159	.7423	.7316	
	70.00	.5688	.4490	-.0943	-.2274	.6681	.5624	.4408	-.0920	-.2218	.6793		70.00	.5688	.4490	-.0943	-.2274	.6681		70.00	.5688	.4490	-.0943	-.2274	.6681	.6793	
	75.00	.5510	.3856	-.0884	-.2299	.6320	.5472	.3815	-.0871	-.2269	.6273		75.00	.5510	.3856	-.0884	-.2299	.6320		75.00	.5510	.3856	-.0884	-.2299	.6320	.6273	
	80.00	.5172	.3159	-.0800	-.2213	.5642	.5160	.3086	-.0799	-.2143	.5618		80.00	.5172	.3159	-.0800	-.2213	.5642		80.00	.5172	.3159	-.0800	-.2213	.5642	.5618	
	85.00	.5009	.2481	-.0717	-.2035	.5206	.4971	.2422	-.0718	-.1980	.5163		85.00	.5009	.2481	-.0717	-.2035	.5206		85.00	.5009	.2481	-.0717	-.2035	.5206	.5163	
	90.00	.4848	.1676	-.0615	-.1676	.4848	.4780	.1678	-.0620	-.1678	.4780		90.00	.4848	.1676	-.0615	-.1676	.4848		90.00	.4848	.1676	-.0615	-.1676	.4848	.4780	
	95.00	.4705	.0752	-.0493	-.1159	.4221	.4590	.0793	-.0499	-.1119	.4504		95.00	.4705	.0752	-.0493	-.1159	.4221		95.00	.4705	.0752	-.0493	-.1159	.4221	.4504	
	100.00	.4582	-.0229	-.0360	-.0570	.4552	.4429	-.0148	-.0363	-.0623	.4388		100.00	.4582	-.0229	-.0360	-.0570	.4552		100.00	.4582	-.0229	-.0360	-.0570	.4552	.4388	
	105.00	.4486	-.1342	-.0213	.0135	.4680	.4285	-.1225	-.0209	-.0074	.4456		105.00	.4486	-.1342	-.0213	.0135	.4680		105.00	.4486	-.1342	-.0213	.0135	.4680	.4456	
	110.00	.4341	.2583	-.0056	-.0942	.4922	.4119	-.2460	-.0046	-.0903	.4712		110.00	.4341	.2583	-.0056	-.0942	.4922		110.00	.4341	.2583	-.0056	-.0942	.4922	.4712	
	105.00	.4334	.1627	-.0180	.0450	.4607	.4235	-.1458	-.0180	-.0312	.4468		105.00	.4334	.1627	-.0180	.0450	.4607		105.00	.4334	.1627	-.0180	.0450	.4607	.4468	
	110.00	.4161	.2833	-.0037	.1239	.4879	.4065	-.2644	-.0031	.1095	.4724		110.00	.4161	.2833	-.0037	.1239	.4879		110.00	.4161	.2833	-.0037	.1239	.4879	.4724	
	115.00	.3919	.4782	-.0109	.2109	.2134	.5319	.3832	-.3880	.0114	.1897	.5113		115.00	.3919	.4782	-.0109	.2109	.2134		115.00	.3919	.4782	-.0109	.2109	.2134	.5113
	120.00	.3607	.5527	-.0227	.2809	.5788	.3490	-.5189	.0252	.2749	.5617		120.00	.3607	.5527	-.0227	.2809	.5788		120.00	.3607	.5527	-.0227	.2809	.5788	.5617	
	125.00	.3210	.6735	-.0345	.3676	.6492	.3056	-.6549	.0380	.3612	.6259		125.00	.3210	.6735	-.0345	.3676	.6492		125.00	.3210	.6735	-.0345	.3676	.6492	.6259	
	130.00	.2729	.8124	-.0445	.4469	.7313	.2607	-.7908	.0483	.4382	.7080		130.00	.2729	.8124	-.0445	.4469	.7313		130.00	.2729	.8124	-.0445	.4469	.7313	.7080	
	135.00	.2272	.9521	-.0508	.5125	.8339	.1914	-.9245	.0549	.5074	.8124		135.00	.2272	.9521	-.0508	.5125	.8339		135.00	.2272	.9521	-.0508	.5125	.8339	.8124	
	135.00	.1951	.9663	-.0524	.5453	.8213	.1914	-.9245	.0558	.5184	.7899		135.00	.1951	.9663	-.0524	.5453	.8213		135.00	.1951	.9663	-.0524	.5453	.8213	.7899	
	140.00	.1568	-.1028	.0542	.5888	.9456	.1564	-.1051	.0592	.5588	.9087		140.00	.1568	-.1028	.0542	.5888	.9456		140.00	.1568	-.1028	.0542	.5888	.9456	.9087	
	145.00	.1264	-.2170	.0527	.5945	1.0694	.1276	-.11748	.0573	.5693	1.0355		145.00	.1264	-.2170	.0527	.5945	1.0694		145.00	.1264	-.2170	.0527	.5945	1.0694	.10355	
	150.00	.0963	-.3175	.0486	.5754	1.1892	.1030	-.12767	.0541	.5502	1.1589		150.00	.0963	-.3175	.0486	.5754	1.1892		150.00	.0963	-.3175	.0486	.5754	1.1892	.1589	
	155.00	.0704	-.4082	.0426	.5313	1.3061	.0770	-.13774	.0475	.5123	1.2809		155.00	.0704	-.4082	.0426	.5313	1.3061		155.00	.0704	-.4082	.0426	.5313	1.3061	.12809	
	160.00	.0456	-.4825	.0342	.4662	1.4087	.0542	-.14597	.0399	.4483	1.3974		160.00	.0456	-.4825	.0342	.4662	1.4087		160.00	.0456	-.4825	.0342	.4662	1.4087	.13974	
	165.00	.0307	-.5155	.0259	.3693	1.4969	.0370	-.15208	.0312	.4379	1.3712		165.00	.0307	-.5155	.0259	.3693	1.4969		165.00	.0307	-.5155	.0259	.3693	1.4969	.13712	
	170.00	.0200	-.5792	.0181	.2817	1.5540	.0238	-.15597	.0215	.4274	1.3555		170.00	.0200	-.5792	.0181	.2817	1.5540		170.00	.0200	-.5792	.0181	.2817	1.5540	.13555	
	175.00	.0185	-.6345	.0109	.2328	1.5635	.0169	-.15637	.0155	.4106	1.3214		175.00	.0185	-.6345	.0109	.2328	1.5635		175.00	.0185	-.6345	.0109	.2328	1.5635	.13214	
	180.00	.0100	-.7059	.0054	.2066	1.5200	.0146	-.15646	.0105	.3906	1.2066		180.00	.0100	-.7059	.0054	.2066	1.5200		180.00	.0100	-.7059	.0054	.2066	1.5200	.12066	
	185.00	.0050	-.7512	.0026	.1771	1.4800	.0127	-.15654	.0082	.3548	1.1611		185.00	.0050	-.7512	.0026	.1771	1.4800		185.00	.0050	-.7512	.0026	.1771	1.4800	.11611	
	190.00	.0049	-.8080	.0083	.1110	1.2800	.0108	-.15662	.0059	.3488	1.0530		190.00	.0049	-.8080	.0083	.1110	1.2800		190.00	.0049	-.8080	.0083	.1110	1.2800	.10530	
	195.00	.0042	-.8623	.0080	.1110	1.2800	.0108	-.15671	.0059	.3488	1.0530		195.00	.0042	-.8623	.0080	.1110	1.2800		195.00	.0042						

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	a_s deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
2121	-5.00	-.0822	.8506	.0128	-.0078	.8546	-.0744	.8602	.0097	.0009	.8634
	-3.00	-.0517	.8544	.0089	-.0069	.8559	-.0428	.8635	.0053	.0025	.8645
	-1.00	-.0211	.8594	.0043	-.0061	.8597	-.0170	.8619	.0034	-.0020	.8621
	.00	-.0082	.8606	.0022	-.0082	.8606	-.0035	.8623	.0016	-.0035	.8623
	1.00	.0061	.8612	.0003	-.0089	.8612	.0100	.8616	-.0008	-.0050	.8617
	3.00	.0335	.8603	-.0035	-.0115	.8609	.0376	.8617	-.0047	-.0076	.8625
	5.00	.0620	.8606	-.0072	-.0132	.8627	.0663	.8613	-.0083	-.0091	.8638
	10.00	.1313	.8654	-.0154	-.0210	.8751	.1345	.8612	-.0166	-.0170	.8715
	15.00	.2049	.8681	-.0246	-.0268	.8915	.2050	.8595	-.0254	-.0245	.8833
	20.00	.2827	.8669	-.0342	-.0308	.9113	.2793	.8545	-.0348	-.0298	.8985
	16.00	.2476	.8703	-.0322	-.0019	.9048	.2287	.8495	-.0294	-.0130	.8748
	20.00	.3077	.8671	-.0397	-.0075	.9200	.2855	.8394	-.0365	-.0188	.8864
	25.00	.3814	.8547	-.0487	-.0155	.9358	.3632	.8337	-.0457	-.0231	.9091
	30.00	.4622	.8542	-.0578	-.0268	.9709	.4385	.8243	-.0540	-.0325	.9332
	35.00	.5354	.8445	-.0647	-.0458	.9989	.5076	.8113	-.0604	-.0495	.9557
	40.00	.5894	.8226	-.0685	-.0773	1.0090	.5640	.7833	-.0645	-.0715	.9625
	45.00	.6277	.7775	-.0699	-.1059	.9937	.6034	.7356	-.0661	-.0935	.9469
	50.00	.6505	.7171	-.0694	-.1312	.9592	.6259	.6715	-.0660	-.1121	.9111
	45.00	.6138	.7493	-.0693	-.0958	.9638	.5949	.7308	-.0676	-.0961	.9375
	50.00	.6333	.6918	-.0697	-.1228	.9298	.6186	.6742	-.0682	-.1189	.9073
	55.00	.6462	.6330	-.0704	-.1479	.8924	.6314	.6124	-.0686	-.1394	.8685
	60.00	.6489	.5739	-.0708	-.1725	.8490	.6314	.5476	-.0687	-.1585	.8206
	65.00	.6438	.5078	-.0716	-.1881	.7981	.6324	.4909	-.0696	-.1776	.7807
	70.00	.6338	.4415	-.0720	-.1981	.7466	.6240	.4289	-.0699	-.1896	.7331
	75.00	.6201	.3825	-.0721	-.2090	.6980	.6106	.3713	-.0698	-.2006	.6859
	75.00	.5994	.3797	-.0718	-.2117	.6773	.5985	.3628	-.0704	-.1955	.6720
	80.00	.5839	.3180	-.0711	-.2118	.6302	.5619	.3042	-.0692	-.1986	.6259
	85.00	.5676	.2545	-.0697	-.2040	.5876	.5641	.2161	-.0675	-.1940	.5835
	90.00	.5509	.1868	-.0672	-.1868	.5509	.5448	.1055	-.0648	-.1855	.5448
	95.00	.5325	.1083	-.0643	-.1543	.5211	.5220	.1166	-.0613	-.1617	.5098
	100.00	.5127	.0216	-.0618	-.1103	.5011	.4989	.0389	-.0587	-.1249	.4845
	105.00	.4924	-.0946	-.0599	-.0360	.5001	.4737	-.0665	-.0570	-.0584	.4748
	110.00	.4708	-.2379	-.0565	-.0426	.5238	.4477	.2079	-.0538	-.0423	.4918
	105.00	.4706	-.1300	-.0599	-.0038	.4882	.4671	-.0058	-.0566	-.0284	.4760
	110.00	.4476	-.2729	-.0564	-.1033	.5159	.4383	.2424	-.0531	.0779	.4948
	115.00	.4130	-.4595	-.0487	-.2419	.5685	.4048	.0472	-.0467	.1979	.5390
	120.00	.3782	-.6271	-.0403	-.3540	.6411	.3625	.5926	-.0384	.3319	.6102
	125.00	.3312	-.8305	-.0278	-.4903	.7477	.3132	.7908	-.0269	.4682	.7102
	130.00	.2811	-.1.0202	-.0131	-.6008	.8711	.2585	.9946	-.0124	.5957	.8373
	135.00	.2252	-.1.2115	-.0018	-.6975	1.0159	.2038	-.1.1834	-.0019	.6927	.9809
2122	45.00	.6096	.7506	-.0693	-.0997	.9619	.5968	.7344	-.0680	-.0973	.9413
	50.00	.6305	.6908	-.0702	-.1239	.9270	.6203	.6786	-.0686	-.1211	.9114
	55.00	.6421	.6333	-.0703	-.1505	.8892	.6332	.6166	-.0690	-.1419	.8724
	60.00	.6435	.5658	-.0705	-.1682	.8402	.6366	.5491	-.0690	-.1572	.8259
	65.00	.6391	.4958	-.0691	-.1792	.7887	.6319	.4837	-.0680	-.1713	.7771
	70.00	.6292	.4289	-.0667	-.1878	.7380	.6259	.4187	-.0661	-.1793	.7314
	75.00	.6250	.3670	-.0638	-.1965	.6790	.6057	.3535	-.0635	-.1847	.6766
	80.00	.5932	.3012	-.0596	-.1936	.6365	.5934	.2914	-.0592	-.1840	.6350
	85.00	.5825	.2310	-.0538	-.1793	.6004	.5809	.2283	-.0539	-.1768	.5986
	90.00	.5713	.1560	-.0465	-.1560	.5713	.5671	.1580	-.0469	-.1580	.5671
	95.00	.5652	.0682	-.0372	-.1170	.5552	.5535	.0752	-.0377	-.1231	.5448
	100.00	.5549	-.0253	-.0257	-.0715	.5509	.5405	.0119	-.0265	-.0822	.5334
	105.00	.5482	-.1338	-.0124	-.0127	.5641	.5328	.1182	-.0126	-.0237	.5452
	110.00	.5390	-.2542	-.0021	-.0546	.5934	.5133	.2343	-.0024	.0446	.5624
	105.00	.5181	-.1666	-.0092	-.0268	.5435	.5179	.1508	-.0088	.0117	.5393
	110.00	.5032	.2842	-.0039	-.0950	.5701	.4977	.2694	-.0057	.0830	.5598
	115.00	.4746	.4073	-.0165	-.1685	.6022	.6641	.3934	-.0195	.1604	.5869
	120.00	.4393	.5284	-.0283	-.2379	.6446	.4267	.5162	-.0317	.2336	.6276
	125.00	.3888	.6590	-.0390	-.3168	.6965	.3725	.6520	-.0433	.3204	.6791
	130.00	.3289	.7962	-.0484	-.3985	.7638	.3165	.7875	-.0527	.3999	.7487
	135.00	.2699	.9340	-.0538	-.4696	.8512	.2589	.9194	-.0579	.4670	.8332
2123	45.00	.6132	.7514	-.0696	-.0977	.9649	.5973	.7369	-.0680	-.0987	.9435
	50.00	.6318	.6893	-.0695	-.1219	.9271	.6212	.6787	-.0684	-.1206	.9122
	55.00	.6435	.6373	-.0705	-.1529	.8926	.6339	.6167	-.0690	-.1432	.8772
	60.00	.6454	.5713	-.0707	-.1721	.8446	.6382	.5568	-.0697	-.1614	.8301
	65.00	.6426	.5021	-.0729	-.1835	.7946	.6308	.4841	-.0705	-.1721	.7763
	70.00	.6366	.4341	-.0765	-.1902	.7467	.6243	.4232	-.0733	-.1842	.7313
	75.00	.6337	.3706	-.0816	-.1940	.7080	.6149	.3583	-.0765	-.1870	.6867
	75.00	.6093	.3693	-.0788	-.1990	.6841	.6090	.3570	-.0774	-.1872	.6807
	80.00	.5975	.3010	-.0832	-.1926	.6407	.5966	.2943	-.0805	-.1862	.6386
	85.00	.5857	.2333	-.0873	-.1814	.6038	.5820	.2326	-.0834	-.1810	.6001
	90.00	.5711	.1618	-.0909	-.1618	.5711	.5638	.1678	-.0858	-.1678	.5638
	95.00	.5559	.0784	-.0964	-.1266	.5470	.5436	.0952	-.0890	-.1422	.5332
	100.00	.5458	-.0169	-.1062	-.0782	.5404	.5286	.0076	-.0982	-.0993	.5193
	105.00	.5386	-.1481	-.1216	-.0037	.5585	.5201	-.1188	-.1158	-.0198	.5331
	110.00	.5319	.3265	-.1395	-.1249	.6115	.5140	.3037	-.1402	-.1096	.5869
	105.00	.5200	.1922	-.1247	-.0511	.5520	.5109	.1662	-.1210	.0283	.5365
	110.00	.5126	.3847	-.1429	-.1862	.6133	.5035	.3530	-.1440	.1595	.5938
	115.00	.5075	.6031	-.1703	-.3321	.7149	.5086	.6067	-.1871	.3350	.7173
	120.00	.4894	.8897	-.1851	-.5258	.8687	.4714	.8346	-.1848	.4871	.8255
	125.00	.4300	.1.0916	-.1578	.6474	.9783	.4166	-.1056	.1679	.6337	.9524
	130.00	.3664	-.1.2938	-.1209	.7556	1.1123	.3515	-.1.2844	-.1346	.7580	1.0949
	135.00	.2705	-.1.4497	-.0601	.8338	1.2164	.2675	-.1.4516	-.0847	.8372	1.2156

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
3121	-5.00	-.0690	.8672	.0088	.0069	.8699	-.0645	.8710	.0088	.0116	.8733
	-3.00	-.0395	.8709	.0055	.0062	.8718	-.0354	.8732	.0048	.0103	.8739
	-1.00	-.0112	.8672	.0013	.0039	.8673	-.0085	.8760	.0014	.0068	.8760
	.00	.0045	.8763	-.0006	.0045	.8763	.0047	.8761	-.0005	.0047	.8761
	1.00	.0195	.8786	-.0029	.0042	.8788	.0178	.8752	-.0077	.0025	.8754
	3.00	.0464	.8796	-.0061	.0003	.8808	.0433	.8781	-.0058	-.0027	.8772
	5.00	.0736	.8807	-.0092	-.0035	.8838	.0698	.8749	-.0091	-.0068	.8777
	10.00	.1442	.8806	-.0168	-.0109	.8922	.1365	.8789	-.0169	-.0182	.8892
	15.00	.2153	.8910	-.0246	-.0226	.9163	.2046	.8826	-.0242	-.0308	.9055
	20.00	.2967	.9009	-.0331	-.0293	.9481	.2831	.8851	-.0328	-.0367	.9285
	16.00	.2382	.9050	-.0269	-.0205	.9356	.2214	.8747	-.0257	-.0283	.9018
	20.00	.2967	.9064	-.0333	-.0312	.9532	.2802	.8789	-.0315	-.0373	.9217
	25.00	.3849	.9130	-.0418	-.0371	.9902	.3636	.8836	-.0394	-.0439	.9545
	30.00	.4655	.9191	-.0475	-.0565	1.0288	.4451	.8847	-.0451	-.0569	.9888
	35.00	.5414	.9130	-.0515	-.0802	1.0584	.5155	.8763	-.0484	-.0803	1.0135
	40.00	.6033	.8973	-.0530	-.1146	1.0752	.5785	.8531	-.0500	-.1052	1.0254
	45.00	.6456	.8487	-.0517	-.1436	1.0566	.6187	.7974	-.0487	-.1263	1.0013
	50.00	.6660	.7745	-.0493	-.1652	1.0080	.6412	.7221	-.0463	-.1410	.9555
	45.00	.6330	.8037	-.0510	-.1207	1.0159	.6124	.7917	-.0498	-.1268	.9928
	50.00	.6546	.7297	-.0496	-.1382	.9704	.6358	.7189	-.0480	-.1420	.9491
	55.00	.6646	.6620	-.0490	-.1611	.9281	.6506	.6411	-.0480	-.1520	.9006
	60.00	.6752	.5848	-.0498	-.1688	.8771	.6567	.5605	-.0487	-.1570	.8490
	65.00	.6734	.5072	-.0515	-.1751	.8247	.6562	.4830	-.0500	-.1604	.7988
	70.00	.6628	.4459	-.0519	-.1923	.7753	.6462	.4114	-.0506	-.1656	.7479
	75.00	.6593	.4580	-.0523	-.2718	.7553	.6383	.3502	-.0518	-.1731	.7072
	75.00	.6273	.3626	-.0529	-.1878	.6997	.6306	.3480	-.0526	-.1729	.6992
	80.00	.6202	.3008	-.0539	-.1885	.6630	.6185	.2893	-.0527	-.1775	.6593
	85.00	.6044	.2361	-.0532	-.1825	.6227	.6057	.2308	-.0520	-.1771	.6235
	90.00	.5944	.1683	-.0522	-.1683	.5944	.5901	.1700	-.0504	-.1700	.5901
	95.00	.5775	.0897	-.0501	-.1397	.5675	.5690	.1028	-.0479	-.1520	.5578
	100.00	.5643	.0059	-.0489	-.1038	.5547	.5502	.0279	-.0463	-.1230	.5370
	105.00	.5467	-.1061	-.0481	-.0390	.5556	.5319	.0749	-.0459	-.0654	.5332
	110.00	.5260	-.2471	-.0456	-.0520	.5795	.5026	.2185	-.0435	-.0334	.5470
	105.00	.5273	-.1147	-.0484	-.0004	.5460	.5163	.1036	-.0452	-.0335	.5255
	110.00	.5021	-.2834	-.0455	-.0946	.5687	.4873	.2478	-.0423	-.0662	.5427
	115.00	.4637	-.4587	-.0395	-.2197	.6142	.4471	.4274	-.0365	.1984	.5858
	120.00	.4246	-.6284	-.0316	.3319	.6819	.4083	.5953	-.0304	.3113	.6513
	125.00	.3776	-.8321	-.0207	.4650	.7866	.3544	.7990	-.0198	.4512	.7486
	130.00	.3209	-1.0302	-.0068	.5829	.9080	.2958	.9998	-.0067	.5758	.8693
	135.00	.2587	-1.2069	-.0065	.6705	1.0363	.2364	-1.1934	-.0067	.6767	1.0111
3122	45.00	.6276	.8024	-.0521	-.1236	1.0112	.6052	.7870	-.0504	-.1286	.9844
	50.00	.6489	.7301	-.0506	-.1422	.9664	.6302	.7156	-.0488	-.1431	.9428
	55.00	.6595	.6528	-.0500	-.1564	.9146	.6448	.6335	-.0485	-.1491	.8916
	60.00	.6672	.5758	-.0502	-.1651	.8657	.6508	.5550	-.0489	-.1552	.8411
	65.00	.6637	.4946	-.0495	-.1678	.8105	.6510	.4745	-.0488	-.1549	.7905
	70.00	.6613	.4233	-.0485	-.1716	.7662	.6461	.4068	-.0478	-.1613	.7462
	75.00	.6546	.3528	-.0464	-.1714	.7236	.6384	.3436	-.0462	-.1667	.7055
	75.00	.6294	.3527	-.0450	-.1778	.6995	.6291	.3345	-.0455	-.1603	.6943
	80.00	.6242	.2860	-.0421	-.1733	.6644	.6190	.2714	-.0423	-.1598	.6567
	85.00	.6166	.2157	-.0375	-.1612	.6331	.6166	.2097	-.0382	-.1552	.6326
	90.00	.6106	.1412	-.0315	-.1412	.6106	.6083	.1414	-.0327	-.1414	.6083
	95.00	.6080	.0560	-.0233	-.1088	.6008	.5991	.0631	-.0247	-.1151	.5913
	100.00	.6043	-.0362	-.0130	-.0692	.6014	.5889	-.0216	-.0143	-.0810	.5838
	105.00	.6011	-.1436	-.0005	-.0169	.6178	.5772	-.1256	-.0011	-.0281	.5900
	110.00	.5926	-.2599	-.0130	.0415	.6458	.5612	-.2430	-.0134	-.0364	.6105
	105.00	.5833	-.1769	-.0027	.0199	.6092	.5717	-.1519	-.0016	-.0013	.5915
	110.00	.5678	-.2959	-.0152	.0839	.6348	.5542	-.2713	-.0156	-.0654	.6156
	115.00	.5346	-.4146	-.0268	.1499	.6597	.5204	-.3936	-.0285	.1368	.6379
	120.00	.4978	-.5319	-.0373	.2117	.6971	.4756	.5159	-.0396	.2090	.6699
	125.00	.4399	-.6668	-.0473	.2939	.7428	.4157	.6527	-.0504	.2963	.7149
	130.00	.3751	-.7975	-.0552	.3698	.7999	.3539	.7840	-.0585	.3731	.7750
	135.00	.3094	-.9371	-.0600	.4458	.8814	.2892	.9305	-.0635	.4535	.8625
3123	45.00	.6308	.8063	-.0516	-.1241	1.0161	.6108	.7930	-.0502	-.1288	.9926
	50.00	.6501	.7302	-.0498	-.1415	.9674	.6352	.7169	-.0488	-.1409	.9474
	55.00	.6633	.6597	-.0494	-.1599	.9217	.6505	.6422	-.0483	-.1530	.9013
	60.00	.6634	.5778	-.0497	-.1687	.8634	.6566	.5611	-.0488	-.1576	.8492
	65.00	.6634	.4960	-.0528	-.1691	.8108	.6567	.4821	-.0511	-.1594	.7989
	70.00	.6631	.4216	-.0572	-.1694	.7673	.6548	.4100	-.0549	-.1613	.7555
	75.00	.6582	.3533	-.0619	-.1709	.7272	.6484	.3466	-.0585	-.1670	.7160
	75.00	.6404	.3574	-.0606	-.1795	.7111	.6377	.3400	-.0594	-.1634	.7040
	80.00	.6332	.2869	-.0661	-.1725	.6734	.6298	.2774	-.0638	-.1638	.6684
	85.00	.6255	.2181	-.0714	-.1628	.6421	.6193	.2149	-.0680	-.1601	.6356
	90.00	.6137	.1472	-.0760	-.1472	.6137	.6073	.1519	-.0716	-.1519	.6073
	95.00	.6059	.0645	-.0833	-.1171	.5980	.5912	.0828	-.0762	-.1340	.5818
	100.00	.5977	-.0316	-.0940	-.0727	.5941	.5785	-.0016	-.0860	-.0989	.5700
	105.00	.5929	-.1573	-.1097	-.0016	.6134	.5717	-.1287	-.1049	-.0237	.5855
	110.00	.5863	-.3249	-.1268	.1048	.6620	.5653	.3091	-.1290	-.0972	.6369
	105.00	.5797	-.2069	-.1150	.0499	.6134	.5643	-.1705	-.1096	.0186	.5892
	110.00	.5662	-.3861	-.1294	.1691	.6642	.5568	.3590	-.1335	.1469	.6460
	115.00	.5535	-.5864	-.1471	.2976	.7494	.5584	.5975	-.1729	.3055	.7586
	120.00	.5405	-.8796	-.1751	.4915	.9079	.5225	.8409	-.1781	.4669	.8730
	125.00	.4829	-1.1001	-.1514	.6241	1.0266	.4610	-1.0640	-.1613	.6072	.9879
	130.00	.4100	-1.3017	-.1152	.7337	1.1508	.3937	-1.2748	-.1328	.7234	1.1210
	135.00	.3115	-1.4435	-.0560	.8004	1.2410	.3024	-1.4472	-.0801	.8095	1.2371

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
1221	-5.00	-.0859	.6493	.0018	-.0290	.6543	-.0817	.6390	.0007	-.0257	.6437
	-3.00	-.0490	.6528	.0006	-.0147	.6545	-.058	.6452	-.0006	-.0119	.6447
	-1.00	-.0122	.6567	-.0010	-.0007	.6568	-.0093	.6479	-.0021	.0020	.6480
	.00	.0075	.6587	-.0019	.0075	.6587	.0072	.6482	-.0024	.0072	.6482
	1.00	.0230	.6589	-.0026	.0115	.6592	.0249	.6493	-.0033	.0136	.6496
	3.00	.0562	.6592	-.0040	.0216	.6612	.0581	.6488	-.0042	.0240	.6509
	5.00	.0921	.6569	-.0056	.0345	.6624	.0935	.6486	-.0052	.0366	.6512
	10.00	.1829	.6640	-.0096	.0648	.6857	.1832	.6515	-.0089	.0675	.6734
	15.00	.2762	.6707	-.0145	.0932	.7193	.2754	.6531	-.0132	.0970	.7021
	20.00	.3744	.6776	-.0203	.1200	.7648	.3714	.6551	-.0190	.1249	.7426
	17.00	.3388	.6780	-.0191	.1258	.7475	.3123	.6378	-.0152	.1122	.7012
	20.00	.4017	.6773	-.0229	.1458	.7739	.3757	.6456	-.0174	.1322	.7352
	25.00	.5088	.6832	-.0313	.1724	.8342	.4799	.6439	-.0256	.1628	.7864
	30.00	.6090	.6842	-.0392	.1853	.8970	.5698	.6506	-.0305	.1682	.8483
	35.00	.7067	.6833	-.0451	.1870	.9650	.6709	.6499	-.0408	.1771	.9168
	40.00	.7898	.6818	-.0511	.1667	1.0300	.7516	.6426	-.0470	.1627	.9754
	45.00	.8526	.6670	-.0535	.1313	1.0745	.8131	.6272	-.0506	.1315	1.0185
	50.00	.8873	.6391	-.0543	.0807	1.0905	.8477	.6004	-.0509	.0850	1.0353
	45.00	.8088	.6186	-.0647	.1345	1.0093	.7843	.6079	-.0596	.1247	.9845
	50.00	.8516	.5926	-.0668	.0934	1.0333	.8296	.5834	-.0580	.0864	1.0105
	55.00	.8691	.5624	-.0694	.0378	1.0345	.8518	.5585	-.0617	.0311	1.0181
	60.00	.8757	.5359	-.0736	-.0262	1.0264	.8626	.5283	-.0663	-.0262	1.0112
	65.00	.8816	.5019	-.0772	-.0823	1.0111	.8672	.5003	-.0681	-.0869	.9974
	70.00	.8756	.4413	-.0794	-.1340	.9806	.8658	.4591	-.0710	-.1353	.9706
	75.00	.8683	.4139	-.0840	-.1761	.9420	.8529	.4137	-.0751	-.1789	.9309
	72.00	.8527	.3684	-.0881	-.1989	.9073	.8385	.3767	-.0768	-.2098	.8950
	75.00	.8161	.3945	-.0747	-.1699	.8904	.8249	.4041	-.0690	-.1768	.9014
	80.00	.7982	.3448	-.0784	-.2013	.8440	.8103	.3557	-.0744	-.2096	.8598
	85.00	.7659	.2846	-.0797	-.2167	.7878	.7831	.2979	-.0753	-.2285	.8061
	90.00	.7447	.2175	-.0805	-.2175	.7447	.7579	.2352	-.0761	-.2352	.7579
	95.00	.7250	.1481	-.0801	-.2107	.7093	.7249	.1659	-.0754	-.2285	.7076
	100.00	.6878	.0496	-.0788	-.1682	.6688	.6869	.0758	-.0749	-.1939	.6633
	105.00	.6623	-.0695	-.0779	-.1043	.6577	.6493	-.0362	-.0741	-.1331	.6366
	110.00	.6204	-.2229	-.0739	-.0027	.6522	.6058	-.1897	-.0703	-.0289	.6342
	107.00	.6514	-.1116	-.0776	-.0837	.6555	.6204	-.0821	-.0698	-.1029	.6173
	110.00	.6267	-.2092	-.0742	-.0177	.6605	.5964	-.1837	-.0677	-.0314	.6232
	115.00	.5770	-.3923	-.0646	.1116	.6887	.5449	-.3628	-.0604	.0985	.6471
	120.00	.5200	-.6020	-.0549	.2613	.7513	.4858	-.5567	-.0505	.2392	.6991
	125.00	.4596	.7940	-.0402	.3986	.8319	.4161	.5790	-.0344	.3830	.7761
	130.00	.3894	-.9994	-.0202	.5153	.9407	.3508	.9602	-.0188	.5101	.8859
	135.00	.3197	-.1.1819	-.0008	.6096	1.0618	.2813	-.1.1400	-.0013	.6100	1.0078
	140.00	.2586	-.1.3292	.0155	.6563	1.1844	.2231	-.1.3026	-.0144	.6664	1.1412
	135.00	.2647	-.1.2000	-.0071	.6613	1.0357	.2513	-.1.1555	-.0074	.6394	.9948
	140.00	.1987	-.1.3539	.0108	.7181	1.1648	.1891	-.1.3032	-.0099	.6928	1.1199
	145.00	.1413	-.1.4448	.0171	.7130	1.2645	.1394	-.1.4150	-.0206	.6974	1.2391
	150.00	.1039	-.1.5261	.0245	.6731	1.3736	.1022	-.1.5044	-.0264	.6657	1.3539
	155.00	.0739	-.1.5932	.0259	.6063	1.4751	.0751	-.1.5719	-.0282	.5962	1.4563
	160.00	.0452	-.1.6307	.0240	.5152	1.5479	.0503	-.1.6369	-.0304	.5126	1.5554
	165.00	.0208	-.1.6738	.0200	.4131	1.6222	.0318	-.1.6726	-.0270	.4022	1.6238
	169.00	.0042	-.1.6982	.0142	.3199	1.6678	.0150	-.1.6924	-.0200	.3082	1.6642
	165.00	.0163	-.1.6257	.0212	.4051	1.5745	.0260	-.1.6398	-.0231	.3993	1.5906
	170.00	-.0026	-.1.6527	.0145	.2896	1.6271	.0085	-.1.6816	-.0170	.2836	1.6576
	175.00	-.0104	-.1.6687	.0090	.1558	1.6615	.0000	-.1.6957	-.0103	.1478	1.6893
	177.00	-.0106	-.1.6744	.0062	.0982	1.6715	-.0017	-.1.7034	-.0065	.0909	1.7010
	179.00	-.0090	-.1.6839	.0037	.0384	1.6834	-.0009	-.1.7058	-.0034	.0289	1.7055
	180.00	-.0068	-.1.6883	.0022	.0068	1.6883	-.0031	-.1.7099	-.0013	-.0031	1.7099
	181.00	-.0041	-.1.6906	.0003	-.0254	1.6904	-.0044	-.1.7074	-.0011	-.0342	1.7070
	183.00	-.0006	-.1.6915	-.0029	-.0891	1.6892	-.0067	-.1.7070	-.0045	-.0960	1.7043
	185.00	-.0032	-.1.6954	-.0053	-.1510	1.6887	-.0068	-.1.7035	-.0125	-.1553	1.6964
1222	17.00	.3137	.6839	-.0124	.1000	.7457	.2928	.6584	-.0074	.0875	.7152
	20.00	.3724	.6836	-.0162	.1161	.7698	.3528	.6591	-.0121	.1061	.7400
	25.00	.4845	.6927	-.0247	.1464	.8326	.4557	.6626	-.0201	.1330	.7931
	30.00	.5880	.6932	-.0319	.1626	.8943	.5561	.6605	-.0282	.1513	.8501
	35.00	.6791	.6877	-.0397	.1618	.9528	.6501	.6593	-.0356	.1543	.9130
	40.00	.7730	.6909	-.0460	.1480	1.0262	.7309	.6502	-.0417	.1420	.9679
	45.00	.8254	.6707	-.0470	.1093	1.0579	.7971	.6363	-.0467	.1137	1.0135
	50.00	.8658	.6453	-.0489	.0609	1.0765	.8323	.6087	-.0462	.0687	1.0289
	45.00	.8046	.6173	-.0534	.1324	1.0054	.7812	.6063	-.0498	.1237	.9811
	50.00	.8487	.5954	-.0546	.0894	1.0328	.8250	.5853	-.0515	.0819	1.0082
	55.00	.8733	.5643	-.0577	.0387	1.0391	.8524	.5606	-.0549	.0297	1.0197
	60.00	.8783	.5334	-.0617	-.0227	1.0273	.8606	.5333	-.0590	-.0315	1.0120
	65.00	.8799	.4972	-.0643	-.0787	1.0076	.8639	.4965	-.0620	-.0849	.9928
	70.00	.8785	.4552	-.0648	-.1282	.9787	.8593	.4549	-.0631	-.1.336	.9631
	75.00	.8677	.4017	-.0657	-.1634	.9421	.8479	.4065	-.0649	-.1.732	.9242
	79.00	.8606	.3562	-.0654	-.1855	.9128	.8366	.3619	-.0654	-.1.957	.8903
	75.00	.8016	.3844	-.0683	-.1638	.8738	.8154	.3925	-.0650	-.1.681	.8892
	80.00	.7825	.3299	-.0676	-.1890	.8279	.7953	.3378	-.0642	-.1.946	.8419
	85.00	.7690	.2660	-.0653	-.1980	.7893	.7836	.2731	-.0636	-.2.038	.8044
	90.00	.7531	.1969	-.0604	-.1969	.7531	.7638	.2044	-.0607	-.2.044	.7638
	95.00	.7361	.1089	-.0542	-.1727	.7238	.7383	.1212	-.0546	-.1.851	.7249
	100.00	.7200	.0083	-.0446	-.1332	.7077	.7149	.0232	-.0447	-.1.469	.7000
	105.00	.7049	-.1031	-.0330	-.0828	.7076	.6913	-.0850	-.0330	-.0968	.6897
	110.00	.6774	-.2262	-.0199	-.0191	.7139	.6587	-.2103	-.0186	-.0277	.6909

TABLE I--AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Config- uration	α , deg	$M_{\infty} = 3.5$					$M_{\infty} = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
1222	107.00	.7056	-.1426	-.0288	-.0699	.7165	.6646	-.1221	-.0257	-.0775	.6713
	110.00	.6870	-.2224	-.0198	-.0260	.7217	.6502	-.2031	-.0166	-.0315	.6805
	115.00	.6409	-.3471	-.0064	.0437	.7276	.6041	-.3373	-.0026	.0504	.6900
	120.00	.5814	-.4935	.0082	.1367	.7503	.5449	-.4683	.0120	.1331	.7061
	125.00	.5177	-.6246	.0210	.2147	.7825	.4742	-.6017	.0250	.2209	.7335
	130.00	.4390	-.7682	.0349	.3063	.8301	.4014	-.7491	.0378	.3158	.7890
	135.00	.3688	-.9127	.0444	.3846	.9062	.3341	-.8851	.0463	.3897	.8621
	140.00	.3029	-.1.0398	.0508	.4364	.9912	.2735	-.1.0064	.0510	.4374	.9467
	135.00	.3130	-.9161	.0440	.4265	.8691	.3019	-.8738	.0486	.4044	.8314
	140.00	.2513	-.1.0516	.0484	.4835	.9671	.2413	-.1.0110	.0506	.4651	.9296
	145.00	.1959	-.1.1836	.0453	.5184	1.0819	.1936	-.1.1351	.0495	.4925	1.0408
	150.00	.1465	-.1.2957	.0438	.5210	1.1954	.1543	-.1.2491	.0481	.4910	1.1589
	155.00	.1153	-.1.3683	.0398	.4738	1.2888	.1201	-.1.3507	.0442	.4620	1.2750
	160.00	.0839	-.1.4542	.0357	.4186	1.3952	.0876	-.1.4372	.0390	.4093	1.3805
	165.00	.0506	-.1.5315	.0264	.3475	1.4924	.0590	-.1.5136	.0313	.3347	1.4773
	169.00	.0272	-.1.5697	.0195	.2728	1.5461	.0367	-.1.5517	.0242	.2601	1.5302
	165.00						.0533	-.1.4905	.0287	.3343	1.4535
	170.00	.0202	-.1.5257	.0183	.2450	1.5060	.0290	-.1.5351	.0213	.2380	1.5168
	175.00	.0017	-.1.5531	.0117	.1337	1.5473	.0104	-.1.5640	.0136	.1259	1.5590
	177.00	-.0047	-.1.5637	.0089	.0865	1.5614	.0036	-.1.5749	.0092	.0788	1.5729
	179.00	-.0087	-.1.5681	.0049	.0361	1.5677	.0002	-.1.5807	.0054	.0274	1.5805
	180.00	-.0066	-.1.5699	.0038	.0066	1.5699	.0067	-.1.5834	.0022	-.0067	1.5834
	181.00	.0008	-.1.5747	.0002	-.0283	1.5745	.0015	-.1.5847	-.0003	-.0292	1.5845
	183.00	.0075	-.1.5760	-.0099	-.0900	1.5734	.0075	-.1.5932	-.0084	-.0909	1.5906
	185.00	.0029	-.1.5760	-.0118	-.1403	1.5697	.0011	-.1.5774	-.0112	-.1386	1.5713
1223	17.00	.3434	.6760	-.0211	.1308	.7469	.3184	.6697	-.0150	.1145	.7144
	20.00	.4094	.6777	-.0261	.1529	.7768	.3837	.6494	-.0188	.1385	.7414
	25.00	.5093	.6786	-.0317	.1748	.8302	.4806	.6508	-.0260	.1606	.7929
	30.00	.6082	.6809	-.0388	.1862	.8938	.5782	.6498	-.0338	.1758	.8518
	35.00	.7044	.6798	-.0471	.1871	.9609	.6696	.6662	-.0424	.1779	.9134
	40.00	.7876	.6728	-.0526	.1708	1.0217	.7558	.6114	-.0487	.1667	.9771
	45.00	.8551	.6649	-.0557	.1344	1.0748	.8148	.6264	-.0523	.1333	1.0191
	50.00	.8899	.6386	-.0566	.0828	1.0922	.8512	.6015	-.0532	.0865	1.0387
	45.00	.8065	.6195	-.0540	.1322	1.0084	.7856	.6084	-.0514	.1253	.9857
	50.00	.8470	.5896	-.0572	.0927	1.0278	.8249	.5890	-.0527	.0790	1.0105
	55.00	.8687	.5624	-.0590	.0376	1.0342	.8502	.5636	-.0557	.0260	1.0197
	60.00	.8769	.5366	-.0626	.0262	1.0277	.8620	.5360	-.0598	-.0332	1.0145
	65.00	.8782	.5006	-.0667	.0826	1.0075	.8640	.5015	-.0634	.0899	.9950
	70.00	.8741	.4566	-.0723	.1299	.9775	.8585	.4605	-.0683	.1391	.9642
	75.00	.8673	.4006	-.0828	.1625	.9415	.8508	.4083	-.0779	.1742	.9275
	79.00	.8616	.3541	-.0909	.1832	.9134	.8370	.3657	-.0881	.1993	.8914
	75.00	.8120	.3948	-.0812	.1711	.8845	.8242	.4002	-.0777	.1733	.8997
	80.00	.7988	.3386	-.0905	.1948	.8455	.8075	.3434	-.0856	.1980	.8548
	85.00	.7793	.2729	-.1000	.2040	.8001	.7850	.2821	-.0933	.2126	.8066
	90.00	.7626	.2113	-.1040	.2113	.7626	.7630	.2201	-.0999	.2201	.7630
	95.00	.7388	.1246	-.1147	.1885	.7251	.7325	.1477	-.1063	.2109	.7168
	100.00	.7152	.1715	-.1276	.1404	.7014	.7030	.0413	-.1203	.1628	.6851
	105.00	.6984	.1783	-.1445	.0665	.7052	.6821	-.0904	-.1391	-.0892	.6823
	110.00	.6771	.3132	-.1641	.0627	.7434	.6593	-.2922	-.1661	.0491	.7194
	107.00	.7022	.1808	-.1521	-.0324	.7244	.6641	-.1597	-.1479	-.0415	.6818
	110.00	.6840	.3086	-.1634	.0561	.7482	.6502	-.2877	-.1627	.0479	.7094
	115.00	.6547	.5340	-.1832	.2073	.8191	.6448	-.5710	-.2118	.2450	.8257
	120.00	.6273	.8465	-.2089	.4194	.9666	.5913	-.7977	-.2072	.3951	.9110
	125.00	.5566	.1059	-.1766	.5489	1.0638	.5191	-.1.0182	-.1.1837	.5366	1.0092
	130.00	.4672	.12694	-.1314	.6721	1.1739	.4356	-.1.2301	-.1.4240	.6623	1.1244
	135.00	.3688	.1.4185	-.0683	.7422	1.2638	.3364	-.1.3883	-.0827	.7438	1.2196
	140.00	.2732	.1.4923	-.0066	.7499	1.3188	.2428	-.1.4685	-.0189	.7579	1.2810
	135.00	.3154	.1.4261	-.0658	.7854	1.2314	.3158	-.1.4123	-.0912	.7754	1.2220
	140.00	.2132	.1.4894	-.0030	.7941	1.2779	.2125	-.1.4904	-.0231	.7952	1.2783
	145.00	.1465	.1.5547	-.0166	.7717	1.3575	.1425	-.1.5368	-.0154	.7648	1.3406
	150.00	.0992	.1.5972	-.0254	.7127	1.4328	.0943	-.1.5912	-.0275	.7139	1.4252
	155.00	.0646	.1.6437	-.0302	.6362	1.5170	.0643	-.1.6376	-.0346	.6338	1.5114
	160.00	.0377	.1.6701	-.0282	.5358	1.5823	.0390	-.1.6697	-.0328	.5345	1.5823
	165.00	.0158	.1.7191	-.0192	.4296	1.6646	.0174	-.1.7124	-.0267	.4264	1.6586
	169.00	.0030	.1.7378	-.0139	.3287	1.7065	.0057	-.1.7255	-.0204	.3236	1.6949
	165.00	.0065	.1.6564	.0259	.4224	1.6017	.0156	-.1.6818	-.0274	.4202	1.6285
	170.00	-.0104	.1.6781	.0182	.3016	1.6508	.0021	-.1.7022	-.0195	.2935	1.6767
	175.00	-.0139	.1.6928	.0114	.1613	1.6852	-.0028	-.1.7125	-.0111	.1521	1.7058
	177.00	-.0115	.1.6973	.0086	.1003	1.6944	-.0004	-.1.7190	-.0074	.0904	1.7166
	179.00	-.0082	.1.7061	.0058	.0380	1.7057	.0031	-.1.7355	-.0032	.0272	1.7353
	180.00	-.0077	.1.7114	.0040	.0077	1.7114	.0061	-.1.7353	-.0015	-.0061	1.7353
	181.00	-.0028	.1.7128	.0023	-.0271	1.7125	.0072	-.1.7226	-.0007	-.0373	1.7222
	183.00	.0000	.1.7126	-.0008	-.0896	1.7103	.0097	-.1.7333	-.0043	-.1004	1.7304
	185.00	.0025	.1.7170	-.0040	-.1522	1.7103	.0121	-.1.7245	-.0131	-.1624	1.7168

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
2221	-5.00	-.0844	.6356	.0013	-.0287	.6406	-.0830	.6369	.0007	-.0272	.6417
	-3.00	-.0493	.6388		-.0158	.6405	-.0459	.6402	-.0008	-.0123	.6417
	-1.00	-.0135	.6440	-.0009	-.0023	.6441	-.0110	.6419	-.0012	.0002	.6420
	.00	.0034	.6468	-.0010	.0034	.6468	.0038	.6419	-.0019	.0038	.6419
	1.00	.0210	.6485	-.0020	.0097	.6488	.0198	.6420	-.0024	.0086	.6422
	3.00	.0560	.6503	-.0035	.0219	.6523	.0873	.6427	-.0030	.0181	.6445
	5.00	.0894	.6519	-.0043	.0323	.6572	.1717	.6492	-.0061	.0564	.6691
	10.00	.1812	.6620	-.0064	.0634	.6838	.2674	.6576	-.0102	.0881	.7044
	15.00	.2769	.6760	-.0107	.0925	.7247	.3761	.6758	-.0155	.1223	.7636
	20.00	.3847	.6943	-.0156	.1240	.7840	.3084	.6523	-.0114	.1042	.7140
	17.00	.3272	.6852	-.0124	.1126	.7510	.3761	.6758	-.0155	.1223	.7636
	20.00	.3918	.6940	-.0144	.1308	.7861	.3795	.6636	-.0132	.1249	.7517
	25.00	.5090	.7105	-.0197	.1610	.8590	.4866	.6772	-.0188	.1548	.8194
	30.00	.6195	.7196	-.0242	.1767	.9330	.5881	.6835	-.0217	.1675	.8860
	35.00	.7221	.7282	-.0265	.1738	1.0107	.6881	.6908	-.0254	.1675	.9606
	40.00	.8040	.7261	-.0276	.1492	1.0730	.7707	.6833	-.0269	.1512	1.0188
	45.00	.8735	.7090	-.0283	.1164	1.1190	.8394	.6635	-.0287	.1243	1.0627
	50.00	.9068	.6657	-.0257	.0729	1.1225	.8776	.6245	-.0264	.0859	1.0736
	45.00	.8328	.6429	-.0342	.1343	1.0435	.8058	.6298	-.0325	.1245	1.0151
	50.00	.8811	.6151	-.0347	.0952	1.0704	.8529	.5992	-.0424	.0892	1.0386
	55.00	.9033	.5726	-.0366	.0491	1.0683	.8809	.5580	-.0337	.0482	1.0417
	60.00	.9081	.5385	-.0393	-.0123	1.0557	.8922	.5233	-.0355	-.0071	1.0344
	65.00	.9181	.5037	-.0402	.0685	1.0450	.9019	.4905	-.0379	-.0633	1.0247
	70.00	.9201	.4552	-.0443	-.1130	1.0203	.9037	.4482	-.0406	-.1121	1.0025
	75.00	.9131	.4109	-.0485	.1606	.9883	.8940	.4045	-.0450	.1593	.9682
	79.00	.9028	.3669	-.0535	.1879	.9562	.8800	.3658	-.0494	.1912	.9336
	75.00	.8678	.4078	-.0471	.1693	.9437	.8677	.3950	-.0460	.1569	.9403
	80.00	.8541	.3574	-.0519	-.2037	.9032	.8590	.3484	-.0505	.1939	.9065
	85.00	.8328	.2976	-.0553	-.2239	.8555	.8400	.2950	-.0535	.2207	.8625
	90.00	.8231	.2364	-.0568	-.2344	.8231	.8197	.2367	-.0549	.2367	.8197
	95.00	.8017	.1602	-.0564	.2295	.7947	.7926	.1702	-.0547	.2387	.7748
	100.00	.7755	.0692	-.0562	.2028	.7517	.7582	.0862	-.0536	.2166	.7317
	105.00	.7387	-.0517	-.0549	.1413	.7269	.7190	-.0211	-.0531	.1657	.7000
	110.00	.6967	-.2029	-.0515	.0476	.7241	.6720	-.1723	-.0510	.0479	.6904
	107.00	.7290	-.0893	-.0548	.1277	.7232	.8189	-.0736	-.0510	.1290	.8736
	110.00	.7011	-.1948	-.0529	.0568	.7256	.6515	-.1705	-.0486	.0626	.6705
	115.00	.6452	-.3723	-.0457	.0647	.7421	.6023	-.3528	-.0435	.0652	.6950
	120.00	.5852	-.5674	-.0366	.1988	.7905	.5398	-.5398	-.0347	.1976	.7374
	125.00	.5177	-.7727	-.0239	.3361	.8673	.4702	-.7412	-.0223	.3375	.8103
	130.00	.4402	-.9818	-.0053	.4691	.9683	.3940	-.9452	-.0065	.4708	.9094
	135.00	.3632	-.11636	.0113	.5660	1.0796	.3166	1.1318	-.0087	.5764	1.0242
	140.00	.2905	-.13017	.0254	.6142	1.1839	.2492	-.1274	.0214	.6285	1.1367
	135.00	.2961	-.11984	.0006	.6380	1.0568	.2858	-.1502	.0021	.6112	1.0154
	140.00	.2198	-.13337	.0149	.6889	1.1630	.2147	.1295	.0158	.6708	1.1335
	145.00	.1551	-.14411	.0225	.6995	1.2695	.1571	.14178	.0249	.6845	1.2515
	150.00	.1104	-.15016	.0252	.6552	1.3556	.1135	.15055	.0296	.6545	1.3606
	155.00	.0793	-.15671	.0268	.5904	1.4538	.0840	.15629	.0310	.5844	1.4520
	160.00	.0500	-.16217	.0262	.5077	1.5410	.0573	.16155	.0302	.4987	1.5377
	165.00	.0261	-.16639	.0209	.4055	1.6140	.0366	.16596	.0266	.3941	1.6126
	169.00	.0069	-.16902	.0140	.3157	1.6605	.0211	.16797	.0203	.2998	1.6528
2222	45.00	.8337	.6462	-.0349	.1326	1.0464	.8038	.6335	-.0324	.1204	1.0164
	50.00	.8728	.6093	-.0344	.0943	1.0603	.8521	.6017	-.0321	.0668	1.0395
	55.00	.8955	.5658	-.0366	.0501	1.0580	.8729	.5590	-.0321	.0428	1.0356
	60.00	.9002	.5300	-.0381	-.0089	1.0446	.8971	.5283	-.0354	-.0089	1.0411
	65.00	.9080	.4890	-.0398	-.0595	1.0296	.9006	.4872	-.0366	-.0610	1.0221
	70.00	.9116	.4400	-.0410	-.1017	1.0071	.9030	.4419	-.0379	.1064	.9996
	75.00	.9122	.3921	-.0426	.1426	.9826	.8963	.3990	-.0393	.1534	.9691
	79.00	.9056	.3457	-.0438	.1665	.9550	.8840	.3554	-.0406	.1802	.9356
	75.00	.8533	.3609	-.0490	.1277	.9176	.8773	.3746	-.0427	.1347	.9444
	80.00	.8449	.3072	-.0491	.1558	.8854	.8665	.3197	-.0428	.1643	.9088
	85.00	.8369	.2427	-.0476	.1689	.8549	.8534	.2611	-.0427	.1857	.8730
	90.00	.8271	.1765	-.0441	.1765	.8271	.8364	.1945	-.0403	.1945	.8364
	95.00	.8145	.0923	-.0382	.1629	.8034	.8141	.1120	-.0361	.1826	.8012
	100.00	.8018	-.0048	-.0285	.1345	.7904	.7931	.0200	-.0272	.1574	.7776
	105.00	.7815	-.1165	-.0161	.0898	.7851	.7656	-.0917	-.0150	.1095	.7630
	110.00	.7511	-.2381	-.0038	.0332	.7872	.7296	-.2128	-.0023	.0495	.7584
	107.00	.7885	-.1275	-.0068	-.1086	.7913	.7431	-.1135	-.0067	.1088	.7438
	110.00	.7652	-.2030	-.0006	-.0709	.7885	.7239	-.1941	-.0016	.0652	.7466
	115.00	.7138	-.3316	.0129	-.0012	.7870	.6716	-.3203	.0140	.0665	.7441
	120.00	.6490	-.4690	-.0254	.0817	.7965	.6050	-.4575	.0271	.0937	.7527
	125.00	.5799	-.6006	-.0362	.1594	.8195	.5310	-.5892	.0391	.1780	.7730
	130.00	.4970	-.7493	-.0467	.2545	.8623	.4493	-.7332	.0489	.2729	.8155
	135.00	.4094	-.8924	-.0553	.3415	.9205	.3714	-.8713	.0562	.3535	.8787
	140.00	.3361	-.10224	-.0584	.3997	.9992	.2999	-.10009	.0587	.4137	.9595
	135.00	.3413	-.9073	-.0472	.4003	.8829	.3353	-.8680	.0528	.3767	.8509
	140.00	.2672	-.10494	.0500	.4698	.9757	.2655	-.10070	.0548	.4439	.9421
	145.00	.2063	-.11788	-.0479	.5071	1.0839	.2108	-.13398	.0538	.4811	1.0546
	150.00	.1629	-.12702	-.0460	.4940	1.1815	.1705	-.12452	.0511	.4799	1.1637
	155.00	.1248	-.13721	-.0403	.4668	1.2962	.1305	-.13544	.0447	.4551	1.2827
	160.00	.0892	-.14535	-.0345	.4133	1.3963	.0963	-.14406	.0382	.4022	1.3866
	165.00	.0540	-.15191	-.0250	.3410	1.4813	.0640	-.15132	.0299	.3298	1.4782
	169.00	.0318	-.15555	.0191	.2656	1.5330	.0421	-.15471	.0233	.2539	1.5267

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Config- uration	$M_{\infty} = 3.5$						$M_{\infty} = 4.2$					
	α_0 deg	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D	
2223	45.00	.8365	.6461	-.0363	.1546	1.0484	.8085	.6333	-.0331	.1239	1.0195	
	50.00	.8784	.6145	-.0356	.0939	1.0679	.8550	.6012	-.0323	.0891	1.0414	
	55.00	.8977	.5723	-.0354	.0461	1.0637	.8853	.5623	-.0334	.0472	1.0477	
	60.00	.9053	.5376	-.0376	-.0129	1.0528	.8957	.5269	-.0354	-.0084	1.0392	
	65.00	.9143	.4987	-.0400	-.0656	1.0394	.9024	.4927	-.0376	-.0651	1.0261	
	70.00	.9208	.4496	-.0458	-.1076	1.0191	.9036	.4485	-.0421	-.1125	1.0025	
	75.00	.9181	.3950	-.0564	-.1439	.9890	.8986	.3998	-.0504	-.1536	.9715	
	79.00	.9119	.3476	-.0645	-.1672	.9614	.8878	.3561	-.0583	-.1802	.9394	
	75.00	.8671	.3874	-.0542	-.1948	.9379	.8751	.3846	-.0518	-.1450	.9448	
	80.00	.8601	.3303	-.0653	-.1759	.9044	.8652	.3306	-.0612	-.1754	.9095	
	85.00	.8482	.2678	-.0756	-.1929	.8683	.8500	.2720	-.0700	-.1969	.8705	
	90.00	.8346	.2002	-.0836	-.2002	.8346	.8306	.2117	-.0775	-.2117	.8306	
	95.00	.8175	.1226	-.0920	-.1934	.8037	.8037	.1433	-.0836	-.2129	.7981	
	100.00	.7963	.0225	-.1040	-.1605	.7803	.7787	.0534	-.0956	-.1878	.7576	
	105.00	.7770	-.1203	-.1231	-.0849	.7816	.7536	-.0867	-.1176	-.1113	.7503	
	110.00	.7539	.3059	-.1427	-.0297	.8130	.7279	.2811	-.1448	-.0151	.7801	
	107.00	.7779	-.1747	-.1303	-.0603	.7950	.7391	.1517	-.1260	-.0710	.7512	
	110.00	.7542	-.2905	-.1408	.0150	.8081	.7216	.2841	-.1441	.0202	.7753	
	115.00	.7175	-.5212	-.1625	.1692	.8706	.7072	.5606	-.1936	.2092	.8778	
	120.00	.6845	-.8330	-.1923	.3791	1.0093	.6486	.7860	-.1909	.3564	.9547	
	125.00	.6113	-.10424	-.1642	.5033	1.0986	.5699	.1025	-.1696	.5025	1.0475	
	130.00	.5153	-.12563	-.1205	.6312	1.2022	.4794	.1230	-.1302	.6287	1.1533	
	135.00	.4086	-.14029	-.0569	.7031	1.2809	.3785	.1377	-.0764	.7066	1.2418	
	140.00	.3104	-.14841	-.0006	.7162	1.3364	.2761	.14777	-.0135	.7384	1.3095	
	135.00	.3430	-.14173	-.0560	.7597	1.2447	.3490	.13931	-.0817	.7383	1.2319	
	140.00	.2389	-.14821	-.0006	.7697	1.2889	.2429	.14900	-.0173	.7717	1.2975	
	145.00	.1614	-.15392	.0211	.7507	1.3534	.1613	.15318	.0208	.7465	1.3473	
	150.00	.1118	-.15815	.0272	.6940	1.4255	.1096	.15821	.0292	.6962	1.4249	
	155.00	.0742	-.16252	.0301	.6196	1.5043	.0750	.16313	.0331	.6214	1.5102	
	160.00	.0432	-.16601	.0297	.5272	1.5748	.0472	.16688	.0342	.5264	1.5843	
	165.00	.0216	-.16997	.0224	.4190	1.6474	.0259	.17048	.0297	.4762	1.6534	
	169.00	.0057	-.17234	.0149	.3252	1.6928	.0138	.17191	.0237	.3145	1.6901	
3221	-5.00	-.0659	.6443	-.0046	-.0094	.6476	-.0759	.6515	-.0007	-.0188	.6556	
	-3.00	-.0308	.6468	-.0059	.0031	.6475	-.0279	.6501	-.0055	.0061	.6507	
	-1.00	.0041	.6473	-.0060	.0154	.6471	.0032	.6525	-.0056	.0146	.6523	
	.00	.0203	.6492	-.0065	.0203	.6492	.0193	.6518	-.0061	.0193	.6518	
	1.00	.0374	.6522	-.0066	.0260	.6528	.0353	.6514	-.0062	.0239	.6519	
	3.00	.0695	.6532	-.0073	.0352	.6559	.0658	.6517	-.0068	.0316	.6542	
	5.00	.1037	.6573	-.0081	.0460	.6638	.0980	.6524	-.0074	.0407	.6584	
	10.00	.1963	.6594	-.0104	.0771	.6933	.1827	.6601	-.0093	.0653	.6818	
	15.00	.2920	.6893	-.0135	.1037	.7414	.2796	.6751	-.0134	.0954	.7245	
	20.00	.4064	.7150	-.0185	.1374	.8109	.3899	.6951	-.0181	.1287	.7666	
	17.00	.3268	.7066	-.0087	.1059	.7712	.3114	.6722	-.0092	.1013	.7338	
	20.00	.3947	.7208	-.0096	.1244	.8123	.3780	.6848	-.0114	.1210	.7728	
	25.00	.5212	.7437	-.0158	.1581	.8943	.4955	.7048	-.0140	.1512	.8482	
	30.00	.6263	.7547	-.0157	.1650	.9668	.5966	.7223	-.0150	.1555	.9238	
	35.00	.7326	.7720	-.0159	.1573	1.0526	.6962	.7301	-.0151	.1515	.9974	
	40.00	.8171	.7702	-.0151	.1308	1.1152	.7783	.7200	-.0148	.1334	1.0518	
	45.00	.8832	.7465	-.0138	.0966	1.1524	.8455	.6968	-.0142	.1045	1.0899	
	50.00	.9235	.6981	-.0103	.0588	1.1561	.8834	.6488	-.0109	.0708	1.0937	
	45.00	.8550	.6820	-.0246	.1224	1.0868	.8242	.6642	-.0232	.1131	1.0525	
	50.00	.8938	.6360	-.0224	.0873	1.0935	.8679	.6250	-.0207	.0791	1.0665	
	55.00	.9077	.5898	-.0224	.0873	1.0818	.8935	.5767	-.0195	.0401	1.0627	
	60.00	.9235	.5382	-.0252	-.0043	1.0689	.9051	.5308	-.0215	-.0071	1.0492	
	65.00	.9352	.4889	-.0272	-.0179	1.0542	.9200	.4833	-.0234	-.0492	1.0381	
	70.00	.9370	.4413	-.0307	-.0942	1.0314	.9242	.4397	-.0265	-.0971	1.0189	
	75.00	.9320	.3917	-.0358	-.1372	1.0016	.9187	.3983	-.0303	-.1469	.9905	
	79.00	.9262	.3848	-.0403	-.1053	.9757	.9074	.3595	-.0347	-.1798	.9593	
	75.00	.8830	.3969	-.0333	-.1549	.9556	.8937	.3880	-.0327	-.1435	.9637	
	80.00	.8745	.3456	-.0382	-.1885	.9212	.8907	.3408	-.0366	-.1809	.9364	
	85.00	.8646	.2911	-.0413	-.2146	.8867	.8687	.2861	-.0391	-.2093	.8903	
	90.00	.8526	.2280	-.0426	-.2280	.8526	.8588	.2312	-.0408	-.2312	.8588	
	95.00	.8340	.1577	-.0421	-.2298	.8171	.8528	.1680	-.0406	-.2400	.8150	
	100.00	.8046	.0666	-.0412	-.2053	.7808	.7941	.0862	-.0394	-.2228	.7670	
	105.00	.7694	.0530	-.0405	-.1479	.7569	.7570	.0241	-.0397	-.1726	.7374	
	110.00	.7328	.1952	-.0377	-.072	.7554	.7067	.1719	-.0382	-.0802	.7229	
	107.00	.7612	.0882	-.0413	.1383	.7537	.7263	.0703	-.0383	-.1451	.7152	
	110.00	.7375	.1840	-.0396	.0793	.7559	.6888	.1649	-.0366	-.0806	.7037	
	115.00	.6803	.3588	-.0341	.0377	.7682	.6336	.3445	-.0314	.0444	.7198	
	120.00	.6146	.5630	-.0261	.1803	.8138	.5681	.5341	-.0247	.1784	.7591	
	125.00	.5434	.7654	-.0141	.3153	.8841	.4964	.7333	-.0149	.3160	.8272	
	130.00	.4607	.9645	.0018	.4427	.9729	.4149	.9375	.0006	.4515	.9204	
	135.00	.3797	-.1475	.0170	.5429	1.0799	.3378	-.1233	.0146	.5554	1.0332	
	140.00	.3059	-.12980	.0305	.6000	1.1909	.2657	-.12716	.0268	.6154	1.1436	
	135.00	.3172	-.1901	.0093	.6214	1.0616	.3005	-.1353	.0090	.5903	1.0153	
	140.00	.2336	-.13206	.0206	.6700	1.1618	.2298	-.12843	.0226	.6498	1.1313	
	145.00	.1684	-.14276	.0283	.6809	1.2660	.1658	-.14061	.0291	.6707	1.2469	
	150.00	.1234	-.14955	.0300	.6409	1.3568	.1232	-.14882	.0327	.6374	1.3504	
	155.00	.0905	-.15628	.0308	.5785	1.4546	.0915	-.15640	.0336	.5781	1.4562	
	160.00	.0593	-.16124	.0289	.4958	1.5355	.0643	-.16163	.0324	.4924	1.5408	
	165.00	.0307	-.16525	.0216	.3980	1.6041	.0391	-.16612	.0275	.3922	1.6147	
	169.00	.0149	-.16813	.0153	.3062	1.6532	.0246	-.16757	.0213	.2956	1.6496	

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_{\infty} = 3.5$											
Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
3222	45.00	.8529	.6812	-.0228	.1214	1.0848	.8255	.6723	-.0225	.1083	1.0591
	50.00	.8868	.6392	-.0211	.0803	1.0902	.8717	.6318	-.0201	.0763	1.0739
	55.00	.9070	.5886	-.0225	.0380	1.0806	.8849	.5738	-.0202	.0376	1.0540
	60.00	.9159	.5382	-.0239	-.0081	1.0623	.9010	.5293	-.0215	.0079	1.0450
	65.00	.9301	.4864	-.0251	-.0477	1.0486	.9162	.4794	-.0229	.0473	1.0350
	70.00	.9298	.4331	-.0270	.0890	1.0218	.9206	.4331	-.0240	.0921	1.0132
	75.00	.9317	.3841	-.0280	.1299	.9994	.9147	.3861	-.0260	.1362	.9834
	79.00	.9256	.3356	-.0293	.1528	.9726	.9080	.3441	-.0267	.1645	.9570
	75.00	.8863	.3809	-.0282	.1385	.9547	.8891	.3776	-.0264	.1346	.9565
	80.00	.8817	.3263	-.0284	.1682	.9250	.8843	.3237	-.0264	.1652	.9271
	85.00	.8772	.2640	-.0280	.1865	.8969	.8834	.2672	-.0262	.1912	.9035
	90.00	.8722	.1955	-.0283	.1955	.8722	.8726	.2046	-.0236	.2046	.8726
	95.00	.8629	.1167	-.0187	.1915	.8494	.8572	.1275	-.0192	.2017	.8428
	100.00	.8949	.0189	-.0093	.1661	.8332	.8360	.0345	-.0098	.1792	.8173
	105.00	.8305	-.0941	.0035	.1241	.8246	.8062	-.0763	.0023	.1350	.7984
	110.00	.8024	-.2128	.0145	.0744	.8268	.7712	-.1922	.0139	.0832	.7904
	107.00	.8302	-.1242	.0072	.1239	.8302	.7839	-.1124	.0075	.1217	.7825
	110.00	.8057	-.2003	.0147	.0874	.8256	.7583	-.1884	.0152	.0824	.7770
	115.00	.7505	-.3223	.0255	-.0251	.8164	.7025	-.3147	.0265	.0117	.7697
	120.00	.6887	-.4661	.0364	.0613	.8261	.6709	-.4525	.0378	.0764	.7727
	125.00	.6089	-.6000	.0472	.1422	.8429	.5573	-.5825	.0478	.1575	.7906
	130.00	.5182	-.7434	.0569	.2364	.8749	.4723	-.7237	.0569	.2508	.8270
	135.00	.4329	-.8927	.0679	.5251	.9373	.3882	-.8655	.0625	.3375	.8865
	140.00	.3585	-.1.0189	.0660	.3803	1.0109	.3155	-.9874	.0641	.3930	.9592
	135.00	.3522	-.9071	.0544	.3924	.8904	.3480	-.8659	.0590	.3662	.8584
	140.00	.2750	-.1.0465	.0548	.4620	.9785	.2772	-.0058	.0604	.4342	.9487
	145.00	.2145	-.1.1762	.0528	.4989	1.0865	.2159	-.1.1438	.0575	.4792	.1.0607
	150.00	.1688	-.1.2642	.0492	.4859	1.1792	.1762	-.1.2478	.0542	.4713	.1.1687
	155.00	.1307	-.1.3684	.0436	.4598	1.2954	.1361	-.1.3457	.0475	.4454	.1.2771
	160.00	.0921	-.1.4497	.0365	.4093	1.3938	.1002	-.1.4414	.0399	.3988	.1.3888
	165.00	.0557	-.1.5139	.0274	.3380	1.4767	.0667	-.1.5111	.0317	.3267	.1.4769
	169.00	.0324	-.1.5535	.0198	.2646	1.5312	.0464	-.1.5503	.0250	.2503	.1.5307
3223	45.00	.8576	.6873	-.0231	.1204	1.0924	.8205	.6661	-.0229	.1092	1.0512
	50.00	.8937	.6126	-.0212	.0822	1.0977	.8652	.6293	-.0194	.0740	1.0673
	55.00	.9099	.5924	-.0215	.0366	1.0851	.8962	.5823	-.0198	.0370	1.0681
	60.00	.9213	.5441	-.0232	-.0105	1.0700	.9007	.5312	-.0213	.0096	1.0456
	65.00	.9363	.4936	-.0256	.0517	1.0572	.9173	.4832	-.0231	.0502	1.0356
	70.00	.9385	.4397	-.0313	.0922	1.0323	.9209	.4371	-.0279	.0957	1.0149
	75.00	.9387	.3867	-.0417	.1305	1.0068	.9195	.3935	-.0350	.1421	.9900
	79.00	.9339	.3372	-.0506	.1528	.9810	.9157	.3464	-.0443	.1657	.9630
	107.00	.8168	-.1.7322	.1167	.0732	.8317	.7690	-.1527	.1124	.0788	.7800
	110.00	.7958	-.2822	-.1272	-.0070	.8443	.7498	-.2778	.1299	.0046	.7996
	115.00	.7582	.5123	-.1495	.1139	.9037	.7337	-.5670	.1823	.2038	.9046
	120.00	.7215	.8111	-.1836	.3589	1.0404	.6662	-.7706	.1786	.3343	.9822
	125.00	.6433	-.1.0429	.1555	.4853	1.1252	.5874	-.9963	.1583	.4792	1.0527
	130.00	.5422	-.1.2511	.1123	.6099	1.2195	.4961	-.1.2008	.1211	.6010	1.1519
	135.00	.4337	-.1.4084	.0539	.6892	1.3026	.3923	-.1.3572	.0680	.6823	1.2371
	140.00	.3276	-.4.6889	.0046	.7061	1.3512	.2874	-.1.4421	.0079	.7068	1.2894
	135.00	.3619	-.1.4133	.0485	.7435	1.2553	.3652	-.1.3889	.0739	.7239	1.2403
	140.00	.2563	-.1.4771	.0076	.7532	1.2962	.2525	-.1.4801	.0098	.7580	1.2961
	145.00	.1729	.5365	.0269	.7397	1.3578	.1726	-.1.5238	.0251	.7326	1.3472
	150.00	.1214	-.1.5771	.0320	.6835	1.4265	.1192	-.1.5761	.0329	.6849	1.4245
	155.00	.0825	.6236	.0345	.6114	1.5064	.0824	-.1.6269	.0363	.6129	1.5093
	160.00	.0502	.6557	.0331	.5198	1.5749	.0540	-.1.6613	.0364	.5175	1.5796
	165.00	.0244	.6951	.0251	.4151	1.6436	.0301	-.1.6964	.0319	.4100	1.6464
	169.00	.0110	.7161	.0170	.3166	1.6867	.0156	-.1.7131	.0239	.3116	1.6846
1321	-5.00	-.1.1009	.4723	-.0040	.0593	.4793	-.1.1021	.4615	-.0023	.-0.615	.4686
	-3.00	-.0.6062	.4746	-.0028	.0353	.4771	-.0.617	.4629	-.0022	-.0.374	.4655
	-1.00	-.0.175	.4785	-.0018	.0092	.4787	-.0.196	.4648	-.0011	-.0.115	.4650
	0.00	-.0.034	.4828	-.0018	.0034	.4828	-.0.009	.4691	-.0014	-.0.009	.4691
	1.00	0.0238	.4844	-.0013	.0153	.4847	0.0199	.4685	-.0011	0.017	.4687
	3.00	0.0617	.4865	-.0012	.0361	.4890	0.0601	.4690	-.0003	.0355	.4715
	5.00	0.1062	.4907	-.0009	.0630	.4981	0.1000	.4716	-.0003	.0585	.4785
	10.00	0.2167	.5033	-.0005	.1200	.5333	.2049	.4817	-.0002	.1202	.5103
	15.00	.3291	.5212	-.0019	.1830	.5886	.3198	.4982	-.0008	.1800	.5640
	20.00	.4595	.5462	-.0050	.2450	.6705	.4496	.5196	-.0004	.2448	.6421
	17.00	.3925	.5188	-.0014	.2236	.6109	.3764	.4884	-.0003	.2172	.5771
	20.00	.4745	.5380	-.0026	.2619	.6679	.4520	.5028	-.0004	.2527	.6271
	25.00	.6122	.5574	-.0056	.3192	.7639	.5794	.5250	-.0028	.3032	.7207
	30.00	.7289	.5704	-.0073	.3460	.8585	.7036	.5441	-.0060	.3372	.8230
	35.00	.8584	.5917	-.0097	.3638	.9771	.8208	.5578	-.0079	.3525	.9277
	40.00	.9509	.5999	-.0085	.3428	1.0707	.9182	.5675	-.0092	.3386	1.0249
	45.00	1.0487	.6061	-.0105	.3129	1.1701	1.0030	.5708	-.0107	.3056	1.1128
	50.00	1.1050	.6013	-.0058	.2497	1.2330	1.0596	.5648	-.0080	.2884	1.1747
	45.00	.9831	.5537	-.0228	.3037	1.0867	.9655	.5406	-.0196	.2990	1.0636
	50.00	1.0351	.5452	-.0196	.2478	1.1433	1.0234	.5368	-.0180	.2466	1.1290
	55.00	1.0670	.5279	-.0200	.1796	1.1768	1.0635	.5290	-.0169	.1767	1.1746
	60.00	1.1028	.5233	-.0224	.0982	1.2167	1.0949	.5197	-.0199	.0974	1.2081
	65.00	1.1175	.5081	-.0273	.0118	1.2275	1.1101	.5049	-.0240	.0116	1.2195
	70.00	1.1180	.4802	-.0341	-.0688	1.2148	1.1088	.4792	-.0305	-.0711	1.2058
	75.00	1.1136	.4452	-.0435	-.1418	1.1909	1.1001	.4473	-.0389	-.1474	1.1784
	79.00	1.0971	.4090	-.0505	-.1922	1.1549	1.0756	.4124	-.0453	-.1996	1.1345

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_\infty = 3.5$							$M_\infty = 4.2$						
Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D		
1321	75.00	1.0731	.4491	-.0382	-.1561	1.1527	1.0745	.4446	-.0374	-.1514	1.1530		
	80.00	1.0511	.4048	-.0460	-.2162	1.1054	1.0584	.4028	-.0452	-.2129	1.1122		
	85.00	1.0400	.3569	-.0538	-.2649	1.0671	1.0448	.3558	-.0525	-.2633	1.0718		
	90.00	1.0120	.2914	-.0581	-.2914	1.0120	1.0128	.2977	-.0571	-.2977	1.0128		
	95.00	.9900	.2201	-.0610	-.3056	.9670	.9771	.2308	-.0593	-.3151	.9533		
	100.00	.9443	.1277	-.0621	-.2898	.9078	.9301	.1449	-.0607	-.3042	.8908		
	105.00	.8967	.0041	-.0640	-.2361	.8650	.8690	.0264	-.0622	-.2504	.8326		
	110.00	.8424	-.1384	-.0621	-.1580	.8389	.8101	-.1175	-.0610	-.1667	.8014		
	107.00	.8665	-.0692	-.0705	-.1871	.8488	.8237	-.0360	-.0619	-.2064	.7982		
	110.00	.8263	-.1752	-.0688	-.1180	.8364	.7867	-.1416	-.0619	-.1360	.7877		
	115.00	.7600	-.3612	-.0595	-.0062	.8415	.7097	-.3280	-.0541	-.0026	.7818		
	120.00	.6825	-.5637	-.0530	.1469	.8730	.6380	-.5253	-.0490	.1359	.8152		
	125.00	.6010	-.7701	-.0400	.2861	.9340	.5517	-.7228	-.0341	.2757	.8665		
	130.00	.5086	-.9898	-.0230	.4313	1.0258	.4580	-.9464	-.0180	.4306	.9591		
	135.00	.4157	-1.1659	-.0025	.5305	1.1183	.3729	-1.1337	-.0022	.5380	1.0654		
	140.00	.3297	-1.3230	.0148	.5978	1.2254	.2861	-1.2914	.0136	.6109	1.1732		
	135.00	.3502	-1.1545	-.0061	.5588	1.0640	.3377	-1.1030	-.0045	.5411	1.0187		
	140.00	.2641	-1.3107	.0100	.6002	1.1738	.2544	-1.2707	.0094	.6219	1.1365		
	145.00	.1914	-1.4156	.0197	.6552	1.2694	.1833	-1.3974	.0200	.6513	1.2498		
	150.00	.1370	-1.4895	.0225	.6262	1.3584	.1343	-1.4907	.0248	.6291	1.3582		
	155.00	.1032	-1.5603	.0230	.5659	1.4577	.1047	-1.5639	.0275	.5660	1.4616		
	160.00	.0715	-1.6173	.0245	.4859	1.5443	.0765	-1.6203	.0283	.4823	1.5488		
	165.00	.0404	-1.6624	.0212	.3913	1.6163	.0505	-1.6664	.0261	.3825	1.6227		
	169.00	.0183	-1.6950	.0173	.3054	1.6674	.0330	-1.6739	.0211	.2870	1.6495		
	165.00	.0197	-1.6073	.0202	.3970	1.5576	.0297	-1.6382	.0208	.3953	1.5901		
	170.00	-.0032	-1.6377	.0143	.2876	1.6123	.0073	-1.6703	.0146	.2828	1.6462		
	175.00	-.0214	-1.6614	.0064	.1661	1.6532	-.0078	-1.6863	.0069	.1548	1.6792		
	177.00	-.0254	-1.6673	.0059	.1127	1.6637	-.0105	-1.6917	.0028	.0990	1.6889		
	179.00	-.0153	-1.6653	-.0003	.0444	1.6648	-.0075	-1.6935	-.0016	.0371	1.6931		
	180.00	-.0195	-1.6757	-.0016	.0195	1.6757	-.0123	-1.6932	-.0039	.0123	1.6932		
	181.00	-.0241	-1.6786	-.0058	-.0052	1.6787	-.0154	-1.6924	-.0061	-.0141	1.6924		
	183.00	-.0183	-1.6831	-.0081	-.0698	1.6818	-.0125	-1.6937	-.0100	-.0761	1.6921		
	185.00	-.0210	-1.6857	-.0114	-.1260	1.6811	-.0153	-1.6904	-.0139	-.1321	1.6853		
1322	45.00	.9809	.5568	-.0210	.2999	1.0873	.9575	.5394	-.0185	.2957	1.0505		
	50.00	1.0345	.5497	-.0186	.2439	1.1458	1.0182	.5378	-.0167	.2425	1.1257		
	55.00	1.0718	.5353	-.0189	.1763	1.1850	1.0552	.5265	-.0160	.1757	1.1688		
	60.00	1.1034	.5253	-.0220	.0968	1.2183	1.0891	.5168	-.0187	.0970	1.2016		
	65.00	1.1129	.5044	-.0254	.0132	1.2218	1.1018	.5006	-.0222	.0119	1.2102		
	70.00	1.1147	.4732	-.0303	-.0365	1.2093	1.1056	.4709	-.0264	-.0646	1.2000		
	75.00	1.1087	.4377	-.0360	-.1358	1.1842	1.0963	.4368	-.0327	-.1382	1.1720		
	79.00	1.1000	.3971	-.0405	-.1799	1.1556	1.0848	.3985	-.0374	-.1842	1.1409		
	75.00	1.0608	.4194	-.0348	-.1305	1.1332	1.0789	.4339	-.0319	-.1399	1.1544		
	80.00	1.0501	.3753	-.0394	-.1873	1.0993	1.0664	.3847	-.0370	-.1937	1.1170		
	85.00	1.0429	.3183	-.0426	-.2262	1.0666	1.0524	.3304	-.0403	-.2374	1.0772		
	90.00	1.0301	.2501	-.0431	-.2501	1.0301	1.0303	.2644	-.0423	-.2644	1.0303		
	95.00	1.0073	.1685	-.0412	-.2557	.9888	1.0038	.1863	-.0410	-.2731	.9838		
	100.00	.9834	.0684	-.0398	-.2384	.9564	.9486	.0896	-.0352	-.2564	.9383		
	105.00	.9497	-.0488	-.0255	-.1987	.9299	.9287	-.0275	-.0258	-.2138	.9042		
	110.00	.9045	-.1698	-.0162	-.1498	.9080	.8690	-.1564	-.0152	-.1592	.8701		
	107.00	.9283	-.0906	-.0201	-.1848	.9142	.8748	-.0755	-.0188	-.1836	.8587		
	110.00	.8973	-.1699	-.0130	-.1472	.9013	.8425	-.1558	-.0102	-.1418	.8450		
	115.00	.8334	-.2991	-.0048	-.0811	.8817	.7723	-.2967	-.0009	-.0575	.8253		
	120.00	.7505	-.4444	-.0077	-.096	.8721	.6918	-.4332	-.0112	-.0293	.8157		
	125.00	.6643	-.5930	-.0210	-.1048	.8843	.6072	-.5732	-.0233	.1212	.8262		
	130.00	.5691	-.7373	-.0319	.1990	.9099	.5180	-.7052	-.0364	.2072	.8501		
	135.00	.4750	-.8867	-.0418	.2911	.9629	.4242	-.8593	-.0436	.3076	.9076		
	140.00	.3855	-.1.0330	-.0466	.3687	1.0391	.3373	-.1.0008	-.0460	.3849	.9835		
	135.00	.3989	-.8876	-.0384	.3455	.9097	.3862	-.8353	-.0415	.3175	.8637		
	140.00	.3128	-.1.0299	-.0398	.4224	.9900	.3039	-.9801	-.0447	.3972	.9661		
	145.00	.2423	-.1.1592	-.0400	.4664	1.0886	.2407	-.1.1293	-.0441	.4505	1.0632		
	150.00	.1914	-.2.1782	-.0379	.4733	1.2026	.1892	-.1.2365	-.0407	.4544	1.1654		
	155.00	.1531	-.3.586	-.0356	.4354	1.2960	.1520	-.3.3883	-.0378	.4278	1.2771		
	160.00	.1122	-.14.5388	-.0283	.3918	1.4045	.1167	-.1.4341	-.0326	.3808	1.3875		
	165.00	.0748	-.1.5192	-.0244	.3209	1.4868	.0811	-.1.5027	-.0261	.3106	1.4725		
	169.00	.0483	-.1.5616	-.0187	.2506	1.5421	.0555	-.1.5411	-.0204	.2396	1.5234		
	165.00	.0685	-.1.4600	-.0268	.3117	1.4280	.0707	-.1.4775	-.0278	.3141	1.4455		
	170.00	.0385	-.1.5073	-.0198	.2238	1.4911	.0405	-.1.5276	-.0200	.2254	1.5114		
	175.00	.0150	-.1.5381	-.0124	.1192	1.5336	.0190	-.1.5566	-.0120	.1168	1.5524		
	177.00	.0204	-.1.5477	-.0069	.0606	1.5467	.0180	-.1.5646	-.0058	.0639	1.5434		
	179.00	.0106	-.1.5553	-.0037	.0165	1.5553	.0078	-.1.5677	-.0022	.0196	1.5676		
	180.00	.0053	-.1.5569	-.0024	-.0053	1.5569	.0033	-.1.5691	-.0005	-.0033	1.5691		
	181.00	.0000	-.1.5601	-.0006	-.0272	1.5599	-.0018	-.1.5694	-.0015	-.0256	1.5692		
	183.00	-.0098	-.1.5619	-.0029	-.0719	1.5603	-.0120	-.1.5693	-.0051	-.0701	1.5678		
	185.00	-.0221	-.1.5627	-.0066	-.1142	1.5587	-.0224	-.1.5662	-.0085	-.1.1442	1.5622		
1323	45.00	.9845	.5571	-.0224	.3022	1.0900	.9698	.5482	-.0189	.2982	1.0734		
	50.00	1.0465	.5552	-.0191	.2474	1.1586	1.0235	.5423	-.0158	.2425	1.1326		
	55.00	1.0787	.5352	-.0188	.1803	1.1906	1.0611	.5309	-.0160	.1737	1.1737		
	60.00	1.1000	.5262	-.0208	.0943	1.2157	1.0790	.5230	-.0183	.0866	1.1959		
	65.00	1.1210	.5131	-.0269	.0088	1.2328	1.1049	.5043	-.0235	.0099	1.2145		
	70.00	1.1215	.4807	-.0349	-.0681	1.2183	1.1021	.4764	-.0317	-.0694	1.2051		
	75.00	1.1246	.4403	-.0492	-.1342	1.2003	1.1051	.4421	-.0429	-.1410	1.1618		
	79.00	1.1170	.3966	-.0026	-.1762	1.1722	1.0917	.4039	-.0546	-.1882	1.1487		

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
1323	75.00	1.0767	.4353	-.0428	-.1418	1.1527	1.0842	.4380	-.0434	-.1425	1.1607
	80.00	1.0698	.3866	-.0580	-.1049	1.1206	1.0725	.3907	-.0563	-.1986	1.1240
	85.00	1.0569	.3286	-.0728	-.2353	1.0815	1.0550	.3367	-.0694	-.2434	1.0803
	90.00	1.0403	.2649	-.0843	-.2649	1.0403	1.0296	.2770	-.0799	-.2770	1.0296
	95.00	1.0129	.1880	-.0951	-.2756	.9927	.9944	.2067	-.0892	-.2926	.9726
	100.00	.9794	.0873	-.1104	-.2561	.9493	.9539	.1100	-.1041	-.2739	.9203
	105.00	.9418	-.0571	-.1321	-.1886	.9245	.9128	-.0250	-.1274	-.2122	.8882
	110.00	.9072	-.2334	-.1529	-.0910	.9323	.8803	-.2130	-.1567	-.1009	.9001
	107.00	.9213	-.1294	-.1471	-.1457	.9188	.8688	-.1102	-.1411	-.1486	.8630
	110.00	.8921	-.2572	-.1593	-.0634	.9263	.8415	-.2399	-.1592	-.0624	.8728
	115.00	.8444	-.4818	-.1820	-.0798	.9689	.8139	-.5242	-.2134	.1311	.9591
	120.00	.7923	-.7945	-.2133	.2919	1.0834	.7400	-.7496	.2105	.2792	1.0157
	125.00	.6972	-.10268	-.1822	.4412	1.1601	.6884	-.9888	.1885	.4381	1.0983
	130.00	.5907	-.12343	-.1352	.5658	1.2459	.5621	-.1933	.1435	.5656	1.1823
	135.00	.4720	-.13896	-.0695	.6488	1.3164	.4296	-.13506	-.0857	.6512	1.2588
	140.00	.3533	-.14487	-.0033	.6735	1.3522	.3093	-.14455	-.0137	.6923	1.3061
	135.00	.4040	-.13894	-.0635	.6968	1.2682	.4040	-.13484	-.0977	.6678	1.2392
	140.00	.2896	-.14577	-.0029	.7152	1.3029	.2864	-.14456	-.0222	.7098	1.2015
	145.00	.1983	-.15290	.0192	.7146	1.3662	.1950	-.15159	.0177	.7098	1.3535
	150.00	.1391	-.15765	.0275	.6678	1.4349	.1307	-.15751	.0274	.6744	1.4295
	155.00	.1029	-.16237	.0321	.5929	1.5151	.0967	-.16265	.0321	.5998	1.5150
	160.00	.0675	-.16683	.0323	.5072	1.5908	.0851	-.16707	.0322	.5102	1.5922
	165.00	.0401	-.16960	.0257	.4003	1.6486	.0392	-.16979	.0300	.4016	1.6502
	169.00	.0218	-.17360	.0195	.3098	1.7083	.0223	-.17169	.0238	.3057	1.6897
	165.00	.0217	-.16605	.0263	.4036	1.5902	.0296	-.16760	.0269	.4052	1.6266
	170.00	-.0005	-.16669	.0184	.2900	1.6415	.0101	-.17000	.0192	.2853	1.6760
	175.00	-.0161	-.16839	.0097	.1628	1.6761	-.0034	-.17172	.0092	.1531	1.7104
	177.00	-.0189	-.16697	.0063	.1073	1.6864	-.0057	-.17204	.0050	.0957	1.7177
	179.00	-.0172	-.16954	.0034	.0648	1.6948	-.0043	-.17242	.0008	.0344	1.7238
	180.00	-.0152	-.16980	.0017	.0152	1.5980	-.0008	-.17226	-.0017	.0008	1.7226
	181.00	-.0113	-.17029	-.0012	.0184	1.7028	-.0048	-.17237	-.0045	-.0253	1.7235
	183.00	-.0052	-.17045	-.0049	.0840	1.7025	-.0022	-.17236	-.0093	-.0924	1.7211
	185.00	-.0053	-.17089	-.0080	.1436	1.7029	-.0006	-.17222	-.0128	-.1507	1.7156
2321	-5.00	-.1042	.4673	-.0014	-.0631	1.4746	-.1023	.4556	-.0021	-.0622	.4628
	-3.00	-.0635	.4695	-.0006	.0388	1.4722	-.0578	.4575	-.0013	-.0338	.5599
	-1.00	-.0202	.4730	-.0001	.0119	1.4733	-.0210	.4587	-.0006	-.0130	.4590
	.00	-.0006	.4765	.0005	-.0006	1.4765	-.0004	.4602	-.0004	.0004	.4602
	1.00	.0184	.4785	.0008	.0101	1.4787	.0178	.4597	-.0003	.0098	.4599
	3.00	.0556	.4818	.0012	.0303	1.4840	.0555	.4614	.0006	.0313	.4637
	5.00	.0963	.4860	.0016	.0535	1.4926	.0952	.4648	.0008	.0543	.4713
	10.00	.2075	.5010	.0015	.1173	1.5294	.2002	.4778	.0008	.1142	.5053
	15.00	.3298	.5277	.0006	.1820	1.5951	.3188	.5025	-.0007	.1778	.5679
	20.00	.4618	.5613	-.0001	.2419	1.6853	.4490	.5314	-.0017	.2402	.6530
	17.00	.3923	.5425	.0082	.2166	1.6335	.3822	.5065	.0045	.2174	.5961
	20.00	.4781	.5543	.0052	.2597	1.6844	.4601	.5230	.0042	.2535	.6489
	25.00	.6214	.5870	.0064	.3151	1.7946	.5916	.5491	.0054	.3041	.7477
	30.00	.7502	.6090	.0073	.3452	1.9025	.7043	.5741	.0142	.3228	.8494
	45.00	.8652	.6322	.0104	.3512	1.0068	.8410	.5868	.0067	.3523	.9631
	40.00	.9743	.6302	.0104	.3413	1.1091	.9358	.5959	.0110	.3359	1.0579
	45.00	1.0656	.6360	.0145	.3038	1.2032	1.0187	.5943	.0111	.3001	1.1405
	50.00	1.1226	.6169	.0187	.2475	1.2578	1.0740	.5807	.0150	.2456	1.1960
	45.00	1.0661	.5811	-.0087	.3005	1.1223	.9766	.5601	-.0072	.2945	1.0867
	50.00	1.0659	.5598	-.0057	.2563	1.1763	1.0421	.5475	-.0032	.2505	1.1502
	55.00	1.1015	.5328	-.0038	.1954	1.2079	1.0864	.5283	-.0006	.1903	1.1929
	60.00	1.1344	.5220	-.0043	.1151	1.2434	1.1160	.5156	-.0010	.1115	1.2243
	65.00	1.1455	.4980	-.0095	.0328	1.2487	1.1337	.4956	-.0044	.0299	1.2370
	70.00	1.1491	.4704	-.0150	.0490	1.2407	1.1369	.4715	-.0107	-.0543	1.2296
	75.00	1.1484	.4370	-.0235	.1249	1.2224	1.1307	.4395	-.0183	.1319	1.2060
	79.00	1.1377	.4002	-.0312	.1757	1.1932	1.1210	.4078	-.0256	-.1864	1.1782
	75.00	1.0974	.4341	-.0186	.1353	1.1724	1.1153	.4413	-.0170	-.1376	1.1915
	80.00	1.0894	.3952	-.0262	.2000	1.1415	1.1035	.3996	-.0245	-.2019	1.1561
	85.00	1.0746	.4541	-.0327	.2501	1.1006	1.0860	.3522	-.0309	.2562	1.1126
	90.00	1.0567	.2856	-.0368	.2856	1.0567	1.0587	.2968	-.0353	.2968	1.0587
	95.00	1.0381	.2161	-.0388	.3058	1.0154	1.0231	.2302	-.0373	.3185	.9991
	100.00	.9932	.1268	-.0399	.2974	.9561	.9775	.1501	-.0388	.3175	.9366
	105.00	.9384	.0054	-.0407	.2181	.9050	.9157	.0334	-.0410	.2493	.8759
	110.00	.8868	.1384	-.0411	.1732	.8806	.8523	-.1088	-.0412	.1893	.0381
	107.00	.9158	.0506	-.0461	.2194	.8906	.8553	-.0313	-.0405	.2202	.6271
	110.00	.8756	.1484	-.0445	.1601	.8736	.8170	-.1333	-.0400	.1541	.8133
	115.00	.8053	.3313	-.0402	.0400	.8699	.7417	-.3133	-.0368	.0296	.8046
	120.00	.7206	.5388	-.0346	.1063	.8935	.6621	-.5060	-.0311	.1071	.8264
	125.00	.6385	.7486	-.0232	.2470	.9524	.5736	-.7151	-.0205	.2568	.8801
	130.00	.5422	.9647	-.0075	.3905	1.0354	.4804	-.9200	-.0053	.3960	.9594
	135.00	.4455	-1.1444	.0118	.4942	1.1242	.3930	-1.1132	.0107	.5093	1.0651
	140.00	.3511	-1.2949	.0262	.5633	1.2176	.3025	-1.2707	.0242	.5851	1.1678
2322	45.00	1.0015	.5787	-.0078	.2990	1.1174	.9812	.5632	-.0072	.2956	1.0920
	50.00	1.0600	.5563	-.0054	.2553	1.1696	1.0472	.5509	-.0033	.2511	1.1563
	55.00	1.0967	.5352	-.0035	.1906	1.2054	1.0909	.5338	-.0004	.1894	1.1998
	60.00	1.1351	.5233	-.0043	.1144	1.2447	1.1211	.5157	-.0014	.1140	1.2288
	65.00	1.1448	.4052	-.0073	.0350	1.2468	1.1506	.4911	-.0046	.0327	1.2322
	70.00	1.1520	.4669	-.0122	.0447	1.2422	1.1363	.4637	-.0087	.0471	1.2264
	75.00	1.1416	.4270	-.0170	.1170	1.2132	1.1319	.4293	-.0141	.1217	1.2044
	79.00	1.1393	.3872	-.0220	.1627	1.1923	1.1196	.3928	-.0177	.1720	1.1740



TABLE I-- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α_s deg	$M_\infty = 3.5$						$M_\infty = 4.2$					
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D		
2322	75.00	1.0997	.4281	-.0115	-.1289	1.1730	1.1057	.4268	-.0121	-.1261	1.1785		
	80.00	1.0931	.3817	-.0159	-.1861	1.1428	1.0981	.3816	-.0162	-.1851	1.1477		
	85.00	1.0873	.3273	-.0184	-.2313	1.1117	1.0872	.3289	-.0189	-.2329	1.1118		
	90.00	1.0817	.2619	-.0181	-.2619	1.0817	1.0765	.2700	-.0198	-.2700	1.0765		
	95.00	1.0619	.1841	-.0157	-.2760	1.0419	1.0412	.1921	-.0178	-.2822	1.0205		
	100.00	1.0383	.0786	-.0091	-.2577	1.0089	1.0142	.0920	-.0113	-.2667	.9828		
	105.00	1.0012	-.0297	-.0008	-.2304	.9748	.9615	-.0141	-.0031	-.2353	.9323		
	110.00	.9478	-.1541	.0049	-.1794	.9433	.9154	-.1398	.0057	-.1817	.9080		
	107.00	.9762	-.0765	-.0003	-.2122	.9559	.9199	-.0636	.0011	-.2082	.8983		
	110.00	.9372	-.1543	.0037	-.1755	.9335	.8837	-.1470	.0053	-.1641	.8807		
	115.00	.8675	-.2882	.0139	-.1054	.9080	.8071	-.2866	.0150	-.0814	.8526		
	120.00	.7861	-.4290	.0231	-.0216	.8953	.7229	-.4260	.0261	-.0074	.8390		
	125.00	.6911	-.5759	.0347	-.0753	.8964	.6343	-.5634	.0368	-.0977	.8428		
	130.00	.5882	-.7247	.0441	-.1770	.9164	.5358	-.7090	.0458	-.1987	.8661		
	135.00	.4904	-.8724	.0523	-.2701	.9637	.4402	-.8499	.0533	-.2997	.9123		
	140.00	.3934	-1.0166	.0559	.3521	1.0317	.3506	-.9902	.0544	.3679	.9839		
2323	45.00	1.0058	.5884	-.0087	.2951	1.1273	.9795	.5635	-.0087	.2941	1.0911		
	50.00	1.0611	.5422	-.0066	.2514	1.1742	1.0422	.5515	-.0043	.2474	1.1529		
	55.00	1.0989	.5397	-.0048	.1882	1.2098	1.0835	.5324	-.0024	.1854	1.1929		
	60.00	1.1273	.5239	-.0056	.1100	1.2383	1.1173	.5215	-.0015	.1071	1.2284		
	65.00	1.1445	.5021	-.0096	.0286	1.2495	1.1311	.4983	-.0062	.0264	1.2357		
	70.00	1.1689	.4709	-.0182	.0496	1.2407	1.1370	.4693	-.0140	.0521	1.2289		
	75.00	1.1477	.4313	-.0313	.1196	1.2202	1.1355	.4350	-.0246	.1263	1.2094		
	79.00	1.1478	.3911	-.0439	.1649	1.2013	1.1266	.3989	-.0355	.1766	1.1820		
	75.00	1.1178	.4324	-.0234	.1284	1.1916	1.1138	.4313	-.0225	.1283	1.1875		
	80.00	1.1144	.3856	-.0375	.1862	1.1645	1.1091	.3868	-.0350	.1883	1.1595		
	85.00	1.0970	.3278	-.0506	.2310	1.1211	1.0949	.3338	-.0476	.2371	1.1198		
	90.00	1.0810	.2652	-.0620	.2652	1.0810	1.0798	.2795	-.0580	.2795	1.0792		
	95.00	1.0564	.1915	-.0721	.2829	1.0357	1.0383	.2109	-.0665	.3006	1.0160		
	100.00	1.0258	.0936	-.0866	.2703	.9939	1.0035	.1133	-.0821	.2859	.9686		
	105.00	.9937	-.0537	-.1104	.2053	.9737	.9637	-.0113	-.1047	.2385	.9338		
	110.00	.9518	-.2203	-.1307	.1185	.9697	.9198	-.1973	.1340	.1292	.9318		
	107.00	.9624	-.1273	-.1256	.1597	.9575	.9122	-.1087	.1201	.1628	.9041		
	110.00	.9294	-.2482	-.1383	.0865	.9575	.8883	-.2338	.1390	.0854	.9128		
	115.00	.8811	-.4813	-.1649	.0588	1.0019	.8491	.5237	-.1959	.1158	.9908		
	120.00	.8288	-.7952	-.1984	.2743	1.1154	.7719	.7492	-.1937	.2628	1.0431		
	125.00	.7300	-1.0218	-.1690	.4183	1.1841	.6751	.9768	-.1736	.4129	1.1133		
	130.00	.6195	-1.2312	-.1237	.5449	1.2660	.5663	.1928	-.1325	.5497	1.2005		
	135.00	.4940	-1.3853	-.0599	.6303	1.3289	.4520	.13431	-.0753	.6301	1.2693		
	140.00	.3716	-1.1738	.0049	.6626	1.3679	.3290	-.14541	-.0083	.6827	1.3254		
3321	-5.00	-.0991	.4684	-.0030	-.0579	.4752	-.1011	.4645	-.0002	-.0602	.4715		
	-3.00	-.0557	.4716	-.0026	.0309	.4739	-.0590	.4649	-.0003	-.0346	.4674		
	-1.00	-.0183	.4755	-.0012	.0100	.4757	-.0202	.4670	-.0007	-.0121	.4673		
	.00	.0027	.4754	-.0010	.0027	.4754	-.0043	.4672	-.0007	-.0043	.4672		
	1.00	.0214	.4793	-.0007	.0130	.4796	.0174	.4671	-.0000	-.0092	.4673		
	3.00	.0588	.4821	-.0002	.0335	.4848	.0539	.4684	-.0005	-.0293	.4706		
	5.00	.0996	.4874	-.0002	.0567	.4942	.0928	.4702	-.0008	-.0514	.4765		
	10.00	.2117	.5064	-.0003	.1206	.5355	.1981	.4879	-.0001	.1104	.5149		
	15.00	.3321	.5380	-.0011	.1816	.6057	.3216	.5173	-.0021	.1767	.5829		
	20.00	.4670	.5744	-.0002	.2423	.6995	.4570	.5512	-.0018	.2409	.6743		
	17.00	.3981	.5505	-.0019	.2198	.6428	.3822	.5202	-.0012	.2134	.6092		
	20.00	.4823	.5720	-.0035	.2576	.7025	.4615	.5397	-.0024	.2491	.6650		
	25.00	.6193	.5955	-.0047	.3096	.8014	.5925	.5699	-.0047	.2961	.7669		
	30.00	.7463	.6206	-.0087	.3360	.9107	.7088	.5955	-.0133	.3160	.8701		
	35.00	.8755	.6415	-.0100	.3492	1.0277	.8412	.6074	-.0077	.3407	.9801		
	40.00	.9836	.6505	-.0117	.3354	1.1305	.9378	.6159	-.0111	.3225	.10746		
	45.00	1.0613	.6497	-.0158	.2911	1.2099	1.0214	.6132	-.0137	.2886	.1558		
	50.00	1.1225	.6331	-.0199	.2365	1.2669	1.0795	.5942	-.0175	.2387	.2088		
	45.00	1.0129	.5960	-.0022	.2948	1.1376	.9914	.5839	-.0009	.2881	.1139		
	50.00	1.0701	.5708	-.0011	.2505	1.1866	1.0528	.5681	-.0047	.2415	.1717		
	55.00	1.1120	.5395	-.0048	.1959	1.2203	1.1016	.5404	-.0091	.1892	.2124		
	60.00	1.1629	.5174	-.0049	.1234	1.2485	1.1337	.5185	-.0092	.1179	.2411		
	65.00	1.1567	.4955	-.0009	.0397	1.2577	1.1536	.4960	-.0052	.0380	.12551		
	70.00	1.1617	.4630	-.0044	.0378	1.2500	1.1592	.4705	-.0004	-.0456	.12502		
	75.00	1.1603	.4261	-.0125	.1113	1.2311	1.1557	.4372	-.0068	-.1232	.12295		
	79.00	1.1575	.3959	-.0193	.1677	1.2117	1.1356	.4052	-.0126	.1811	.1920		
	75.00	1.1216	.4412	-.0071	.1359	1.1976	1.1522	.4366	-.0066	.1287	.12066		
	80.00	1.1066	.3994	-.0140	.2011	1.1592	1.1182	.3948	-.0131	.1946	.1698		
	85.00	1.1043	.3533	-.0202	.2557	1.1309	1.1028	.3469	-.0187	.2495	.1288		
	90.00	1.0784	.2914	-.0233	.2914	1.0784	1.0829	.2968	-.0229	.2968	.10829		
	95.00	1.0573	.2257	-.0249	.3170	1.0336	1.0432	.2337	-.0238	.3237	.10188		
	100.00	1.0188	.1369	-.0254	.3117	.9795	.9977	.1551	-.0251	.3260	.9556		
	105.00	.9638	.0125	-.0279	.2616	.9278	.9344	.0379	-.0277	.2784	.8928		
	110.00	.9126	-.1231	-.0292	.1964	.8997	.8701	-.1045	-.0297	.1994	.8533		
	107.00	.9363	-.0411	-.0376	.2344	.9074	.8906	-.0229	-.0288	.2385	.8584		
	110.00	.8975	-.1411	-.0331	.1744	.8917	.8459	-.1251	-.0293	.1717	.8377		
	115.00	.8295	-.3213	-.0297	.0594	.8876	.7697	-.3033	-.0274	.0504	.8258		
	120.00	.7424	-.5315	-.0249	.0891	.9087	.6886	-.4994	-.0229	.0882	.8660		
	125.00	.6567	-.7301	-.0145	.2214	.9567	.5970	-.7033	-.0120	.2337	.8924		
	130.00	.5599	-.9460	.0003	.3648	1.0370	.5031	-.9139	.0003	.3767	.9728		
	135.00	.4589	-.1408	.0159	.4822	1.1312	.4109	-.1059	.0146	.4914	1.0726		
	140.00	.3654	-.3016	.0304	.5568	1.2320	.3150	-.12709	.0277	.5756	1.1761		

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_\infty = 3.5$										$M_\infty = 4.2$									
Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m
3322	45.00	1.0106	.5974	-.0011	.2922	1.1370	.9875	.5823	.0013	.2865	1.1101	3322	3322	3322	3322	3322	3322	3322	3322
	50.00	1.0668	.5739	.0034	.2461	1.1861	1.0475	.5664	.0051	.2394	1.1665								
	55.00	1.1098	.5442	.0054	.1908	1.2212	1.0970	.5388	.0095	.1878	1.2076								
	60.00	1.1374	.5199	.0054	.1185	1.2450	1.1206	.5105	.0088	.1182	1.2258								
	65.00	1.1539	.4915	.0019	.0422	1.2535	1.1400	.4854	.0058	.0419	1.2383								
	70.00	1.1616	.4590	-.0025	.0340	1.2485	1.1452	.4564	.0022	.0372	1.2322								
	75.00	1.1607	.4208	-.0058	.1059	1.2301	1.1486	.4218	-.0025	.1101	1.2187								
	79.00	1.1597	.3829	-.0095	.1546	1.2115	1.1509	.3921	-.0052	.1653	1.2046								
	75.00	1.1135	.4176	-.0029	.1152	1.1837	1.1188	.4241	-.0011	.1201	1.1905								
	80.00	1.1116	.3738	-.0063	.1751	1.1596	1.1241	.3825	-.0003	.1815	1.1734								
	85.00	1.1080	.3188	-.0084	.2210	1.1316	1.1064	.3273	-.0066	.2297	1.1307								
	90.00	1.0984	.2521	-.0076	.2521	1.0984	1.0982	.2690	-.0071	.2690	1.0982								
	95.00	1.0726	.1716	-.0041	.2644	1.0535	1.0629	.1914	-.0042	.2833	1.0422								
	100.00	1.0497	.0728	.0026	.2540	1.0212	1.0356	.0933	.0023	.2717	1.0037								
	105.00	1.0178	-.0359	.0102	.2287	.9924	.9900	-.0150	.0089	.2417	.9602								
	110.00	.9658	.1528	.0164	.1867	.9599	.9337	-.1443	.0166	.1837	.9268								
	107.00	1.0011	-.0703	.0121	.2255	.9780	.9359	-.0601	.0137	.2161	.9126								
	110.00	.9612	.1499	.0159	.1878	.9545	.9027	-.1409	.0165	.1763	.8965								
	115.00	.8908	.2818	.0234	.1211	.9264	.8266	.2795	.0250	.0960	.8673								
	120.00	.8067	-.4247	.0320	-.0356	.9110	.7395	-.4187	.0345	-.0072	.8498								
	125.00	.7153	-.5746	.0424	.0604	.9155	.6498	.5522	.0441	.0796	.8400								
	130.00	.6100	.7149	.0506	.1555	.9268	.5561	-.7023	.0521	.1805	.8774								
	135.00	.5032	.8659	.0567	.2564	.9680	.4526	-.8393	.0589	.2767	.9167								
	140.00	.4050	-.1014	-.0587	.3417	1.0371	.3605	-.9873	.0584	.3584	.9880								
3323	45.00	1.0159	.6012	-.0023	.2933	1.1435	.9904	.5865	-.0003	.2856	1.1150	3323	3323	3323	3323	3323	3323	3323	3323
	50.00	1.0729	.5788	.0012	.2462	1.1939	1.0509	.5678	.0037	.2405	1.1700								
	55.00	1.1158	.5465	.0043	.1923	1.2275	1.0994	.5417	.0085	.1869	1.2113								
	60.00	1.1371	.5187	.0048	.1194	1.2442	1.1318	.5197	.0091	.1158	1.2401								
	65.00	1.1622	.4993	.0006	.0387	1.2643	1.1534	.4941	.0050	.0396	1.2541								
	70.00	1.1646	.4653	-.0065	.0389	1.2535	1.1577	.4657	-.0019	.0416	1.2472								
	75.00	1.1687	.4220	-.0197	.1059	1.2383	1.1597	.4270	-.0134	.1123	1.2307								
	79.00	1.1708	.3854	-.0308	.1549	1.2228	1.1445	.3911	-.0231	.1655	1.1981								
	75.00	1.1274	.4253	-.0129	.1190	1.1991	1.1283	.4273	-.0117	.1207	1.2005								
	80.00	1.1251	.3787	-.0262	.1775	1.1738	1.1245	.3804	-.0240	.1793	1.1735								
	85.00	1.1212	.3249	-.0390	.2260	1.1452	1.1214	.3316	-.0361	.2326	1.1460								
	90.00	1.1053	.2610	-.0501	.2610	1.1054	1.0977	.2743	-.0457	.2743	1.0977								
	95.00	1.0756	.1870	-.0598	.2800	1.0552	1.0689	.2099	-.0538	.3021	1.0445								
	100.00	1.0512	.0858	-.0752	.2670	1.0203	1.0174	.1118	-.0688	.2868	.9825								
	105.00	1.0057	-.0521	.0967	.2100	.9849	.9829	-.0122	.0923	-.2426	.9526								
	110.00	.9709	-.2215	.1195	.1240	.9881	.9883	-.1970	.1227	-.1358	.9491								
	107.00	.9863	.1149	.1119	.1785	.9768	.9391	-.0980	.1073	-.1809	.9268								
	110.00	.9521	-.2438	.1260	.0965	.9781	.9087	-.2283	.1274	-.0963	.9320								
	115.00	.8982	-.4759	.1533	.0517	1.0151	.8738	.5192	-.1865	.1013	1.0113								
	120.00	.8442	-.7911	.1899	.2656	1.1282	.7959	.7322	-.1866	.2361	1.0554								
	125.00	.7474	-.1012	.1626	.4029	1.1945	.6984	.9664	-.1662	.3910	1.1264								
	130.00	.6332	-.1230	.1185	.5360	1.2764	.5836	.1904	-.1271	.5368	1.2123								
	135.00	.5133	-.1383	.0584	.6152	1.3412	.4591	-.13517	-.0713	.6312	1.2804								
	140.00	.3865	-.1472	.0069	.6503	1.3763	.3043	-.14453	-.0057	.6683	1.3259								
1131	-5.00	-.0737	.8232	.0120	-.0016	.8265	-.0740	.8210	.0122	-.0021	.8243	1131	1131	1131	1131	1131	1131	1131	1131
	-3.00	-.0431	.8273	.0066	.0003	.8285	-.0402	.8238	.0060	.0030	.8248								
	-1.00	-.0115	.8329	.0012	.0030	.8330	-.0094	.8262	.0007	.0050	.8263								
	.00	.0032	.8354	-.0013	.0032	.8356	.0060	.8259	-.0022	.0060	.8259								
	1.00	.0193	.8365	-.0044	.0047	.8367	.0209	.8251	-.0048	.0065	.8254								
	3.00	.0489	.8356	-.0095	.0051	.8371	.0499	.8240	-.0099	.0067	.8255								
	5.00	.0790	.8445	-.0147	.0060	.8382	.0809	.8230	-.0105	.0089	.8270								
	10.00	.1571	.8389	-.0274	.0090	.8535	.1559	.8210	-.0275	.0109	.8356								
	15.00	.2284	.8349	-.0398	.0045	.8685	.2304	.8148	-.0403	.0117	.8466								
	20.00	.3024	.8033	-.0519	-.0005	.8767	.2458	.7951	-.0421	.0171	.8321								
	25.00	.3915	.8182	-.0664	.0000	.9027	.3678	.7773	-.0511	.0107	.8434								
	30.00	.4649	.80																

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

M _m = 3.5										M _m = 4.2									
Configuration	a, deg	C _N	C _A	C _M	C _L	C _D	C _N	C _A	C _M	C _L	C _D	C _N	C _A	C _M	C _L	C _D			
1131	105.00	.3732	-.1155	-.0749	.0150	.3904	.3615	-.0876	-.0706	-.0090	.3719								
	110.00	.3400	-.2784	-.0673	.1453	.4147	.3287	-.2384	-.0634	.1116	.3904								
	115.00	.3067	-.4436	-.0581	.2724	.4655	.2934	-.4044	-.0544	.2425	.4368								
	120.00	.2695	-.4436	-.0463	.4226	.5552	.2527	-.6045	-.0428	.3971	.5211								
	125.00	.2249	-.8461	-.0310	.5641	.6695	.2078	-.8151	-.0289	.5485	.6377								
	130.00	.1807	-.10439	-.0147	.6835	.8094	.1631	-.10110	-.0135	.6697	.7748								
	135.00	.1395	-.12300	.0010	.7711	.9683	.1234	-.12076	-.0024	.7666	.9412								
	135.00	.1204	-.12615	.0037	.8069	.9771	.1079	-.12024	-.0035	.7739	.9265								
	140.00	.0847	-.13823	.0152	.8236	1.1133	.0804	-.13442	.0173	.8024	1.0814								
	145.00	.0601	-.48242	.0226	.8011	1.2488	.0598	-.14471	.0255	.7810	1.2197								
	150.00	.0413	-.15487	.0277	.7386	1.3619	.0415	-.15283	.0291	.7283	1.3443								
	155.00	.0234	-.16035	.0276	.6565	1.4632	.0252	-.15944	.0297	.6510	1.4557								
	160.00	.0093	-.16513	.0250	.5561	1.5549	.0129	-.16453	.0289	.5506	1.5505								
	165.00	.0033	-.16840	.0205	.4327	1.6275	.0048	-.16818	.0238	.4307	1.6257								
	169.00	.0022	-.17121	.0129	.3245	1.6810	.0038	-.17004	.0183	.3208	1.6699								
	165.00	.0032	-.16362	.0241	.4204	1.5813	.0054	-.16605	.0248	.4246	1.6053								
	170.00	.0015	-.16591	.0172	.2866	1.6342	.0051	-.16841	.0175	.2874	1.6594								
	175.00	.0016	-.16726	.0109	.1482	1.6663	.0041	-.16942	.0097	.1436	1.6882								
	177.00	.0017	-.16752	.0086	.0860	1.6730	.0048	-.17094	.0072	.0847	1.7074								
	179.00	.0004	-.16897	.0060	.0291	1.6894	.0048	-.17014	.0038	.0249	1.7012								
	180.00	.0023	-.16818	.0048	.0023	1.6818	.0054	-.17034	.0020	-.0054	1.7034								
	181.00	.0052	-.16921	.0028	.0347	1.6917	.0061	-.17016	-.0007	.0358	1.7012								
	183.00	.0059	-.16899	-.0001	.0943	1.6873	.0061	-.16991	-.0038	.0950	1.6965								
	185.00	.0006	-.16943	-.0027	.1523	1.6875	.0056	-.16974	-.0064	.1535	1.6904								
1231	-5.00	-.0884	.5607	.0044	-.0392	.5663	-.0987	.5522	.0063	-.0502	.5587								
	-3.00	-.0488	.5436	.0022	-.0192	.5454	-.0529	.5534	.0019	-.0238	.5554								
	-1.00	-.0133	.5480	-.0007	-.0034	.5481	-.0155	.5555	-.0006	-.0058	.5557								
	.00	.0086	.5710	-.0022	.0086	.5710	.0054	.5555	-.0024	.0054	.5555								
	1.00	.0249	.5732	-.0037	.0169	.5736	.0237	.5547	-.0038	.0140	.5550								
	3.00	.0621	.5752	-.0064	.0319	.5777	.0620	.5551	-.0066	.0328	.5575								
	5.00	.1013	.5770	-.0097	.0506	.5836	.1006	.5558	-.0094	.0518	.5625								
	10.00	.2019	.5885	-.0179	.0966	.6147	.1982	.5644	-.0169	.0972	.5902								
	15.00	.3024	.6033	-.0266	.1360	.6610	.2984	.5764	-.0257	.1390	.6340								
	20.00	.4138	.6242	-.0366	.1753	.7281	.4059	.5928	-.0355	.1787	.6958								
	17.00	.3508	.6134	-.0283	.1562	.6892	.3432	.5757	-.0259	.1599	.6508								
	20.00	.4172	.6230	-.0337	.1789	.7281	.4105	.5878	-.0335	.1847	.6927								
	25.00	.5253	.6354	-.0437	.2076	.7979	.5049	.6013	-.0410	.2035	.7584								
	30.00	.6244	.6527	-.0512	.2143	.8775	.6004	.6174	-.0480	.2128	.8322								
	35.00	.7127	.6631	-.0575	.2035	.9520	.6868	.6233	-.0558	.2051	.9045								
	40.00	.7748	.6650	-.0609	.1660	1.0074	.7532	.6298	-.0595	.1722	.9666								
	45.00	.8180	.6647	-.0620	.1211	1.0357	.7967	.6165	-.0611	.1275	.9993								
	50.00	.8451	.6219	-.0632	.0668	1.0472	.8258	.5912	-.0640	.0779	1.0126								
	45.00	.7762	.6136	-.0635	.1150	.9828	.7631	.5995	-.0609	.1157	.9635								
	50.00	.8072	.5909	-.0673	.0662	.9981	.7898	.5828	-.0631	.0613	.9796								
	55.00	.8144	.5690	-.0713	.0222	.9952	.8037	.5620	-.0670	.0006	.9808								
	60.00	.8210	.5472	-.0743	.0634	.9846	.8088	.5424	-.0714	.0453	.9716								
	65.00	.8248	.5188	-.0786	.1216	.9668	.8101	.5150	-.0749	.1243	.9518								
	70.00	.8229	.4818	-.0826	.1713	.9381	.8039	.4781	-.0777	.1744	.9189								
	75.00	.8062	.4390	-.0863	.2153	.8923	.7898	.4408	-.0813	.2214	.8770								
	79.00	.7947	.3989	-.0890	.2400	.8562	.7740	.4026	-.0840	.2475	.8366								
	75.00	.7617	.4166	-.0871	.2053	.8435	.7702	.4273	-.0816	.2134	.8546								
	80.00	.7440	.3696	-.0898	.2348	.7969	.7594	.3820	-.0854	.2443	.8142								
	85.00	.7205	.3175	-.0912	.2535	.7455	.7313	.3304	-.0865	.2654	.7573								
	90.00	.6993	.2562	-.0910	.2562	.6993	.7036	.2707	-.0866	.2707	.7036								
	95.00	.6737	.1799	-.0891	.2379	.6554	.6727	.2021	-.0848	.2599	.6525								
	100.00	.6427	.0838	-.0867	.1937	.6184	.6340	.1116	-.0826	.2200	.6050								
	105.00	.6003	-.0476	-.0826	.1094	.5921	.5853	.0168	-.0788	.1353	.5697								
	110.00	.5593	-.1980	-.0764	.0052	.5933	.5343	.1674	-.0734	.0254	.5594								
	107.00	.5989	-.0686	-.0816	.1095	.5928	.5607	.0502	-.0751	.1159	.5509								
	110.00	.5709	-.1591	-.0765	.0458	.5909	.5275	.1510	-.0703	.0385	.5473								
	115.00	.5154	-.3497	-.0667	.0991	.6149	.4730	.3325	-.0618	.1014	.5692								
	120.00	.4510	-.5619	-.0535	.2611	.6716	.4103	.5292	-.0482	.2531	.6199								
	125.00	.3888	-.7623	-.0361	.4014	.7557	.3465	.7367	-.0337	.4048	.7064								
	130.00	.3200	-.9702	-.0163	.5375	.8687	.2824	.9386	-.0151	.5375	.8196								
	135.00	.2568	-.1510	-.0018	.6323	.9955	.2200	.11303	-.0014	.6436	.9548								
	140.00	.2022	-.13030	.0164	.6827	1.1282	.1713	.12751	-.0160	.6884	1.0869								
	135.00	.2046	-.12129	.0002	.7126	1.0020	.1949	-.1556	-.0010	.6793	.9549								
	140.00	.1511	-.13537	.0149	.7544	1.1341													
	145.00	.1059	-.14616	.0224	.7516	1.2580	.1039	-.14270	.0240	.7334	1.2285								
	150.00	.0791	-.15245	.0270	.6938	1.3598	.0800	-.15090	.0292	.6852	1.3468								
	155.00	.0528	-.15921	.0276	.6250	1.4652	.0581	-.15816	.0312	.6157	1.4580								
	160.00	.0314	-.16313	.0258	.5281	1.5436	.0395	-.16349	.0309	.5221	1.5498								
	165.00	.0142	-.16840	.0204	.4222	1.6303	.0224	-.16796	.0258	.4131	1.6282								
	169.00	.0042	-.16937	.0153	.3191	1.6634	.0109	-.16957	.0198	.3129	1.6666								
	165.00	-.0020	-.16228	.0200	.4219	1.5670	.0146	-.16573	.0233	.4148	1.6046								
	170.00	-.0167	-.16665	.0068	.1619	1.6587	.0009	-.16811	.0165	.2910	1.6558								
	175.00	-.0159	-.16797	.0042	.1038	1.6766	.0028	-.17052	.0060	.0921	1.7028								
	177.00	-.0155	-.16889	.0026	.0450	1.6883	.0021	-.17091	.0024	.0319	1.7088								
	179.00	-.0134	-.16958	.0001	.0134	1.6958	.0009	-.17122	.0000	.0009	1.7122								
	181.00	-.0107	-.16986	-.0005	.0189	1.6985	.00												

TABLE I-- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_\infty = 3.5$					$M_\infty = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
1232	45.00	.7850	.6152	-.0648	.1201	.9901	.7604	.5949	-.0618	.1170	.9584
	50.00	.8054	.5898	-.0676	.0659	.9961	.7885	.5777	-.0637	.0643	.9753
	55.00	.8156	.5667	-.0720	.0036	.9931	.8013	.5585	-.0603	.0021	.9767
	60.00	.8203	.5418	-.0750	-.0590	.9813	.8068	.5357	-.0721	-.0605	.9666
	65.00	.8296	.5111	-.0786	-.1126	.9679	.8086	.5055	-.0744	-.1164	.9464
	70.00	.8176	.4655	-.0798	-.1578	.9275	.8023	.4648	-.0770	-.1624	.9129
	75.00	.8095	.4228	-.0798	-.1989	.8913	.7932	.4243	-.0775	-.2045	.8760
	79.00	.8024	.3796	-.0788	-.2195	.8601	.7793	.3844	-.0776	-.2286	.8383
	80.00	.7694	.4140	-.0777	-.2008	.8504	.7770	.4198	-.0769	-.2044	.8592
	85.00	.7551	.3649	-.0767	-.2283	.8070	.7627	.3680	-.0756	-.2330	.8150
	90.00	.7303	.2382	-.0691	-.2382	.7303	.7442	.3108	-.0731	-.2447	.7685
	95.00	.7062	.1565	-.0608	-.2175	.6899	.7252	.2458	-.0689	-.2458	.7252
	100.00	.6933	.0503	-.0492	-.1699	.6792	.7012	.1641	-.0609	-.2246	.6842
	105.00	.6666	-.0689	-.0347	-.1059	.6617	.6779	.0655	-.0493	-.1822	.6562
	110.00	.6318	-.1871	-.0203	-.0403	.6577	.6017	.1818	-.0182	-.0350	.6276
	107.00	.6623	-.0983	-.0286	-.0994	.6621	.6184	.0908	-.0263	-.0940	.6179
	110.00	.6385	-.1790	-.0192	-.0549	.6595	.5936	.1699	-.0167	-.0433	.6159
	115.00	.5861	-.3101	-.0028	-.0333	.6623	.5386	.3098	-.0001	.0532	.6190
	120.00	.5175	-.4531	-.0139	-.1336	.6748	.4780	.4415	-.0161	.1433	.6348
	125.00	.4523	.5915	-.0278	.2251	.7098	.4134	.5805	.0297	.2384	.6716
	130.00	.3843	.7435	-.0401	.3224	.7722	.3451	.7247	.0430	.3333	.7302
	135.00	.3153	.8799	-.0494	.4070	.8530	.2856	.8672	.0505	.4112	.8152
	140.00	.2648	-.10300	-.0545	.4593	.9592	.2348	.9955	.0539	.4600	.9135
	135.00	.2520	-.9216	-.0448	.4735	.8299	.2460	.8793	.0489	.4479	.7957
	140.00	.2014	-.10592	-.0486	.5265	.9409	.1977	-.10149	.0520	.5010	.9046
	145.00	.1563	-.11861	-.0475	.5523	1.0613	.1592	-.1491	.0515	.5287	1.0326
	150.00	.1258	-.12777	-.0456	.5300	1.1694	.1319	-.12508	.0499	.5112	1.1492
	155.00	.0897	-.13755	-.0391	.5000	1.2845	.1008	-.15578	.0457	.4826	1.2732
	160.00	.0614	-.14564	-.0328	.4404	1.3896	.0725	-.14434	.0385	.4256	1.3811
	165.00	.0346	.15159	-.0240	.3589	1.4733	.0495	-.15162	.0309	.3446	1.4773
	169.00	.0189	-.15574	-.0183	.2786	1.5324	.0308	-.15514	.0228	.2658	1.5288
	165.00	.0360	-.14804	-.0265	.3484	1.4393	.0428	-.14883	.0291	.3439	1.4487
	170.00	.0153	-.15207	-.0187	.2490	1.5003	.0214	-.15319	.0201	.2449	1.5123
	175.00	.0024	-.15477	-.0106	.1325	1.5420	.0086	-.15566	.0119	.1272	1.5534
	179.00	-.0021	.15645	-.0037	.0298	1.5643	.0048	-.15687	.0075	.0773	1.5669
	180.00	-.0027	.15695	-.0017	.0207	1.5695	.0022	-.15801	.0033	.0254	1.5799
	181.00	-.0013	.15711	-.0004	.0261	1.5709	.0016	-.15783	.0011	-.0022	1.5783
	183.00	-.0013	.15726	-.0038	.0810	1.5705	.0006	-.15876	-.0016	-.0291	1.5757
	185.00	-.0033	.15712	-.0075	.1336	1.5655	-.0039	-.15704	-.0137	-.0837	1.5854
1233	45.00	.7834	.6168	-.0661	.1178	.9900	.7670	.5995	-.0641	.1185	.9663
	50.00	.8056	.5902	-.0684	.0657	.9965	.7967	.5846	-.0659	.0643	.9861
	55.00	.8220	.5713	-.0739	.0035	1.0010	.8089	.5627	-.0703	.0031	.9854
	60.00	.8265	.5468	-.0778	.0602	.9892	.8133	.5403	-.0742	-.0612	.9745
	65.00	.8278	.5146	-.0819	-.1166	.9677	.8108	.5103	-.0769	-.1198	.9505
	70.00	.8256	.4720	-.0885	-.1611	.9372	.8042	.4721	-.0827	-.1685	.9172
	75.00	.8184	.4263	-.0970	-.2000	.9008	.7794	.4309	-.0896	-.2103	.8798
	79.00	.8122	.3825	-.1050	-.2205	.8703	.7824	.3860	-.0976	-.2296	.8417
	80.00	.7628	.3670	-.0991	-.2289	.8149	.7764	.3721	-.0951	-.2337	.8173
	85.00	.7447	.3109	-.1070	-.2448	.7690	.7419	.3182	-.1017	-.2523	.7668
	90.00	.7214	.2429	-.1124	-.2429	.7214	.7245	.2813	-.1073	-.2613	.7245
	95.00	.7025	.1609	-.1203	-.2215	.6858	.6902	.1858	-.1124	-.2453	.6714
	100.00	.6806	.0523	-.1330	-.1597	.6612	.6650	.0793	-.1256	-.1936	.6411
	105.00	.6553	-.0976	-.1496	-.0753	.6583	.6361	-.0775	-.1466	-.0897	.6345
	110.00	.6309	-.2953	-.1703	-.0617	.6939	.6110	-.2829	-.1745	-.0568	.5710
	107.00	.6536	-.1545	-.1600	-.0434	.6702	.6151	.1364	-.1542	-.0494	.6281
	110.00	.6343	-.2652	-.1707	-.0326	.6858	.6045	-.2681	-.1737	.0451	.6597
	115.00	.6150	-.5555	-.2098	.2436	.7922	.5858	-.5593	-.2183	.2593	.7673
	120.00	.5645	-.8258	-.2119	.4329	.9018	.5207	-.7763	-.2032	.4119	.8391
	125.00	.4923	-.10408	-.1805	.5702	1.0003	.4499	-.9972	-.1795	.5588	.9405
	130.00	.4054	-.12450	-.1337	.6931	1.1109	.3715	-.12099	-.1412	.6880	1.0623
	135.00	.3062	-.13988	-.0688	.7726	1.2056	.2784	-.13762	-.0821	.7762	1.1700
	140.00	.2214	-.16988	-.0084	.7890	1.2835	.1961	-.14657	-.0215	.7919	1.2489
	135.00	.2513	.14270	-.0598	.8313	1.1867	.2519	-.14128	-.0087	.8209	1.1771
	140.00	.1582	-.16874	-.0007	.8349	1.2471	.1651	-.14984	-.0208	.8367	1.2539
	145.00	.1045	-.15339	.0195	.7942	1.3164	.0989	-.15256	.0187	.7941	1.3064
	150.00	.0698	-.15813	.0273	.7303	1.4043	.0686	-.15900	.0296	.7356	1.4113
	155.00	.0431	-.16268	.0310	.6984	1.4926	.0438	-.16247	.0340	.6469	1.4910
	160.00	.0200	-.16638	.0283	.5503	1.5703	.0249	-.16626	.0339	.5452	1.5708
	165.00	.0054	-.16999	.0220	.4348	1.6434	.0083	-.16961	.0279	.4719	1.6404
	169.00	-.0043	-.17159	.0097	.3316	1.6836	.0010	-.17098	.0216	.3252	1.6786
	165.00	-.0023	-.16721	.0295	.4350	1.6145	.0088	-.16890	.0270	.4286	1.6338
	170.00	-.0125	-.16896	.0186	.3057	1.6617	.0015	-.17103	.0195	.2985	1.6840
	175.00	-.0117	-.17060	.0117	.1604	1.6985	.0001	-.17240	.0112	.1504	1.7174
	177.00	-.0090	-.17109	.0089	.0985	1.7081	.0013	-.17270	.0072	.0891	1.7247
	179.00	-.0077	-.17204	.0042	.0377	1.7200	.0043	-.17322	.0040	.0259	1.7320
	180.00	-.0061	-.17233	.0045	.0061	1.7233	.0054	-.17320	.0020	-.0054	1.7330
	181.00	-.0022	-.17274	.0031	-.0279	1.7271	.0066	-.17326	-.0002	-.0368	1.7322
	183.00	.0005	-.17269	.0002	-.0909	1.7245	.0079	-.17326	-.0038	-.0986	1.7298
	185.00	.0019	-.17292	.0028	-.1526	1.7224	.0102	-.17273	-.0070	-.1608	1.7196

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_\infty = 3.5$												$M_\infty = 4.2$											
Config-	uation	α ,	deg	C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D										
2231	-5.00	-0.0926	.5391	.0040	-.0452	.5452	-.0923	.5292	.0049	-.0458	.5352												
	-3.00	-.0525	.5396	.0015	-.0242	.5416	-.0534	.5293	.0018	-.0256	.5314												
	-1.00	-.0132	.5441	-.0010	-.0037	.5442	-.0154	.5298	-.0008	-.0062	.5300												
	.00	.0093	.5472	-.0029	.0093	.5472	.0066	.5295	-.0026	.0066	.5295												
	1.00	.0263	.5488	-.0039	.0167	.5492	.0246	.5339	-.0041	.0173	.5343												
	3.00	.0636	.5513	-.0067	.0346	.5538	.0642	.5348	-.0069	.0361	.5375												
	5.00	.1039	.5554	-.0096	.0551	.5624	.1018	.5378	-.0096	.0545	.5447												
	10.00	.2100	.5721	-.0177	.1075	.5999	.2026	.5521	-.0173	.1036	.5789												
	15.00	.3175	.5958	-.0258	.1525	.6577	.3114	.5742	-.0262	.1522	.6532												
	20.00	.4296	.6218	-.0336	.1910	.7312	.4263	.6006	-.0345	.1952	.7102												
	17.00	.3647	.6108	-.0252	.1702	.6907	.3548	.5749	-.0257	.1712	.6535												
	20.00	.4340	.6282	-.0305	.1929	.7387	.4239	.5938	-.0302	.1952	.7030												
	25.00	.5410	.6500	-.0354	.2156	.8177	.5259	.6165	-.0358	.2161	.7810												
	30.00	.6469	.6699	-.0420	.2255	.9032	.6230	.6351	-.0412	.2219	.8615												
	35.00	.7342	.6806	-.0467	.2110	.9786	.6928	.6460	-.0398	.1970	.9266												
	40.00	.7930	.6854	-.0461	.1669	1.0347	.7707	.6945	-.0491	.1755	.9898												
	45.00	.8400	.6672	-.0483	.1222	1.0658	.8126	.6280	-.0486	.1305	1.0187												
	50.00	.8674	.6356	-.0482	.0707	1.0731	.8362	.5958	-.0477	.0811	1.0234												
	45.00	.8046	.6263	-.0564	.1260	1.0118	.7818	.6083	-.0533	.1227	.9829												
	50.00	.8216	.5919	-.0587	.0747	1.0099	.8099	.5845	-.0553	.0728	.9961												
	55.00	.8374	.5678	-.0597	.0152	1.0117	.8266	.5596	-.0571	.0157	.9981												
	60.00	.8523	.5420	-.0609	-.0432	1.0091	.8432	.5380	-.0574	-.0443	.9992												
	65.00	.8571	.5109	-.0654	-.1008	.9927	.8452	.5060	-.0614	-.1014	.9798												
	70.00	.8548	.4688	-.0700	.1481	.9635	.8398	.4712	-.0650	-.1556	.9504												
	75.00	.8410	.4265	-.0750	.1943	.9227	.8278	.4330	-.0696	-.2039	.9117												
	79.00	.8312	.3872	-.0778	.2215	.8898	.8128	.3975	-.0721	-.2351	.8737												
	75.00	.8080	.4359	-.0721	.2119	.8933	.8064	.4254	-.0702	-.2022	.8890												
	80.00	.7906	.3894	-.0752	.2462	.8462	.7939	.3844	-.0722	-.2407	.8486												
	85.00	.7677	.3362	-.0758	.2680	.7941	.7746	.3582	-.0733	.2694	.8012												
	90.00	.7558	.2763	-.0757	.2763	.7538	.7490	.2798	-.0724	.2798	.7499												
	95.00	.7242	.2027	-.0731	.2650	.7037	.7185	.2159	-.0703	.2777	.6970												
	100.00	.6925	.1091	-.0705	.2277	.6631	.6790	.1283	-.0683	.2443	.6464												
	105.00	.6481	.0240	-.0676	.1445	.6322	.6303	.0018	-.0657	.1648	.6083												
	110.00	.6026	.1757	-.0625	.0410	.6264	.5763	.1486	-.0607	.0575	.5923												
	107.00	.6251	.1020	-.0728	.0653	.6276	.5922	.0672	-.0639	.1088	.5859												
	110.00	.5931	.2025	-.0685	.0126	.6266	.5575	.1691	-.0609	.0118	.5817												
	115.00	.5285	.3859	-.0590	.1263	.6421	.4936	.3546	-.0522	.1128	.5973												
	120.00	.4687	.5494	-.0462	.2808	.7034	.4327	.5551	-.0405	.2645	.6523												
	125.00	.3971	.7953	-.0303	.4237	.7815	.3643	.7594	-.0267	.4131	.7340												
	130.00	.3321	-1.0093	-.0117	.5597	.9032	.2957	.9653	-.0079	.5499	.8470												
	135.00	.2599	-1.1825	-.0054	.6528	1.0196	.2307	-1.1495	-.0059	.6497	.9759												
	140.00	.2000	-1.3355	-.0197	.7052	1.1516	.1743	-1.3034	-.0199	.7043	1.1105												
2232	45.00	.8020	.6248	-.0559	.1253	1.0089	.7831	.6122	-.0527	.1207	.9871												
	50.00	.8231	.5947	-.0575	.0735	1.0128	.8149	.5871	-.0548	.0741	1.0016												
	55.00	.8367	.5698	-.0596	.0131	1.0122	.8236	.5599	-.0568	.0138	.9958												
	60.00	.8517	.5397	-.0604	-.0415	1.0075	.8411	.5361	-.0567	-.0437	.9965												
	65.00	.8538	.5005	-.0639	-.0928	.9853	.8433	.5000	-.0603	-.0968	.9756												
	70.00	.8526	.4589	-.0657	.1396	.9582	.8412	.4632	-.0622	-.1476	.9489												
	75.00	.8431	.4183	-.0659	.1858	.9227	.8315	.4225	-.0647	-.1929	.9126												
	79.00	.8448	.3759	-.0667	.2078	.9010	.8208	.3832	-.0636	-.2196	.8788												
	75.00	.8011	.4124	-.0650	.1910	.8805	.8088	.4139	-.0637	-.1905	.8883												
	80.00	.7922	.3647	-.0637	.2216	.8435	.7932	.3664	-.0619	-.2231	.8448												
	85.00	.7816	.3058	-.0609	.2365	.8053	.7919	.3109	-.0596	-.2415	.8040												
	90.00	.7698	.2377	-.0554	.2377	.7698	.7444	.2462	-.0550	-.2462	.7644												
	95.00	.7540	.1586	-.0475	.2237	.7373	.7433	.1686	-.0475	-.2328	.7258												
	100.00	.7360	.0575	-.0385	.1844	.7148	.7153	.0697	-.0362	-.1928	.6923												
	105.00	.7080	.0601	-.0223	.1251	.6995	.6810	.0442	-.0224	-.1336	.6699												
	110.00	.6699	.1807	-.0091	.0593	.6913	.6364	.1686	-.0082	-.0593	.6557												
	107.00	.6922	.1085	-.0199	.0986	.6937	.6446	.0955	-.0166	-.0972	.6443												
	110.00	.6703	.1829	-.0102	-.0574	.6925	.6174	.1770	-.0081	-.0449	.6047												
	115.00	.6139	.3193	-.0054	.0300	.6913	.5621	.3180	-.0087	.0506	.6438												
	120.00	.5445	.4658	-.0201	.1311	.7044	.4984	.4498	-.0236	.1403	.6565												
	125.00	.4681	.6064	-.0328	.2282	.7312	.4251	.5958	-.0368	.2442	.6899												
	130.00	.3949	.7585	-.0448	.3272	.7901	.3567	.7275	-.0470	.3280	.7408												
	135.00	.3276	.8939	-.0531	.4005	.8637	.2912	.8700	-.0536	.4093	.8211												
	140.00	.2650	-1.0451	-.0573	.4688	.9709	.2344	-1.0131	-.0567	.4716	.9268												
2233	45.00	.7997	.6312	-.0562	.1192	1.0118	.7848	.6191	-.0532	.1171	.9927												
	50.00	.8247	.6032	-.0584	.0680	1.0195	.8140	.5942	-.0557	.0680	1.0055												
	55.00	.8401	.5740	-.0600	.0101	1.0186	.8291	.5682	-.0579	.0102	1.0051												
	60.00	.8547	.5481	-.0617	-.0473	1.0143	.8453	.5464	-.0579	-.0505	1.0052												
	65.00	.8581	.5150	-.0658	.1040	.9953	.8492	.5143	-.0622	-.1072	.9870												
	70.00	.8554	.4706	-.0731	.1496	.9648	.8465	.4736	-.0691	-.1555	.9574												
	75.00	.8507	.4285	-.0811	.1937	.9326	.8398	.4351	-.0755	-.2029	.9238												
	79.00	.8455	.3817	-.0904	-.2134	.9028	.8198	.3901	-.0824	-.2265	.8791												

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

Configuration	α , deg	$M_{\infty} = 3.5$					$M_{\infty} = 4.2$				
		C_N	C_A	C_m	C_L	C_D	C_N	C_A	C_m	C_L	C_D
2233	75.00	.8085	.4143	-.0805	-.1909	.8882	.8175	.4225	-.0753	-.1965	.8990
	80.00	.7910	.3591	-.0890	-.2162	.8414	.8049	.3734	-.0832	-.2279	.8575
	85.00	.7845	.3051	-.0977	-.2355	.8081	.7873	.5200	-.0900	-.2502	.8122
	90.00	.7666	.2421	-.1034	-.2421	.7666	.7642	.2621	-.0947	-.2621	.7642
	95.00	.7477	.1646	-.1103	-.2292	.7206	.7359	.1886	-.1007	-.2520	.7167
	100.00	.7241	.0490	-.1234	-.1740	.7046	.7061	.0819	-.1144	-.2033	.6812
	105.00	.6925	-.1057	-.1408	-.0771	.6963	.6755	-.0718	-.1359	-.1656	.6059
	110.00	.6636	-.2889	-.1607	-.0445	.7224	.6444	-.2834	-.1475	-.0459	.7024
	115.00	.6452	-.1639	-.1523	-.0449	.7072	.6455	-.1472	-.1475	-.0479	.6603
	120.00	.5846	-.5696	-.2011	.2445	.8255	.6352	-.2836	-.1683	.0492	.6939
	125.00	.5049	-.10452	-.1662	.5666	1.0151	.6098	.5013	-.2112	.2691	.7984
	130.00	.4154	-.12541	-.1219	.6937	1.1243	.3805	-.2199	-.1300	.6899	1.0756
	135.00	.3202	-.14002	-.0615	.7637	1.2165	.2880	-.3804	-.0743	.7725	1.1797
	140.00	.2220	-.14830	-.0001	.7832	1.2787	.1954	-.14663	-.0091	.7928	1.2488
3231	-5.00	-.1013	.5338	.0067	-.0544	.5406	-.0947	.5225	-.0055	-.0488	.5288
	-3.00	-.0579	.5347	.0036	-.0298	.5370	-.0505	.5204	.0024	-.0232	.5223
	-1.00	-.0204	.5370	.0015	-.0110	.5373	-.0160	.5296	.0000	-.0069	.5208
	.00	.0011	.5390	.0000	.0011	.5390	.0004	.5204	-.0013	.0043	.5204
	1.00	.0187	.5403	-.0019	.0093	.5405	.0204	.5197	-.0026	.0113	.5206
	3.00	.0595	.5427	-.0046	.0310	.5451	.0611	.5272	-.0059	.0334	.5297
	5.00	.0966	.5473	-.0074	.0485	.5536	.0979	.5105	-.0082	.0513	.5370
	10.00	.2037	.5680	-.0155	.1020	.5948	.2009	.5508	-.0184	.1022	.5773
	15.00	.3186	.6023	-.0243	.1518	.6643	.3172	.5804	-.0253	.1562	.6427
	20.00	.4314	.6323	-.0302	.1891	.7417	.3585	.5812	-.0258	.1729	.6606
	17.00	.3735	.6181	-.0266	.1765	.7003	.3585	.5812	-.0258	.1729	.6606
	20.00	.4423	.6373	-.0294	.1976	.7502	.4262	.6018	-.0291	.1947	.7113
	25.00	.5539	.6661	-.0348	.2205	.8578	.5315	.6351	-.0336	.2133	.8002
	30.00	.6521	.6863	-.0389	.2215	.9204	.6325	.6560	-.0382	.2198	.8844
	35.00	.7436	.7031	-.0431	.2058	1.0024	.7150	.6665	-.0419	.2034	.9561
	40.00	.8045	.7056	-.0435	.1627	1.0576	.7769	.6666	-.0434	.1666	1.0100
	45.00	.8329	.6901	-.0379	.1010	1.0770	.8227	.6185	-.0449	.1231	1.0403
	50.00	.8701	.6479	-.0434	.0630	1.0830	.8455	.6109	-.0433	.0755	1.0404
	45.00	.7996	.6303	-.0512	.1197	1.0111	.7856	.6206	-.0478	.1167	.9943
	50.00	.8241	.6045	-.0509	.0668	1.0197	.8182	.5928	-.0489	.0718	1.0078
	55.00	.8401	.5496	-.0520	.0153	1.0149	.8322	.5620	-.0500	.0169	1.0041
	60.00	.8508	.5393	-.0558	.0416	1.0065	.8447	.5366	-.0515	-.0423	.9998
	65.00	.8588	.4986	-.0599	.0890	.9890	.8506	.5013	-.0555	-.0948	.9828
	70.00	.8621	.4622	-.0641	.1394	.9682	.8483	.4653	-.0590	.1471	.9562
	75.00	.8476	.4205	-.0674	.1868	.9275	.8399	.4316	-.0616	.1995	.9230
	79.00	.8378	.3829	-.0702	.2160	.8955	.8272	.3960	-.0655	.2309	.8876
	75.00	.8150	.4279	-.0645	.2024	.8979	.8178	.4249	-.0622	.1987	.8999
	80.00	.8017	.3838	-.0675	.2388	.8561	.8040	.3821	-.0641	.2367	.8582
	85.00	.7861	.3345	-.0684	.2647	.8123	.7856	.3567	-.0647	.2669	.8119
	90.00	.7691	.2748	-.0672	.2748	.7691	.7661	.2844	-.0638	.2844	.7661
	95.00	.7450	.2010	-.0652	.2651	.7247	.7374	.2189	-.0617	.2824	.7155
	100.00	.7129	.1113	-.0634	.2334	.6828	.6975	.1314	-.0599	.2505	.6641
	105.00	.6684	-.0207	-.0609	.1530	.6510	.6452	.0029	-.0584	.1698	.6224
	110.00	.6189	-.1701	-.0561	.0519	.5915	.5915	-.1456	-.0543	-.0655	.6056
	107.00	.6496	-.0812	-.0614	.1122	.6449	.6036	-.0638	-.0571	.1155	.5959
	110.00	.6166	-.1829	-.0581	.0390	.6420	.5701	-.4018	-.0532	-.0430	.5910
	115.00	.5507	.3647	-.0499	.0978	.6532	.5038	-.3543	-.0453	.1082	.6063
	120.00	.4825	.5671	-.0381	.2498	.7015	.4413	-.5360	-.0332	.2435	.6502
	125.00	.4199	.7713	-.0217	.3910	.7864	.3700	.7527	-.0212	.4044	.7348
	130.00	.3494	.9857	-.0048	.5305	.9013	.3021	.9499	-.0037	.5335	.8420
	135.00	.2742	-.1634	.0120	.6274	1.0180	.2337	-.1404	.0118	.6411	.9717
	140.00	.2142	-.13177	.0263	.6829	1.1471	.1777	-.12890	.0245	.6925	1.1016
3232	45.00	.8080	.6416	-.0487	.1176	1.0250	.7903	.6282	-.0474	.1146	1.0030
	50.00	.8322	.6130	-.0492	.0653	1.0315	.8233	.5997	-.0477	.0698	1.0162
	55.00	.8465	.5804	-.0507	.0101	1.0263	.8373	.5708	-.0484	.0127	1.0133
	60.00	.8571	.5457	-.0532	-.0440	1.0152	.8495	.5393	-.0503	-.0422	1.0054
	65.00	.8635	.5018	-.0559	-.0899	.9947	.8563	.5019	-.0529	-.0930	.9882
	70.00	.8637	.4599	-.0583	-.1368	.9689	.8566	.4633	-.0550	-.1424	.9634
	75.00	.8587	.4150	-.0593	-.1787	.9368	.8433	.4182	-.0564	.1857	.9228
	79.00	.8540	.3743	-.0592	-.2044	.9097	.8346	.3817	-.0562	.2154	.8921
	75.00	.8098	.4078	-.0595	-.1843	.8877	.8221	.4113	-.0576	.1845	.9006
	80.00	.8067	.3606	-.0590	-.2150	.8570	.8121	.3659	-.0565	.2193	.8633
	85.00	.7996	.3068	-.0560	-.2359	.8233	.8017	.4122	-.0539	.2411	.8259
	90.00	.7905	.2387	-.0506	-.2387	.7905	.7919	.2516	-.0499	.2516	.7919
	95.00	.7750	.1592	-.0423	-.2261	.7582	.7694	.1730	-.0417	.2394	.7514
	100.00	.7549	.0610	-.0308	-.1912	.7328	.7343	.0732	-.0301	.1996	.7104
	105.00	.7246	-.0581	-.0169	-.1314	.7149	.7016	-.0437	-.0172	.1394	.6890
	110.00	.6852	-.1823	-.0032	-.0631	.7063	.6505	.1670	-.0028	.0656	.6684
	107.00	.7068	-.1099	-.0098	-.1015	.7080	.6605	.0993	-.0090	-.0981	.6606
	110.00	.6796	-.1841	-.0015	-.0594	.7016	.6335	-.1779	-.0002	-.0495	.6561
	115.00	.6255	-.3215	.0128	.0271	.7028	.5739	-.3134	.0150	.0415	.6525
	120.00	.5544	-.4632	.0277	.1239	.7117	.5059	-.4484	.0297	.1353	.6623
	125.00	.4821	-.6093	.0409	-.2226	.7444	.4354	-.5915	.0422	.2348	.6960
	130.00	.4045	-.7521	.0498	.3161	.7933	.3632	-.7388	.0519	.3325	.7531
	135.00	.3367	-.9050	.0572	.4018	.8780	.2986	-.8791	.0572	.4105	.8327
	140.00	.2713	-.1.0367	.0598	.4586	.9686	.2405	-.1.0100	.0594	.4650	.9283

TABLE I.- AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

$M_\infty = 3.5$											
Config- uration	α , deg	c_N	c_A	c_m	c_L	c_D	c_N	c_A	c_m	c_L	c_D
3233	45.00	.8047	.6365	-.0512	.1189	1.0191	.7924	.6251	-.0476	.1183	1.0023
	50.00	.8289	.6085	-.0518	.0667	1.0261	.8224	.5997	-.0480	.0692	1.0155
	55.00	.8443	.5735	-.0519	.0145	1.0205	.8374	.5680	-.0494	.0150	1.0118
	60.00	.856	.5431	-.0544	-.0430	1.0117	.8480	.5399	-.0512	-.0436	1.0044
	65.00	.8591	.4995	-.0594	-.0896	.9897	.8556	.5039	-.0549	-.0951	.9884
	70.00	.8632	.4606	-.0656	-.1376	.9686	.8556	.4655	-.0607	-.1448	.9632
	75.00	.8565	.4184	-.0730	-.1624	.9356	.8429	.4227	-.0672	-.1901	.9236
	79.00	.8583	.3746	-.0830	-.2039	.9140	.8310	.3841	-.0737	-.2184	.8890
	75.00	.8210	.4176	-.0706	-.1909	.9011	.8312	.4192	-.0681	-.1898	.9114
	80.00	.8144	.3648	-.0791	-.2179	.8653	.8211	.3718	-.0752	-.2236	.8732
	85.00	.8022	.3111	-.0870	-.2400	.8263	.8053	.3217	-.0814	-.2503	.8302
	90.00	.7859	.2496	-.0925	-.2496	.7859	.7829	.2643	-.0856	-.2643	.7829
	95.00	.7681	.1719	-.0995	-.2381	.7502	.7564	.1922	-.0912	-.2574	.7367
	100.00	.7453	.0640	-.1119	-.1922	.7229	.7258	.0894	-.1050	-.2140	.6993
	105.00	.7153	-.0936	-.1304	-.0947	.7151	.6928	-.0675	-.1268	-.1141	.6867
	110.00	.6833	-.2788	-.1507	.0283	.7375	.6626	-.2710	-.1563	.0281	.7153
	107.00	.7052	-.1623	-.1448	-.0510	.7219	.6576	-.1436	-.1404	-.0550	.6709
	110.00	.6839	-.2800	-.1575	-.0292	.7385	.6413	-.2761	-.1599	.0401	.6970
	115.00	.6533	-.5605	-.1938	.2319	.8200	.6162	.5635	-.2028	.2503	.7966
	120.00	.5909	-.8218	-.1939	.4162	.9226	.5466	-.7814	-.1905	.4034	.8641
	125.00	.5131	-.10389	-.1608	.5567	1.0162	.4772	-.10158	-.1702	.5584	.9735
	130.00	.4219	-.1.2521	-.1.1882	.6880	1.1280	.3850	-.1.2189	-.1.2726	.6862	1.0784
	135.00	.3191	-.1.3952	-.0.551	.7610	1.2122	.2913	-.1.3793	-.0.722	.7693	1.1813
	140.00	.2273	-.1.4891	-.0.048	.7831	1.2868	.1974	-.1.4632	-.0.063	.7893	1.2478
$M_\infty = 4.2$											
1331	-5.00	-.1299	.4149	.0100	-.0932	.4246	-.1317	.3867	.0109	-.0975	.3967
	-3.00	-.0771	.4148	.0057	-.0553	.4182	-.0792	.3841	.0064	-.0590	.3877
	-1.00	-.0297	.4157	.0026	-.0224	.4161	-.0286	.3821	.0022	-.0219	.3825
	.00	-.0044	.4171	.0013	-.0044	.4171	-.0052	.3813	.0002	-.0052	.3813
	1.00	.0184	.4186	-.0008	.0111	.4188	.0210	.3825	-.0025	.0143	.3828
	3.00	.0665	.4225	-.0049	.0443	.4254	.0575	.3865	-.0065	.0472	.3895
	5.00	.1164	.4282	-.0090	.0787	.4367	.1191	.3924	-.0113	.0844	.4013
	10.00	.2418	.4501	-.0188	.1599	.4853	.2462	.4145	-.0210	.1705	.4510
	15.00	.3677	.4797	-.0257	.2310	.5586	.3724	.4454	-.0284	.2444	.5266
	20.00	.4946	.5116	-.0321	.2898	.6499	.4915	.4756	-.0335	.2992	.6150
	17.00	.4333	.4881	-.0285	.2717	.5935	.4325	.4562	-.0287	.2802	.5628
	20.00	.5035	.5074	-.0308	.2996	.6490	.5003	.4701	-.0310	.3093	.6128
	25.00	.6241	.5296	-.0359	.3418	.7438	.6098	.4924	-.0358	.3446	.7040
	30.00	.7360	.5488	-.0415	.3630	.8433	.7257	.5238	-.0421	.3666	.8165
	35.00	.8439	.5760	-.0474	.3609	.9558	.8240	.5448	-.0481	.3625	.9189
	40.00	.9196	.5853	-.0491	.3283	1.0395	.8990	.5603	-.0485	.3285	1.0071
	45.00	.9808	.5925	-.0469	.2745	1.1125	.9513	.5647	-.0472	.2734	1.0720
	50.00	.1.0096	.5828	-.0451	.2026	1.1480	.9840	.5578	-.0451	.2052	1.1123
	45.00	.9250	.5639	-.0575	.2554	1.0528	.9063	.5450	-.0544	.2555	1.0263
	50.00	.9654	.5583	-.0581	.1928	1.0984	.9438	.5427	-.0541	.1910	.0718
	55.00	.9964	.5491	-.0580	.1217	1.1312	.9790	.5397	-.0541	.1194	.1.1115
	60.00	1.0136	.5420	-.0627	.0374	1.1488	1.0002	.5347	-.0585	.0370	1.1336
	65.00	1.0195	.5319	-.0677	-.0512	1.1488	1.0076	.5243	-.0627	-.0494	1.1348
	70.00	1.0100	.5011	-.0739	-.1255	1.1205	1.0018	.5029	-.0691	-.1300	.1.1134
	75.00	1.0088	.4769	-.0805	.1.196	1.0978	.5096	.4747	-.0746	-.2024	.1.0788
	79.00	.9881	.4410	-.0845	-.2444	1.0540	.9734	.4482	-.0787	-.2543	1.0410
	75.00	.9509	.4543	-.0747	-.1927	1.0361	.9796	.4724	-.0728	-.2028	.1.0685
	80.00	.9308	.4152	-.0802	-.2473	.9888	.9587	.4309	-.0778	-.2579	1.0189
	85.00	.9091	.3677	-.0829	-.2871	.9376	.9302	.3849	-.0803	.3023	.9602
	90.00	.8827	.3086	-.0836	-.3086	.8827	.8964	.3305	-.0811	.3305	.8964
	95.00	.8524	.2348	-.0832	-.3082	.8287	.8527	.2600	-.0795	.3333	.8268
	100.00	.8088	.1361	-.0826	-.2744	.7729	.7978	.1610	-.0795	-.2971	.7577
	105.00	.7520	.0003	-.0814	-.1949	.7263	.7384	.0336	-.0789	-.2236	.7045
	110.00	.6960	.1584	-.0771	-.0892	.7082	.6697	.1269	-.0735	-.1099	.6727
	107.00	.7451	-.0304	-.0626	-.1887	.7214	.6957	-.0132	-.0756	-.1908	.6692
	110.00	.7009	.1297	-.0780	-.1178	.7030	.6543	.1179	-.0725	-.1130	.6551
	115.00	.6362	.3243	-.0696	-.0250	.7137	.5826	.3060	-.0642	.0311	.6573
	120.00	.5504	.5341	-.0560	.1873	.7438	.5094	.4975	-.0520	.1761	.6900
	125.00	.4784	.7361	-.0393	.3286	.8141	.4260	.7162	-.0360	.3424	.7598
	130.00	.3939	.9619	-.0196	.4837	.9200	.3949	.6919	-.0176	.4795	.8586
	135.00	.3178	-.1.1442	-.0004	.5844	1.0338	.2719	-.1.1173	-.0019	.5978	.9824
	140.00	.2455	-.1.3141	-.0179	.6566	1.1645	.2058	.1.2781	-.0174	.6638	1.1114
	135.00	.2601	-.1.1861	-.0042	.6548	1.0226	.2431	-.1.1497	-.0039	.6411	.9849
	140.00	.1889	-.1.3339	-.0125	.7127	1.1432	.1779	-.1.2930	-.0126	.6948	1.1049
	145.00	.1355	-.1.4417	-.0200	.7159	1.2587	.1285	-.1.4218	-.0218	.7102	1.2384
	150.00	.0982	-.1.5156	-.0275	.6015	1.4630	.0742	-.1.5677	-.0323	.5953	1.4522
	155.00	.0731	-.1.5801	-.0276	.5114	1.5479	.0504	-.1.6166	-.0286	.5055	1.5363
	160.00	.0488	-.1.6295	-.0228	.4071	1.6187	.0291	-.1.6576	-.0244	.4009	1.6086
	165.00	.0257	-.1.6689	-.0179	.3127	1.6657	.0160	-.1.6789	-.0173	.3047	1.6512
	169.00	.0109	-.1.6947	-.0034	.4023	1.5675	.0262	-.1.6423	-.0251	.3998	1.5931
	165.00	.0171	-.1.6182	-.0238	.4023	1.6327	.0108	-.1.6708	-.0179	.2795	1.6473
	170.00	.0001	-.1.6579	-.0171	.2878	1.6667	.0002	-.1.6959	-.0067	.0886	1.6936
	175.00	-.0096	-.1.6757	-.0097	.1557	1.6685	.0013	-.1.6894	-.0099	.1459	1.6831
	177.00	-.0114	-.1.6696	-.0072	.0988	1.6667	.0002	-.1.6959	-.0067	.0886	1.6936
	179.00	-.0107	-.1.6765	-.0046	.0400	1.6760	.0004	-.1.6997	-.0020	.0293	1.6994
	180.00	-.0086	-.1.6817	-.0028	.0086	1.6817	.0010	-.1.7136	-.0002	-.0010	1.7136
	181.00	-.0059	-.1.6844	-.0004	-.0235	1.6842	.0028	-.1.7004	-.0021	-.0325	1.7001
	183.00	-.0005	-.1.6839	-.0034	-.0876	1.6816	.0039	-.1.6982	-.0057	-.0928	1.6957
	185.00	.0001	-.1.6874	-.0059	-.1472	1.6810	.0023	-.1.6971	-.0091	-.1502	1.6905

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Config- uration	c_a , deg	C_N	C_A	C_m	C_L	C_D	Config- uration	c_a , deg	C_N	C_A	C_m	C_L	C_D
1111	-5.00	-.0676	.8818	.0166	.0096	.8843	1211	61.00	.9010	.5101	-.0470	-.0093	1.0353
	-3.00	-.0342	.8837	.0041	.0121	.8843		65.00	.9054	.4801	-.0486	-.4525	1.0235
	-1.00	-.0038	.8825	-.0008	.0116	.8851		70.00	.8950	.4416	-.0510	-.1089	.9920
	.00	.0141	.8844	-.0044	.0141	.8844		75.00	.8826	.3907	-.0559	-.1420	.9536
	1.00	.0282	.8858	-.0069	.0127	.8862		80.00	.8442	.3459	-.0586	-.1940	.8915
	3.00	.0585	.8795	-.0114	.0124	.8814		85.00	.8126	.2924	-.0603	-.2199	.8820
	5.00	.0919	.8711	-.0179	.0154	.8788		90.00	.7666	.2307	-.0626	-.2307	.7066
	10.00	.1613	.8684	-.0292	.0080	.8852		95.00	.7525	.1694	-.0607	-.2342	.7328
	15.00	.2429	.8515	-.0411	.0046	.8828		100.00	.7124	.0995	-.0616	-.2217	.6843
	20.00	.3031	.8416	-.0551	-.0033	.8945		105.00	.6831	.0246	-.0625	-.1777	.6601
	25.00	.3728	.8203	-.0698	-.0088	.9010		110.00	.6717	.3797	-.0571	-.1575	.9377
	35.00	.4677	.7222	-.0843	-.0311	.8599		115.00	.6523	.3391	-.0600	-.1859	.8983
	40.00	.5117	.6931	-.0935	-.0535	.8598		120.00	.6523	.2817	-.0619	-.2093	.8396
	45.00	.5483	.6516	-.1020	-.0731	.8485		125.00	.7853	.2212	-.0626	-.2212	.7653
	50.00	.5700	.6095	-.1068	-.1005	.8284		130.00	.7459	.1596	-.0619	-.2240	.7292
	55.00	.5797	.5661	-.1100	-.1312	.7996		135.00	.7085	.0828	-.0621	-.2055	.6831
	60.00	.5798	.5176	-.1115	-.1584	.7609		140.00	.6635	-.0169	-.0644	-.1554	.6553
	61.00	.5918	.5353	-.0950	-.1861	.7684		145.00	.6267	-.1658	-.0653	-.0585	.6556
	65.00	.5781	.4942	-.0966	-.2036	.7328		150.00	.5804	.3174	-.0632	-.0696	.6728
	70.00	.5649	.4400	-.0932	-.2203	.6813		155.00	.5469	.4672	-.0608	-.1557	.7022
	75.00	.5456	.3056	-.0905	-.2314	.6268		160.00	.4965	.5260	-.0675	-.1752	.6965
	80.00	.5187	.3285	-.0869	-.2334	.5678		165.00	.4436	.6978	-.0458	-.3172	.7636
	85.00	.4088	.2693	-.0821	-.2257	.5104		170.00	.3679	.9160	-.0293	-.4653	.8705
	90.00	.4609	.2040	-.0753	-.2040	.4609		175.00	.2915	-.1183	-.0139	-.5847	.9969
	95.00	.4300	.1388	-.0695	-.1758	.4163		180.00	.2126	.2126	-.0111	.6544	1.1215
	100.00	.4018	.0592	-.0640	-.1281	.3854		185.00	.1586	.14006	-.0150	.6735	1.2383
	105.00	.3839	-.0056	-.0617	-.0809	.3754		190.00	.1118	.14947	-.0222	.6506	1.3503
	110.00	.5307	.3594	-.0896	-.2306	.5979		195.00	.0813	.15653	-.0248	.5876	1.4530
	115.00	.3225	.3231	-.0865	-.2287	.5636		200.00	.0580	.16134	-.0255	.4973	1.5359
	120.00	.3325	.2032	-.0565	-.0768	.3829		205.00	.0426	.16415	-.0226	.4497	1.5792
	121.00	.2654	.1784	-.0499	-.2167	.4357		210.00	.0295	.15622	-.0136	.6796	1.4094
	125.00	.2335	.1747	-.0389	-.3592	.5225		215.00	.0211	.16043	-.0229	.6117	1.4849
	130.00	.1909	.9567	-.0128	.6102	.7612		220.00	.0152	.16596	-.0212	.5204	1.5767
	135.00	.1425	.1580	-.0043	.7131	.9245		225.00	.0165	.17022	-.0165	.4168	1.6506
	140.00	.1066	.3156	.0144	.7640	1.0763		230.00	.0163	.17246	-.0125	.2928	1.6996
	145.00	.0728	.4338	-.0232	.7626	1.2163		235.00	.0075	.17446	-.0055	.1596	1.7373
	150.00	.0544	.15205	-.0299	.7132	1.3440		240.00	.0126	.17447	-.0015	.1039	1.7416
	155.00	.0369	.15860	-.0350	.6369	1.4530		245.00	.0070	.17541	-.0025	.4396	1.7556
	160.00	.0167	.16426	-.0298	.5461	1.5892		250.00	.0025	.17542	-.0019	.0065	1.7542
	165.00	.0048	.16625	-.0265	.4309	1.6264		255.00	.0020	.17429	-.0029	.0059	1.7475
	170.00	.0299	.15929	-.0252	.6966	1.4329		260.00	.0043	.17560	-.0079	.1488	1.7497
	175.00	.0186	.16150	-.0244	.6656	1.4716		265.00	.0004	.17297	-.0317	.1298	.7189
	180.00	.0074	.16737	-.0239	.5654	1.5753		270.00	.0071	.17474	-.0311	.1447	.9370
	185.00	-.0054	.17145	-.0179	.4489	1.6547		275.00	.0050	.17333	-.0530	-.1700	.8778
	190.00	-.0069	.17386	-.0135	.3087	1.7110		280.00	.0029	.17239	-.0514	-.1925	.8439
	195.00	-.0085	.17563	-.0061	.1616	1.7489		285.00	.0007	.17807	-.0486	-.1984	.8007
	200.00	-.0125	.17578	-.0008	.1045	1.7547		290.00	.0000	.17671	-.0442	-.1885	.7536
	205.00	-.0088	.17854	-.0014	.0400	1.7649		295.00	.0000	.17394	-.0380	-.1576	.7231
	210.00	-.0077	.17886	-.0026	.0077	1.7986		300.00	.00816	.17084	-.0290	-.1045	.7054
	215.00	-.0078	.17885	-.0062	-.0234	1.7883		305.00	.00850	.17026	-.0162	-.0392	.7147
	220.00	-.0079	.17855	-.0082	-.0856	1.7835		310.00	.00574	.17058	-.0050	-.0397	.7330
	225.00	-.0081	.17856	-.0116	-.1475	1.7795		315.00	.0033	.17272	-.0033	.0893	.7421
1211	-5.00	-.0816	.7186	-.0094	-.0187	.7230		320.00	.00562	.17459	-.0097	.1028	.7212
	-3.00	-.0482	.7183	-.0008	-.0105	.7198		325.00	.0108	.17585	-.0191	.1809	.7502
	-1.00	-.0014	.7226	-.0028	-.0012	.7227		330.00	.04308	.17179	-.0348	.2733	.7915
	.00	.0023	.7212	-.0004	.0023	.7212		335.00	.05509	.18585	-.0411	.3590	.8552
	1.00	.0200	.7166	-.0014	.0075	.7168		340.00	.2775	.19957	-.0644	.4274	.9811
	3.00	.0580	.7208	-.0033	.0202	.7228		345.00	.2154	.12120	-.0742	.4666	1.0418
	5.00	.0907	.7172	-.0035	.0279	.7224		350.00	.1733	.12373	-.0477	.4686	1.1582
	10.00	.1760	.7107	-.0060	.0499	.7305		355.00	.1332	.13368	-.0417	.4443	1.2679
	15.00	.2608	.7030	-.0087	.0699	.7665		360.00	.0953	.14244	-.0343	.3976	1.3711
	20.00	.3516	.6971	-.0143	.0920	.7754		365.00	.0721	.14653	-.0270	.3670	1.4204
	25.00	.4427	.6882	-.0218	.1104	.8108		370.00	.1561	.12947	-.0427	.4912	1.2081
	30.00	.2836	.7040	-.0096	.0785	.7549		375.00	.1290	.13765	-.0389	.46468	1.3020
	35.00	.3589	.6928	-.0144	.1003	.7738		380.00	.0934	.14364	-.0323	.4035	1.3817
	40.00	.4433	.6828	-.0187	.1132	.8061		385.00	.0550	.15393	-.0228	.43453	1.5011
	50.00	.5383	.6650	-.0265	.1337	.8451		390.00	.0296	.15056	-.0159	.2461	1.5666
	35.00	.6241	.6472	-.0343	.1400	.8882		395.00	.0065	.16113	-.0068	.1339	1.6058
	40.00	.7093	.6281	-.0432	.1397	.9370		400.00	.0013	.16226	-.0075	.0836	1.6205
	45.00	.7856	.6035	-.0525	.1288	.9622		405.00	-.0040	.16275	-.0009	.0324	1.6272
	50.00	.8478	.5769	-.0587	.1031	.10202		410.00	-.0053	.16291	-.0014	.0053	1.6291
	55.00	.8825	.5483	-.0640	.0571	.10374		415.00	-.0104	.16291	-.0043	.0180	1.6291
	60.00	.8952	.5059	-.0653	.0095	.10283		420.00	-.0197	.16275	-.0114	.1223	1.6230

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_M	C_A	C_B	C_L	C_D	Configuration	α , deg	C_M	C_A	C_B	C_L	C_D
1213	61.00	.9023	.5084	-.0486	-.0073	1.0357	2211	12.00	.5682	-.4999	-.0648	.1488	.7421
	65.00	.9050	.4856	-.0473	-.0576	1.0254		125.00	.5069	-.7333	-.0474	.3100	.8358
	70.00	.9015	.4385	-.0521	-.1038	.9971		130.00	.4169	-.9615	-.0346	.4839	.9503
	75.00	.8881	.3897	-.0588	-.1465	.9587		135.00	.3314	-.1.1739	-.0217	.5958	1.0644
	80.00	.8616	.3386	-.0657	-.1839	.9073		140.00	.2486	-.1.3462	-.0086	.6749	1.1910
	85.00	.8385	.2743	-.0746	-.2002	.8592		145.00	.1742	-.1.4755	-.0020	.7036	1.3086
	90.00	.8055	.2157	-.0803	-.2157	.8055		150.00	.1154	-.1.5675	-.0057	.6839	1.4152
	95.00	.7692	.1484	-.0857	-.2148	.7534		155.00	.0798	-.1.6384	-.0061	.6201	1.5186
	100.00	.7349	.0782	-.0926	-.2046	.7101		160.00	.0533	-.1.6930	-.0045	.5289	1.6091
	103.00	.7244	.0553	-.1057	-.1682	.7046							
	76.00	.8815	.3715	-.0532	-.1472	.9452							
	80.00	.8478	.3227	-.0700	-.1671	.9106							
	85.00	.8422	.2605	-.0792	-.1861	.8617							
	90.00	.8030	.2016	-.0448	-.2016	.8040							
	95.00	.7674	.1397	-.0877	-.2055	.7524							
	100.00	.7312	.0631	-.0954	-.1891	.7091							
	105.00	.7044	.0631	-.1198	-.1213	.6967							
	110.00	.6533	-.2219	-.1043	-.0150	.6899							
	115.00	.6780	-.5421	-.2.04	-.2.04	.8436							
	118.00	.6733	-.7411	-.2.331	-.2.331	.9424							
	121.00	.6236	-.8086	-.2.350	-.2.368	.9596							
	125.00	.5701	-.1.0021	-.2.157	-.4.939	1.0418							
	130.00	.4791	-.1.2139	-.1.743	-.6.219	1.1473							
	135.00	.3513	-.1.3208	-.0.924	-.6.856	1.1824							
	140.00	.2623	-.1.5030	-.0574	-.7.652	1.3200							
	145.00	.1648	-.1.5480	-.0023	-.7.529	1.3625							
	150.00	.1054	-.1.5879	-.0214	-.7.027	1.4279							
	155.00	.0701	-.1.6298	-.0271	-.6.253	1.5067							
	160.00	.0433	-.1.6627	-.0287	-.5.280	1.5772							
	162.70	.0258	-.1.6807	-.0266	-.4.752	1.6124							
	151.00	.0864	-.1.6353	-.0212	-.7.172	1.4722							
	155.00	.0624	-.1.6532	-.0266	-.6.421	1.5247							
	160.00	.0415	-.1.6799	-.024	-.5.424	1.6116							
	165.00	.0174	-.1.7319	-.0250	-.4.315	1.6774							
	170.00	-.0005	-.1.7532	-.0187	-.3.049	1.7265							
	175.00	-.0136	-.1.7705	-.0085	-.1.678	1.7626							
	177.00	-.0150	-.1.7783	-.0050	-.1.081	1.7751							
	179.00	-.0127	-.1.8029	-.0007	-.0.442	1.8024							
	180.00	-.0077	-.1.8060	-.0008	-.0.077	1.8060							
	181.00	0.0000	-.1.8030	-.0005	-.0.315	1.8227							
	183.00	-.0003	-.1.8001	-.0044	-.0.939	1.7976							
	185.00	-.0030	-.1.8032	-.0077	-.1.1542	1.7966							
2211	-5.00	-.0691	.7716	-.0023	-.0015	.7747	2213	61.00	.9459	.5064	-.0078	.0157	.1.0728
	-3.00	.0404	.7475	-.0010	-.0001	.7685		65.00	.9550	.4629	-.0098	.0159	.1.0611
	-1.00	-.0128	.7722	-.0000	-.0007	.7723		70.00	.9613	.4140	-.0115	.0162	.1.0449
	1.00	.0037	.7688	-.0012	-.0037	.7688		75.00	.9576	.3585	-.0184	.0185	.1.0178
	3.00	.0187	.7707	-.0012	-.0053	.7709		80.00	.9330	.3085	-.0240	.0148	.0724
	5.00	.0504	.7681	-.0029	-.0101	.7696		85.00	.9194	.2446	-.0371	.0139	.0372
	6.00	.0819	.7662	-.0026	-.0148	.7704		90.00	.9013	.2964	-.0463	.0122	.0964
	10.00	.1558	.7629	-.0028	-.0209	.7784		95.00	.8698	.1197	-.0528	.0150	.0561
	15.00	.2388	.7579	-.0061	-.0345	.7939		100.00	.8399	.0432	-.0635	.0183	.0196
	20.00	.3286	.7600	-.0089	-.0489	.8266		105.00	.8126	.0725	-.0877	.0103	.0403
	25.00	.4299	.7598	-.0164	-.0685	.8703		110.00	.8012	.2978	-.1.322	.0058	.0548
	16.00	.2579	.7646	-.0049	-.0371	.8061		115.00	.7747	.5445	-.1.712	.1.653	.9340
	20.00	.3356	.7556	-.0086	-.0570	.8248		120.00	.7255	.7427	-.2.068	.2.064	.0249
	25.00	.4341	.7543	-.0137	-.0764	.8679		125.00	.6516	.1045	-.2.121	.4.819	.1.329
	30.00	.5408	.7433	-.0186	-.0966	.9141		130.00	.5250	.1279	-.1.733	.6.930	.1.2249
	35.00	.6406	.7297	-.0210	-.1.062	.9651		135.00	.3902	.1367	-.0934	.6.909	.1.2427
	40.00	.7347	.7014	-.0244	-.1.119	1.0096		140.00	.2970	.1.5628	-.0630	.7.771	.1.3881
	45.00	.8144	.6617	-.0252	-.1.080	1.0438		145.00	.1899	.1.6133	-.0070	.7.698	.1.4304
	50.00	.8901	.6112	-.0317	-.1.039	1.0748		150.00	.1158	.1.6491	-.0086	.7.243	.1.4861
	55.00	.9301	.5570	-.0307	-.0772	1.0814		155.00	.0756	-.1.6963	-.0130	.6.681	.1.5694
	60.00	.9497	.5000	-.0288	-.0419	1.0725		160.00	.0679	-.1.7329	-.0136	.5.477	.1.6448
3211	61.00	.9506	.5045	-.0078	-.0197	.1.0760	3211	-5.00	-.0667	.8268	.0002	.0057	.8295
	65.00	.9585	.4616	-.0087	-.0133	.0.6338		-3.00	-.0369	.8220	-.0006	.0062	.8228
	70.00	.9630	.4079	-.0120	-.0539	.0.4444		-1.00	-.0115	.8241	-.0001	.0029	.8242
	75.00	.9594	.3567	-.0150	-.0962	.1.0190		0.00	-.0024	.8244	-.0003	.0024	.8244
	80.00	.9297	.3117	-.0200	-.1.056	.9697		1.00	.0200	.8211	-.0017	.0057	.8213
	85.00	.9047	.2588	-.0225	-.1.788	.9259		3.00	.0644	.8211	-.0025	.0033	.8224
	90.00	.8852	.1994	-.0258	-.1.994	.8852		5.00	.0765	.8191	-.0032	.0048	.8227
	95.00	.8546	.1411	-.0272	-.2.153	.8410		10.00	.1461	.8213	-.0044	.0013	.8342
	100.00	.8249	.0765	-.0280	-.2.185	.7991		15.00	.2251	.8175	-.0070	.0058	.8479
	105.00	.8051	.0268	-.0291	-.2.072	.7785		20.00	.3122	.8239	-.0088	.0116	.8810
	110.00	.9344	.5517	-.0188	-.1.104	1.0112		25.00	.4249	.8266	-.0170	.0358	.9288
	80.00	.9393	.3055	-.0236	-.1.378	.9781							
	85.00	.9162	.2520	-.0272	-.1.711	.9347							
	90.00	.8914	.1932	-.0292	-.1.932	.8914							
	95.00	.8579	.1380	-.0292	-.2.123	.8426							
	100.00	.8186	.0640	-.0321	-.2.051	.7951							
	105.00	.7808	-.0337	-.0354	-.1.695	.7629							
	110.00	.7403	-.1.797	-.0378	-.0843	.7572							
	115.00	.6865	-.3566	-.0366	.0331	.7729							
	118.00	.6482	-.4798	-.0365	.1.193	.7976							

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Config-	α , deg	c_N	c_A	c_m	c_L	c_D	Config-	α , deg	c_N	c_A	c_m	c_L	c_D
3211	16.00	.2451	.8214	-.0082	.0392	.8572	3213	120.00	-.7424	-.7994	-.2106	.3211	1.0426
	20.00	.3201	.8210	-.0103	.0230	.8810		125.00	.6580	-.0666	-.2032	.4963	1.1508
	25.00	.4278	.8224	-.0139	.0401	.9261		130.00	.5439	-.12689	-.1641	.6224	1.2322
	30.00	.5382	.8142	-.0144	.0590	.9742		135.00	.4255	-.14425	-.1155	.7191	1.3209
	35.00	.6458	.8035	-.0136	.0681	1.0286		140.00	.3140	-.15525	-.0598	.7574	1.3911
	40.00	.7483	.7713	-.0153	.0755	1.0741		145.00	.2015	-.15991	-.0053	.7521	1.4255
	45.00	.8229	.7250	-.0134	.0763	1.1017		150.00	.1220	-.1607	-.0683	.7140	1.4824
	50.00	.9021	.6598	-.0136	.0783	1.1119		155.00	.0813	-.16952	-.0126	.6427	1.5708
	55.00	.9487	.5877	-.0119	.0628	1.1142		160.00	.0537	-.17298	-.0136	.5411	1.6439
	60.00	.9689	.5054	-.0092	.0468	1.0918							
	61.00	.9686	.5045	-.0179	.0268	1.0918							
	65.00	.9797	.4514	-.0125	.0049	1.0787							
	70.00	.9822	.4006	-.0101	-.0405	1.0600							
	75.00	.9803	.3437	-.0051	-.0783	1.0359							
	80.00	.9652	.2938	-.0001	-.1217	1.0015							
	85.00	.9501	.2432	-.0026	-.1595	.9677							
	90.00	.9317	.1896	-.0045	-.1896	.9317							
	95.00	.9085	.1320	-.0058	-.2107	.8935							
	100.00	.8758	.0680	-.0072	-.2191	.8507							
	103.00	.8558	.0113	-.0092	-.2032	.8314							
3211	76.00	.9754	.3288	.0022	-.0830	1.0259	1311	-5.00	-.0d58	.5842	-.0077	-.0346	.5895
	80.00	.9702	.2861	-.0013	-.1133	1.0052		-4.00	-.0498	.5822	-.0053	-.0192	.5840
	85.00	.9519	.2352	-.0052	-.1513	.9688		-1.00	-.0113	.5829	-.0030	-.0011	.5830
	90.00	.9319	.1779	-.0070	-.1779	.9319			.00	.0074	.5844		
	95.00	.9238	.1270	-.0070	-.2053	.8893		1.00	.0277	.5828	-.0027	.0195	.5832
	100.00	.8708	.0516	-.0098	-.2050	.8481		2.00	.0629	.5898	.0020	.0322	.5873
	105.00	.8291	-.0342	-.0129	-.1816	.8098		5.00	.0999	.5799	.0036	.0490	.5864
	110.00	.7888	-.1779	-.0165	-.1026	.8020		10.00	.1215	.5811	.0099	.0877	.6056
	115.00	.7293	-.3527	-.0170	-.0115	.8101		15.00	.2968	.5809	.0114	.1364	.6379
	118.00	.6889	-.4740	-.0182	-.0951	.8368		20.00	.4565	.5862	.0127	.1815	.6998
	120.00	.6212	-.5032	-.0358	-.1252	.7896		25.00	.5322	.5865	.0077	.2344	.7565
	125.00	.5357	-.7448	-.0392	-.3028	.8660		30.00	.5215	.5830	.0147	.1656	.6586
	130.00	.4452	-.9593	-.0180	-.4487	.9576		35.00	.4122	.5857	.0158	.1850	.6946
	135.00	.3615	-.11622	-.0066	-.5662	1.0774		40.00	.3135	.5838	.0122	.2395	.7558
	140.00	.2799	-.13332	-.0042	-.6426	1.2012		45.00	.2150	.5814	.0086	.2819	.8341
	145.00	.1977	-.14582	-.0111	-.6745	1.3079		50.00	.1079	.5796	.0035	.3136	.9267
	150.00	.1332	-.15606	-.0117	-.6649	1.4181		55.00	.0973	.5736	-.0014	.3263	1.0226
	155.00	.0939	-.16290	-.0116	-.6033	1.5161		60.00	.0127	.5617	-.0067	.3189	1.1133
	160.00	.0664	-.16831	-.0109	-.5133	1.6043		65.00	.0973	.5479	-.0112	.2854	1.1925
3212	61.00	.9688	.5076	.0137	.0257	1.0934	1311	60.00	.1365	.5055	-.0138	.1555	1.2803
	65.00	.9830	.4471	.0119	.0102	1.0799		65.00	.1491	.4930	.0113	.1443	1.2773
	70.00	.9923	.3903	.0116	-.0274	1.0660		70.00	.1421	.3916	-.0099	.1020	1.2097
	75.00	.9967	.3278	.0082	-.0586	1.0175		75.00	.1465	.313C	-.0152	.1576	1.1774
	80.00	.9717	.2817	.0082	-.1087	1.0598		80.00	.1072	.2529	-.0300	.2155	1.1276
	85.00	.9632	.2195	.0067	-.1347	.9786		85.00	.1250	.1945	-.0350	.2520	1.0732
	90.00	.9480	.1603	.0084	-.1603	.9480		90.00	.0976	.1223	-.0410	.2900	.9405
	95.00	.9328	.0894	.0125	-.1704	.9215		100.00	.0919	.0222	-.0466	.2593	.8821
	100.00	.9158	.0019	.0170	-.1609	.9016		105.00	.0840	.1300	-.0515	.1733	.8564
	103.00	.9005	-.0614	.0232	-.1428	.8912		110.00	.0792	.3061	-.0499	.0577	.8479
	110.00	.9785	.3191	.0048	-.0729	1.0266		115.00	.0676	.2593	-.0502	.0254	.8593
	120.00	.9736	.2724	.0049	-.0993	1.0059		120.00	.0708	.1318	-.0408	.3023	.9552
	125.00	.9632	.2153	.0052	-.1305	.9783		125.00	.0976	.2883	-.0166		
	130.00	.9480	.1492	.0044	-.1492	.9800		130.00	.0544	.3916	-.0099		
	135.00	.9294	.0846	.0087	-.1653	.9185		135.00	.1321	.3597	-.0152		
	140.00	.9029	.0011	.0141	-.1579	.8820		140.00	.1045	.313C	-.0240		
	145.00	.8807	-.1039	.0218	-.1275	.8776		145.00	.0732	.2529	-.0300		
	150.00	.8520	-.2237	.0314	-.0812	.8771		150.00	.1250	.1945	-.0350		
	155.00	.8021	-.3640	.0401	-.0991	.8808		155.00	.1250	.3263	-.0215		
	160.00	.7589	-.4367	.0436	-.0293	.8751		160.00	.1250	.1555	-.0250		
3213	61.00	.9720	.5062	.0137	.0285	1.0955	1121	120.00	.6276	.6666	-.0332	.1844	.8953
	65.00	.9895	.4514	.0128	-.0091	1.0876		125.00	.5244	.8793	-.0216	.3365	.9669
	70.00	.9923	.3965	.0099	-.0332	1.0681		130.00	.4249	.10841	-.0072	.4661	1.0671
	75.00	.9953	.3435	.0041	-.0742	1.0503		135.00	.3263	.12543	-.0076	.5559	1.1709
	80.00	.9751	.2860	-.0067	-.1124	1.0100		140.00	.2312	.13830	-.0176	.6043	1.2661
	85.00	.9633	.2285	-.0162	-.1436	.9795		145.00	.1570	.14820	-.0218	.6050	1.3419
	90.00	.9499	.1710	-.0241	-.1710	.9499		150.00	.0790	.1184	-.0225	.5572	1.4912
	95.00	.9234	.1164	-.0299	-.1965	.9098		155.00	.0790	.16076	-.0230	.4756	1.5376
	100.00	.8985	.0435	-.0049	-.1988	.8773		160.00	.0790	.16384	-.0233	.4276	1.5829
	103.00	.8899	-.0246	-.0563	-.1762	.8726		165.00	.0790	.14242	-.0233		
	110.00	.9818	.3583	.0009	-.0869	1.0335		170.00	.0790	.17466	-.0018		
	115.00	.9752	.2886	-.0073	-.1149	1.0105		175.00	.0790	.17464	-.0076		
	120.00	.9650	.2277	-.0184	-.1427	.9811		180.00	.0790	.17465	-.0022		
	125.00	.9483	.1689	-.0258	-.1689	.9883		183.00	.0790	.17464	-.0076		
	130.00	.9217	.1080	-.0327	-.1879	.9088		185.00	.0790	.17522	-.0124		
	135.00	.8936	.0428	-.0412	-.1973	.8726							
	140.00	.8685	-.0790	-.0673	-.1485	.8593							
	145.00	.8554	-.2908	-.1096	-.0193	.9033							
	150.00	.8273	-.5545	-.1571	-.1529	.9841							
	155.00	.8145	-.7471	-.1900	-.2773	1.0699							

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_H	C_A	C_M	C_L	C_D	Configuration	α , deg	C_H	C_A	C_M	C_L	C_D
1121	16.00	.2549	.8135	-.0494	.0208	.8523	1122	152.00	.0821	-.1.3592	.0485	.5439	1.2484
	20.00	.3127	.7970	-.0608	.0212	.8558		155.00	.0732	-.1.4021	.0459	.5263	1.3016
	25.00	.3729	.7754	-.0722	.0103	.8604		160.00	.0478	-.1.4892	.0366	.4644	1.4157
	30.00	.4359	.7531	-.0843	.0009	.8702		165.00	.0286	-.1.5635	.0263	.3771	1.5176
	35.00	.4858	.7225	-.0938	-.0165	.8704		170.00	.0172	-.1.5959	.0169	.2640	1.5731
	40.00	.5315	.6907	-.1026	-.0368	.8707		175.00	.0022	-.1.6224	.0060	.1412	1.6162
	45.00	.5627	.6566	-.1093	-.0664	.8622		177.00	-.0037	-.1.6224	.0018	.0886	1.6200
	50.00	.5781	.6270	-.1140	-.1087	.8458		179.00	-.0065	-.1.6759	-.0072	.0350	1.6356
	55.00	.5792	.5760	-.1143	-.1396	.8049		180.00	-.0041	-.1.6359	-.0038	.0041	1.6359
	60.00	.5776	.5148	-.1145	-.1570	.7576		181.00	-.0080	-.1.6392	-.0072	-.0206	1.6391
	61.00	.5847	.5338	-.0965	-.1834	.7702		183.00	-.0094	-.1.6372	-.0113	-.0763	1.6355
	65.00	.5788	.4942	-.0964	-.2033	.7335		185.00	-.0198	-.1.6198	-.0120	-.1215	1.6153
	70.00	.5580	.4401	-.0955	-.2228	.6748							
	75.00	.5353	.3877	-.0928	-.2360	.6174							
	80.00	.5098	.3329	-.0888	-.2393	.5599							
	85.00	.4822	.2748	-.0847	-.2318	.5044							
	90.00	.4521	.2146	-.0786	-.2146	.4521							
	95.00	.4250	.1526	-.0731	-.1890	.4101							
	100.00	.3951	.0665	-.0681	-.1341	.3776							
	103.00	.3802	.0064	-.0665	-.0917	.3691							
	80.00	.5118	.3046	-.0842	-.2111	.5569							
	85.00	.4858	.2507	-.0795	-.2074	.5059							
	90.00	.4539	.1976	-.0738	-.1976	.4539							
	95.00	.4248	.1342	-.0681	-.1707	.4115							
	100.00	.3965	.0629	-.0634	-.1308	.3796							
	105.00	.3644	.0426	-.0611	-.0532	.3630							
	110.00	.3357	-.1830	-.0570	.0579	.3762							
	115.00	.3031	-.3556	-.0504	.1942	.4250							
	120.00	.2631	-.5449	-.0408	.3403	.5003							
	121.00	.2555	-.5701	-.0409	.3571	.5126							
	125.00	.2221	-.7430	-.0266	.4812	.6081							
	130.00	.1781	-.9630	-.0092	.6232	.7554							
	135.00	.1297	-.1.1604	.0029	.7288	.9122							
	140.00	.0949	-.1.3234	.0161	.7780	1.0748							
	145.00	.0629	-.1.4370	.0221	.7727	1.2132							
	150.00	.0470	-.1.5242	.0297	.7214	1.3435							
	155.00	.0309	-.1.5958	.0307	.6464	1.4594							
	160.00	.0155	-.1.6505	.0295	.5499	1.5563							
	165.00	.0047	-.1.6939	.0260	.4339	1.6374							
	153.00	.0237	-.1.6043	.0244	.7072	1.4402							
	155.00	.0175	-.1.6292	.0257	.6726	1.4840							
	160.00	.0048	-.1.6836	.0243	.5713	1.5837							
	165.00	-.0068	-.1.7344	.0181	.4555	1.6735							
	170.00	-.0147	-.1.7507	.0097	.3185	1.7215							
	175.00	-.0125	-.1.7684	.0035	.1666	1.7606							
	177.00	-.0101	-.1.7686	.0014	.1027	1.7657							
	179.00	-.0128	-.1.7732	-.0037	.0437	1.7727							
	180.00	-.0091	-.1.7980	-.0055	.0091	1.7980							
	181.00	-.0680	-.1.8011	-.0068	-.0234	1.8009							
	183.00	-.0081	-.1.7980	-.0091	-.0860	1.7959							
	185.00	-.0082	-.1.7687	-.0129	-.1460	1.7627							
	1122	61.00	.5865	.5289	-.0960	-.1783	.7694						
	65.00	.5791	.4861	-.0953	-.1959	.7302							
	70.00	.5617	.4292	-.0922	-.2112	.6746							
	75.00	.5387	.3733	-.0876	-.2212	.6169							
	80.00	.5193	.3125	-.0809	-.2176	.5657							
	85.00	.4979	.2494	-.0731	-.2051	.5177							
	90.00	.4749	.1802	-.0635	-.1802	.4749							
	95.00	.4548	.0987	-.0521	-.1379	.4445							
	100.00	.4319	.0034	-.0356	-.0783	.4247							
	105.00	.4116	-.1011	-.0202	-.0088	.4238							
	110.00	.3919	-.2201	-.0032	-.0728	.4436							
	115.00	.3659	-.3486	.0135	.1613	.4789							
	120.00	.3290	-.4812	.0283	.2522	.5255							
	121.00	.3221	-.4992	.0312	.2620	.5332							
	125.00	.2918	-.6085	.0465	.3311	.5880							
	130.00	.2426	-.7571	.0570	.4241	.6725							
	135.00	.1991	-.8943	.0617	.4916	.7732							
	140.00	.1661	-.1.0220	.0654	.5297	.8897							
	145.00	.1341	-.1.1618	.0626	.5451	1.0122							
	150.00	.1080	-.1.2581	.0579	.5356	1.1435							
	155.00	.0854	-.1.3559	.0532	.4956	1.2650							
	160.00	.0603	-.1.4481	.0441	.4386	1.3814							
	165.00	.0376	-.1.5190	.0335	.3568	1.4769							
	2121	-5.00	-.0570	.8466	.0060	.0170							
	-3.00	-.0265	.8450	.0010	.0177								
	-1.00	-.0037	.8525	-.0017	.0112								
	0.00	-.0089	.8486	-.0025	.0089								
	1.00	.0214	.8481	-.0038	.0066								
	3.00	.0472	.8434	-.0076	.0030								
	5.00	.0825	.8421	-.0137	.0088								
	10.00	.1995	.8397	-.0221	.0114								
	15.00	.2169	.8322	-.0319	.0059								
	20.00	.2863	.8085	-.0517	.0146								
	25.00	.3095	.816	-.0667	.0235								
	25.00	.3663	.8276	-.0555	.0178								
	30.00	.3311	.8245	-.0339	.0052								
	40.00	.5543	.7402	-.0741	.0152								
	45.00	.5948	.6913	-.0774	.0162								
	50.00	.6187	.6308	-.0790	.0155								
	55.00	.6225	.5709	-.0788	.0106								
	60.00	.6303	.5046	-.0788	.0106								
	61.00	.6355	.5196	-.0693	.0146								
	65.00	.6383	.4726	-.0690	.0158								
	70.00	.6288	.4143	-.0692	.0174								
	75.00	.6161	.3608	-.0694	.0180								
	80.00	.5924	.3079	-.0676	.0203								
	85.00	.5725	.2504	-.0659	.0195								
	90.00	.5520	.1979	-.0628	.0179								
	95.00	.5245	.1380	-.0592	.0183								
	100.00	.4991	.0661	-.0569	.0151								
	103.00	.4790	-.0023	-.0567	-.0105								

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D		
2121	77.00	.6010	.3350	-.0687	-.1912	.6610	3121	16.00	.2163	.8553	-.0293	-.0279	.8818		
	80.00	.5872	.3030	-.0681	-.1964	.6309		20.00	.2754	.8543	-.0360	-.0334	.8970		
	85.00	.5644	.2484	-.0657	-.1983	.5840		25.00	.3598	.8570	-.0467	-.0361	.9288		
	90.00	.5440	.1948	-.0625	-.1948	.5440		30.00	.4369	.8511	-.0522	-.0472	.9556		
	95.00	.5158	.1388	-.0586	-.1833	.5017		35.00	.5112	.8376	-.0681	-.0617	.9793		
	100.00	.4892	.0703	-.0561	-.1541	.4696		40.00	.5681	.8032	-.0697	-.0811	.9805		
	105.00	.4604	-.0131	-.0553	-.0872	.4533		45.00	.6100	.7469	-.0611	-.0968	.9594		
	110.00	.4261	-.1856	-.0525	.0287	.1639		50.00	.6267	.6742	-.0624	-.1072	.9211		
	115.00	.3889	-.3699	-.0467	.1708	.5088		55.00	.6417	.5906	-.0603	-.1157	.8644		
	118.00	.3599	-.4862	-.0417	.2603	.5461		60.00	.6523	.5095	-.0642	-.1150	.8197		
	120.00	.3226	-.5504	-.0564	.3154	.5546		61.00	.6574	.5209	-.0478	-.1369	.8275		
	125.00	.2649	-.7797	-.0457	.4868	.6642		65.00	.6577	.4635	-.0491	-.1421	.7920		
	130.00	.2055	-.0010	-.0359	.6347	.8008		70.00	.6355	.3995	-.0517	-.1500	.7338		
	135.00	.1571	-.1954	-.0245	.7342	.9564		75.00	.6340	.3426	-.0516	-.1668	.7011		
	140.00	.1061	-.3659	-.0140	.7967	1.1145		80.00	.6251	.2892	-.0503	-.1763	.6658		
	145.00	.0686	-.4906	-.0056	.7988	1.2603		85.00	.6108	.2372	-.0503	-.1831	.6292		
	150.00	.0460	-.5816	-.0007	.7510	1.3927		90.00	.5912	.1813	-.0485	-.1010	.5912		
	155.00	.0264	-.6485	-.0007	.6728	1.5053		95.00	.5727	.1260	-.0458	-.1754	.5595		
	160.00	.0091	-1.7053	-.0020	.5746	1.6056		100.00	.5519	.0611	-.0443	-.1560	.5329		
								105.00	.5327	-.0074	-.0443	-.1126	.5207		
2122	61.00	.6295	.5203	-.0679	-.1499	.8028		110.00	.6369	.1182	-.0516	-.1679	.6862		
	65.00	.6368	.4498	-.0687	-.1567	.7755		115.00	.6234	.2836	-.0515	-.1710	.6631		
	70.00	.6269	.4986	-.0670	.1696	.7288		120.00	.6002	.2322	-.0506	-.1783	.6241		
	75.00	.6136	.3493	-.0643	.1706	.6831		125.00	.5995	.1803	-.0495	-.1808	.5895		
	80.00	.5964	.2947	-.0601	.1866	.6385		130.00	.5640	.1282	-.0456	-.1770	.5526		
	85.00	.5804	.2333	-.0549	.1818	.5987		135.00	.5426	.03626	-.0440	-.1558	.5235		
	90.00	.5644	.1663	-.0481	.1663	.5646		140.00	.5127	-.0392	-.0445	-.0947	.5054		
	95.00	.5474	.0925	-.0396	.1598	.5372		145.00	.4769	-.1888	-.0423	.C143	.5127		
	100.00	.5324	.0036	-.0276	.0960	.5237		150.00	.4348	-.3683	-.0379	.1500	.5498		
	105.00	.5234	-.0563	-.0198	.0628	.5227		155.00	.4031	-.4868	-.0347	.2206	.5844		
								160.00	.3703	-.3480	-.0303	.0903	.5669		
	77.00	.6069	.3257	-.0629	-.1809	.6646		123.00	.3480	.5403	-.0494	.2935	.5723		
	80.00	.5961	.2893	-.0607	.1814	.6372		125.00	.2968	.7668	-.0405	.4613	.6780		
	85.00	.5793	.2269	-.0551	.1755	.5969		130.00	.2313	.9901	-.0300	.6098	.8136		
	90.00	.5624	.1659	-.0482	.1659	.5624		135.00	.1770	-.1876	-.0177	.7146	.9650		
	95.00	.5438	.0928	-.0396	.1398	.5336		140.00	.1236	.1354	-.0080	.7753	1.1162		
	100.00	.5266	.0063	-.0277	.0976	.5175		145.00	.0904	.14765	-.0023	.7810	1.2556		
	105.00	.5097	-.1000	-.0134	.0353	.5182		150.00	.0730	.15705	-.0018	.7399	1.3866		
	110.00	.4906	-.2257	-.0027	.0443	.5382		155.00	.0359	.16395	-.0026	.6604	1.5011		
	115.00	.4562	.3549	-.0185	.1288	.5635		160.00	.0138	.16954	-.0023	.5669	.51979		
	118.00	.4251	.4439	-.0278	.1923	.5837									
	120.00	.3924	.4761	-.0156	.2161	.5779									
	125.00	.3313	.6388	-.0256	.3333	.6378									
	130.00	.2748	.7813	-.0345	.4219	.7127									
	135.00	.2235	.9235	-.0387	.4950	.8110									
	140.00	.1789	-.1057	-.0407	.5429	.9252									
	145.00	.1409	-.1873	-.0385	.5656	1.0534									
	150.00	.1107	-.3057	-.0325	.5570	1.1862									
	155.00	.0816	-.4100	-.0246	.5219	1.3124									
	160.00	.0523	-.1494	-.0146	.4620	1.4222									
2123	61.00	.6333	.5229	-.0700	-.1503	.8074		123.00	.6346	.5193	-.0498	-.1446	.8103		
	65.00	.6361	.4744	-.0698	-.1612	.7770		125.00	.6392	.4572	-.0503	-.1443	.7725		
	70.00	.6291	.4154	-.0715	-.1751	.7333		130.00	.6365	.3907	-.0493	-.1494	.7317		
	75.00	.6200	.3563	-.0743	-.1837	.6911		135.00	.6339	.3293	-.0469	-.1540	.6975		
	80.00	.6004	.3016	-.0771	-.1927	.6437		140.00	.6333	.2727	-.0432	-.1586	.6711		
	85.00	.5821	.2426	-.0795	-.1910	.6010		145.00	.6242	.2157	-.0392	-.1605	.6466		
	90.00	.5608	.1860	-.0805	-.1860	.5608		150.00	.6092	.1502	-.0338	-.1502	.6092		
	95.00	.5381	.1259	-.0816	-.1723	.5251		155.00	.5975	.0811	-.0367	-.1329	.5881		
	100.00	.5194	.0416	-.0918	-.1312	.5043		160.00	.5870	-.0038	-.0158	-.0982	.5788		
	103.00	.5158	-.0457	-.1070	-.0715	.5129			123.00	.5791	-.0623	-.0090	-.0696	.5783	
	77.00	.6107	.3293	-.0754	-.1835	.6691									
	80.00	.5994	.2964	-.0770	-.1878	.6418									
	85.00	.5802	.2379	-.0791	-.1844	.5987									
	90.00	.5583	.1795	-.0800	-.1795	.5583									
	95.00	.5327	.1246	-.0807	-.1705	.5198									
	100.00	.5133	.0457	-.0888	-.1341	.4976									
	105.00	.5060	-.1065	-.1161	-.0281	.5164									
	110.00	.5114	-.3370	-.1577	-.1418	.5959									
	115.00	.4895	.5576	-.1743	-.2985	.6793									
	118.00	.4899	-.7538	-.2067	-.4356	.7865									
	120.00	.4523	-.8329	-.2159	-.4951	.8082									
	125.00	.3926	-.1098	-.0022	.6683	.9473									
	130.00	.3144	-.1297	-.1639	.7897	1.0730									
	135.00	.2302	-.14746	-.1239	.8799	1.2055									
	140.00	.1474	-.15857	-.0637	.9046	1.3094									
	145.00	.0731	-.16262	-.0097	.8729	1.3740									
	150.00	.0369	-.16660	-.0017	.8010	1.4613									
	155.00	.0187	-.17038	-.0065	.7032	1.5521									
	160.00	.0015	-.17369	-.0059	.5927	1.6326									
3121	-5.00	-.0557	.8740	.0052	.0207	.8756		123.00	.6389	.5213	-.0501	-.1467	.8118		
	-3.00	-.0268	.8697	.0010	.0187	.8699		125.00	.6439	.4643	-.0510	-.1487	.7798		
	-1.00	-.0048	.8732	-.0015	.0114	.8732		130.00	.6423	.3946	-.0539	-.1511	.7386		
	.03	.0089	.8745	-.0025	.0089	.8745		135.00	.6386	.3342	-.0575	-.1575	.7033		
	1.00	.0217	.8679	-.0049	.0066	.8682		140.00	.6396	.2805	-.0601	-.1649	.6786		
	3.00	.0532	.8718	-.0102	.0075	.8734		145.00	.6269	.2230	-.0637	-.1676	.6439		
	5.00	.0753	.8693	-.0121	.0008	.8726		150.00	.6087	.1670	-.0662	-.1670	.6087		
	10.00	.1395	.8642	-.0205	.0127	.8753		155.00	.5910	.1077	-.0689	-.1588	.5794		
	15.00	.2092	.8648	-.0302	.0217	.8894		160.00	.5668	.0409	-.0764	-.1378	.5513		
	20.00	.2827	.8713	-.0396	.0323	.9155			123.00	.5695	.0518	-.0788	-.1313	.5612	
	25.00	.3698	.8717	-.0512	-.0332	.9463				125.00	.6433	.3123	-.0583	-.1596	.6971
										130.00	.6369	.2778	-.0606	-.1430	.6754
										135.00	.6227	.2204	-.0642	-.1653	.6395
										140.00	.6061	.1697	-.0661	-.1697	.6061
										145.00	.5837	.1118	-.0682	-.1623	.5718
										150.00	.5668	.0409	-.0704	-.1378	.5513
										155.00	.5571	.1047	-.1076	-.0431	.5652
										160.00	.5606	.3364	-.1469	.1244	.6419
										110.00	.5377	.5605	-.1684	.2808	.7242
										115.00	.5353	.7488	-.1980	.4099	.8241

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
3123	120.00	.4336	-.8322	-.2104	.4789	.8349	1222	76.00	.8397	.3069	-.0653	-.1723	.9084
	125.00	.4229	-.1093	-.1959	.6513	.9723		80.00	.8235	.3411	-.0658	-.1929	.8792
	130.00	.3421	-.1302	-.1595	.7776	1.0991		85.00	.7952	.2864	-.0649	-.2160	.8172
	135.00	.2586	-.1672	-.1149	.8582	1.2240		90.00	.7656	.2250	-.0609	-.2250	.7656
	140.00	.1663	-.1588	-.0603	.8935	1.3236		95.00	.7356	.1461	-.0552	-.2096	.7203
	145.00	.0873	-.1631	-.0079	.8643	1.3865		100.00	.7094	.0549	-.0465	-.1773	.6891
	150.00	.0464	-.1666	.0057	.7931	1.4665		105.00	.6731	-.0535	-.0376	-.1225	.6640
	155.00	.0293	-.1706	.0101	.6944	1.5587		110.00	.6433	-.1931	-.0217	-.0385	.6705
	160.00	.0085	-.1744	.0087	.5885	1.6418		115.00	.5924	-.1292	-.0091	.0480	.6760
	118.00							118.00	.5582	-.4169	.0014	.1060	.6886
1221	-5.00	-.0745	.6238	-.0023	-.0198	.6279	121	74.00	.4993	-.4448	-.0011	.1241	.6571
	-3.00	-.0428	.6246	-.0016	-.0100	.6259		78.00	.4427	-.5732	.0209	.2155	.6913
	-1.00	-.0062	.6249	-.0074	.0047	.6249		82.00	.3683	-.7144	.0393	.3106	.7413
	1.00	.0127	.6273	-.0052	.0127	.6275		86.00	.2968	-.8556	.0437	.3951	.8149
	3.00	.0252	.6268	-.0042	.0143	.6271		90.00	.2302	-.9894	.0490	.4597	.9059
	5.00	.0666	.6254	-.0079	.0338	.6290		94.00	.1819	-.1186	.0510	.4927	1.0208
	10.00	.1836	.6221	-.0120	.0728	.6446		98.00	.1503	-.1238	.0500	.4889	1.1474
	15.00	.2735	.6206	-.0171	.1036	.6703		102.00	.1179	-.3319	.0454	.4560	1.2569
	20.00	.3757	.6321	-.0282	.1368	.7225		106.00	.0867	-.4256	.0378	.4061	1.3693
	25.00	.4759	.6340	-.0389	.1634	.7757		110.00	.0695	-.4449	.0331	.3492	1.4193
1223	16.00	.3001	.6197	-.0187	.1177	.6784	121.00	121.00	.4993	-.4448	-.0011	.1241	.6571
	20.00	.3785	.6169	-.0250	.1447	.7071		125.00	.4427	-.5732	.0209	.2155	.6913
	25.00	.4761	.6176	-.0332	.1705	.7699		129.00	.3683	-.7144	.0393	.3106	.7413
	30.00	.5743	.6151	-.0417	.1898	.8199		133.00	.2968	-.8556	.0437	.3951	.8149
	35.00	.6676	.6110	-.0520	.1964	.8834		137.00	.1819	-.1186	.0510	.4927	1.0208
	40.00	.7519	.6028	-.0623	.1805	.9451		141.00	.1503	-.1238	.0500	.4889	1.1474
	45.00	.8167	.5971	-.0680	.1624	.9926		145.00	.1179	-.3319	.0454	.4560	1.2569
	50.00	.8540	.5643	-.0716	.1166	1.0169		149.00	.0867	-.4256	.0378	.4061	1.3693
	55.00	.8704	.5421	-.0744	.0551	1.0239		153.00	.0695	-.4449	.0331	.3492	1.4193
	60.00	.8767	.5104	-.0774	-.0036	1.0144		157.00	.0426	-.6261	.0040	.0825	1.6240
	61.00	.8342	.5194	-.0598	-.0256	1.0251		161.00	.0144	-.6453	-.0015	.0312	1.6351
	65.00	.8798	.4922	-.0622	-.0743	1.0054		165.00	.0027	-.6453	-.0015	.0245	1.6413
	70.00	.8702	.4526	-.0667	-.1277	.9725		169.00	.0041	-.6387	-.0039	.0214	1.6351
	75.00	.8557	.4059	-.0708	-.1706	.9316		173.00	.0043	-.6371	-.0076	.0814	1.6351
	80.00	.8205	.3658	-.0736	-.2177	.8715		177.00	.0026	-.6261	.0040	.0825	1.6240
	85.00	.7932	.3184	-.0742	-.2481	.8180		181.00	.0027	-.6151	.0040	.0825	1.6240
	90.00	.7599	.2633	-.0747	-.2633	.7599		185.00	.0041	-.6040	-.0042	.0245	1.6413
	95.00	.7265	.2055	-.0736	-.2680	.7058		189.00	.0043	-.5971	-.0132	.1295	1.6337
	100.00	.6857	.1343	-.0726	-.2514	.6520		193.00	.0043	-.5878	-.0132	.1295	1.6337
	103.00	.6597	.0734	-.0727	-.2199	.6263		197.00	.0043	-.5787	-.0132	.1295	1.6337
1222	76.00	.8478	.3953	-.0612	-.1785	.9182	1223	14.00	.2834	.6236	-.0111	.1005	.6775
	80.00	.8247	.3547	-.0648	-.2061	.8738		20.00	.3738	.6222	-.0208	.1385	.7125
	85.00	.7893	.3080	-.0625	-.2380	.8131		25.00	.4749	.6210	-.0309	.1680	.7635
	90.00	.7542	.2520	-.0724	-.2520	.7542		30.00	.5725	.6191	-.0402	.1862	.8225
	95.00	.7237	.1907	-.0721	-.2531	.7043		35.00	.6697	.6161	-.0524	.1952	.8838
	100.00	.6557	.1260	-.0729	-.2355	.6464		40.00	.7493	.6084	-.0606	.1829	.9477
	105.00	.6292	.0881	-.0735	-.1706	.6057		45.00	.8151	.5907	-.0668	.1587	.9911
	110.00	.5967	.1586	-.0733	-.0517	.6055		50.00	.8582	.5710	-.0733	.1142	1.0244
	115.00	.5929	.3447	-.0688	-.0887	.6253		55.00	.8734	.5499	-.0745	.0505	1.0308
	118.00	.4883	.4647	-.0641	.1811	.6493		60.00	.8798	.5108	-.0785	.0021	1.0171
1222	121.00	.4325	.5051	-.0654	.2102	.6308	1223	61.00	.8762	.5154	-.0554	-.0260	1.0162
	125.00	.3809	.6855	-.0490	.3432	.7053		65.00	.8750	.4899	-.0579	-.0742	1.0000
	130.00	.2999	.9031	-.0247	.4990	.8102		70.00	.8672	.4508	-.0627	.1270	.9691
	135.00	.2264	.1128	-.0115	.6268	.9470		75.00	.8521	.3983	-.0719	.1642	.9262
	140.00	.1661	.1275	.0054	.6924	1.0836		80.00	.8273	.3592	-.0770	.2107	.8772
	145.00	.1089	.1409	.0149	.7143	1.2100		85.00	.7993	.3019	-.0849	.2311	.8226
	150.00	.0751	.14734	.0206	.6817	1.3309		90.00	.7689	.2486	-.0899	.2486	.7760
	155.00	.0551	.15576	.0231	.6084	1.4350		95.00	.7346	.1918	-.0924	.2551	.7151
	160.00	.0339	.16106	.0230	.5190	1.5251		100.00	.7030	.1062	-.1043	.2267	.6739
	163.00	.0221	.16374	.0206	.4576	1.5723		103.00	.6867	.0265	-.1203	.1803	.6631
1222	171.00	.0662	.15648	.0181	.7007	1.4007	1223	104.00	.8501	.3867	-.0778	.1695	.9185
	175.00	.0553	.16146	.0247	.6323	1.4867		108.00	.8303	.3423	-.0838	.1929	.8771
	180.00	.0415	.16718	.0264	.5528	1.5852		113.00	.7625	.2330	-.0948	.2330	.7625
	185.00	.0133	.17172	.0173	.4316	1.6621		118.00	.7090	.2895	-.0993	.2188	.8212
	190.00	.0004	.17347	.0143	.3007	1.7086		123.00	.7625	.2330	-.0948	.2330	.7625
	195.00	-.0086	.17539	.0069	.1615	1.7465		128.00	.7283	.1748	-.0981	.2372	.7103
	200.00	-.0387	.17590	.0042	.1008	1.7561		133.00	.6952	.0906	-.1079	.2099	.6689
	205.00	-.0676	.17636	.0067	.0384	1.7632		138.00	.6697	.0640	-.1392	.1115	.6635
	210.00	-.0990	.17636	.0029	.0090	1.7636		143.00	.6662	.0361	-.1860	.0604	.7288
	215.00	-.0627	.17719	.0010	-.0282	1.7716		148.00	.6292	.0531	-.2056	.2194	.7910
	220.00	-.0015	.17703	-.0038	-.0912	1.7680		153.00	.6115	.0736	-.2391	.3606	.8843
	225.00	-.0043	.17689	-.0090	-.1499	1.7626		158.00	.5837	.0795	-.2413	.3922	.8956
1222	230.00	.2855	.6279	-.0163	.1013	.6823	1223	155.00	.0349	.1677	.0244	.6774	1.5352
	235.00	.3732	.6188	-.0218	.1391	.7091		160.00	.0212	.1723	.0265	.5692	1.6257
	240.00	.4712	.6229	-.0301	.1639	.7636		165.00	-.0017	.17562	.0208	.4561	1.6960
	250.00	.5752	.6194	-.0405	.1884	.8240		170.00	-.0120	.17680	.0146	.3188	1.7390
	255.00	.6724	.6169	-.0527	.1970	.8910		175.00	-.0212	.17940	.0049	.1775	1.7854
	260.00	.7491	.6027	-.0577	.1864	.9432		177.00	-.0176	.17970	.0028	.1117	1.7936
	265.00	.8110	.5919	-.0626	.1550	.9920		179.00	-.0127	.17969	-.0015	.0441	1.7964
	270.00	.8542	.5682	-.0680	.1138	1.0196		180.00	-.0090	.18051	-.0017	.0090	1.8051
	275.00	.8733	.5438	-.0699	.0554	1.0273		181.00	-.0066	.18052	-.0040	.0249	1.8050
	280.00	.8797	.4969	-.0721	.0096	1.0103		183.00	-.0055	.17971	-.0073	.0886	1.7949
	285.00	.8861	.5074	-.									

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
2221	-5.00	-.0770	.6262	.0017	-.0221	.6305	2223	61.00	.9216	.5082	-.0331	.0023	1.0524
	-3.00	-.0429	.6249	.0032	-.0101	.6262		65.00	.9329	.4779	-.0346	-.0388	1.0475
	-1.00	-.0167	.6224	.0010	-.0058	.6226		71.00	.7226	.4375	-.0324	-.0954	1.0166
	.00	.0049	.6234	-.0018	.0049	.6234		75.00	.9157	.3940	-.0456	-.1143	.9867
	1.00	.0187	.6216	-.0006	.0079	.6218		80.00	.8908	.3433	-.0551	-.1134	.9369
	5.00	.0466	.6224	-.0011	.0139	.6239		85.00	.8672	.2975	-.0621	-.2206	.8904
	10.00	.0833	.6254	-.0036	.0285	.6303		90.00	.8416	.2432	-.0693	-.2432	.8416
	15.00	.1646	.6299	-.0063	.0529	.6480		95.00	.8132	.1862	-.0735	-.2564	.7939
	20.00	.2580	.6254	-.0125	.0873	.6709		100.00	.7256	.1093	-.0845	-.2439	.7541
	25.00	.3690	.6475	-.0227	.1252	.7346		105.00	.7697	.0296	-.1028	-.2019	.7433
	30.00	.4818	.6580	-.0324	.1586	.8000		76.00	.8289	.3840	-.0504	-.1551	.9651
	35.00	.5852	.6249	-.0156	.1020	.6793		80.00	.8819	.3413	-.0576	-.1830	.9278
	40.00	.3745	.6337	-.0220	.1352	.7236		85.00	.8642	.2886	-.0670	-.2122	.8861
	45.00	.4843	.6431	-.0207	.1671	.7875		90.00	.8457	.2368	-.0716	-.2368	.8347
	50.00	.5865	.6460	-.0331	.1949	.8527		95.00	.8032	.1812	-.0758	-.2505	.7844
	55.00	.6660	.6500	-.0495	.1891	.9259		100.00	.7688	.0986	-.0877	-.2306	.7400
	60.00	.7675	.6372	-.0474	.1783	.9814		105.00	.7430	.0545	-.1193	-.1397	.7318
	65.00	.8341	.6107	-.0461	.1580	1.0216		110.00	.7273	.2905	-.1657	-.0244	.7826
	70.00	.8801	.5799	-.0496	.1215	1.0470		115.00	.6859	.5339	-.1915	-.1940	.8472
	75.00	.9008	.5415	-.0515	.0731	1.0485		120.00	.6674	.7279	-.2232	.3284	.9327
	80.00	.9115	.4918	-.0525	.0299	1.0353		125.00	.6258	.7911	-.2146	.3558	.9438
	85.00	.9196	.5053	-.0341	.0039	1.0493		130.00	.5544	.9851	-.1957	.4889	1.0191
	90.00	.9228	.4754	-.0358	.0409	1.0372		135.00	.4510	.1198	-.1609	.6292	1.1167
	95.00	.9147	.4356	-.0392	.0965	1.0065		140.00	.3256	.1312	-.0817	.6980	1.1576
	100.00	.9111	.3922	-.0417	.1430	.9816		145.00	.2331	.1496	-.0460	.7830	1.2958
	105.00	.8734	.3535	-.0473	.1964	.9215		150.00	.1355	.1549	-.0094	.7777	1.3471
	110.00	.8518	.3054	-.0491	.2300	.8752		155.00	.0553	.16285	-.0309	.6381	1.4993
	115.00	.8239	.2561	-.0500	.2561	.8239		160.00	.0354	.16634	-.0322	.5356	1.5752
	120.00	.7943	.2030	-.0501	.2714	.7736		162.70	.0237	.16811	-.0308	.4773	1.6120
	125.00	.7576	.1338	-.0504	.2634	.7229							
	130.00	.7316	.0779	-.0505	.2405	.6953							
	135.00	.6875	.3892	-.0461	.1629	.9553							
	140.00	.6730	.3539	-.0491	.1969	.9212							
	145.00	.8473	.3071	-.0507	.2320	.8709							
	150.00	.8151	.2552	-.0517	.2552	.8151							
	155.00	.7869	.1940	-.0512	.2619	.7670							
	160.00	.7433	.1288	-.0511	.2559	.7096							
	165.00	.6954	.0165	-.0525	.1959	.6674							
	170.00	.6450	.-1.420	-.0524	.0872	.6547							
	175.00	.5824	.-3.315	-.0192	.0543	.6679							
	180.00	.5394	.-4.506	-.0173	.1447	.6878							
	185.00	.4913	.-5.084	-.0425	.1828	.6829							
	190.00	.4215	.-6.821	-.0294	.3169	.7365							
	195.00	.3410	.-8.954	-.0157	.4662	.8374							
	200.00	.2621	.-1.1101	-.0040	.5997	.9703							
	205.00	.1893	.-1.2810	-.0091	.6784	1.1030							
	210.00	.1304	.-1.4027	-.0205	.6978	1.2238							
	215.00	.0894	.-1.5012	-.0236	.6732	1.3448							
	220.00	.0689	.-1.5681	-.0282	.6003	1.4503							
	225.00	.0467	.-1.6177	-.0266	.5094	1.5361							
	230.00	.0343	.-1.6453	-.0261	.4566	1.5811							
2222	61.00	.9147	.5023	-.0337	.0042	1.0435	2221	-5.00	-.0695	.6419	-.0001	-.0133	.6456
	65.00	.9165	.4716	-.0355	.0401	1.0299		-2.00	-.0374	.6412	-.0006	-.0337	.6423
	70.00	.9133	.4252	-.0390	.0872	1.0036		-1.00	-.0376	.6371	-.0025	-.0035	.6371
	75.00	.909	.3778	-.0403	.1291	.9777		0.00	-.0063	.6370	-.0024	-.0063	.6370
	80.00	.8762	.3302	-.0418	.1730	.9202		1.00	-.0190	.6374	-.0018	-.0079	.6376
	85.00	.8560	.2815	-.0401	.2056	.8792		2.00	-.0514	.6333	-.0034	-.0182	.6351
	90.00	.8397	.2194	-.0377	.2194	.8397		5.00	-.0866	.6296	-.0042	-.0206	.6447
	95.00	.8180	.1524	-.0323	.2231	.8016		10.00	-.1672	.6137	-.0100	-.0530	.7150
	100.00	.7950	.0642	-.0250	.2033	.7714		20.00	-.2506	.6520	-.0115	-.0814	.6698
	105.00	.7730	.0033	-.0186	.1771	.7525		30.00	-.3749	.6250	-.0239	-.1219	.7644
	110.00	.6933	.3706	-.0433	.1435	.9565		40.00	-.4688	.5107	-.0161	-.0933	.7017
	115.00	.6818	.3283	-.0436	.1702	.9254		50.00	-.5019	.4267	-.0217	.1254	.7489
	120.00	.6570	.2767	-.0418	.2009	.8778		70.00	-.5973	.3796	-.0261	.1560	.8201
	125.00	.6366	.2131	-.0403	.2131	.8366		80.00	-.6925	.3435	-.0322	.1687	.8905
	130.00	.6116	.1437	-.0347	.2139	.7960		90.00	-.8339	.2974	-.0331	.1743	.9636
	135.00	.5829	.0529	-.0274	.1881	.7618		95.00	-.8593	.2512	-.0363	.2195	.9035
	140.00	.5685	.-4.329	-.0251	.0783	.7103		100.00	-.8326	.1977	-.0367	.2495	.8593
	145.00	.4980	.-5.525	-.0420	.1670	.7248		105.00	-.7057	.1311	-.0355	.2473	.8122
	150.00	.4069	.-6.993	-.0484	.2741	.7612		110.00	-.7659	.0487	-.0372	.2392	.7498
	155.00	.3324	.-8.413	-.0571	.3599	.8299		120.00	-.9209	.3749	-.0315	.1410	.9842
	160.00	.2566	.-9.835	-.0573	.4356	.9183		125.00	-.9029	.3408	-.0347	.1788	.9494
	165.00	.1987	.-1.1104	-.0562	.4741	1.0236		130.00	-.8556	.2937	-.0381	.2156	.9058
	170.00	.1599	.-1.2282	-.0533	.4756	1.1436		135.00	-.8624	.2444	-.0374	.2444	.8624
	175.00	.1257	.-1.3317	-.0478	.4489	1.2600		140.00	-.8272	.1850	-.0374	.2566	.8099
	180.00	.0913	.-1.4173	-.0395	.3989	1.3630		145.00	-.7880	.1252	-.0351	.2601	.7543
	185.00	.0768	.-1.4552	-.0362	.3594	1.4122		150.00	-.7371	.0181	-.0360	.2083	.7073
	190.00							155.00	-.6869	.1383	-.0365	.1049	.6928
	195.00							160.00	-.6149	.3280	-.0358	.0474	.6959
	200.00							165.00	-.5735	.4476	-.0308	.1260	.7165
	205.00							170.00	-.5173	.5017	-.0295	.1636	.7018
	210.00							175.00	-.4511	.5764	-.0163	.2954	.7575
	215.00							180.00	-.3649	.9009	-.0061	.4555	.8586
	220.00							185.00	-.2856	-1.1072	.0057	.5818	.9844
	225.00							190.00	-.2115	-1.2740	.0195	.6569	1.1119
	230.00							195.00	-.1468	-1.3953	.0272	.6900	1.2272
	235.00							200.00	-.1029	-1.4913	.0303	.6566	1.3430
	240.00							205.00	-.0779	-1.5623	.0317	.5897	1.4488
	245.00							210.00	-.0544	-1.6148	.0306	.5012	1.5340
	250.00							215.00	-.0449	-1.6395	.0301	.4446	1.5707

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
3222	61.00	.9327	.5090	-.0193	.0070	1.0626	1321	76.00	1.0616	.4194	-.0375	-.1503	1.1306
	65.00	.9373	.4680	-.0215	-.0281	1.0473		80.00	1.0404	.3854	-.0448	-.1988	1.0917
	70.00	.9338	.4187	-.0241	-.0740	1.0207		85.00	1.0162	.3451	-.0496	-.2552	1.0424
	75.00	.9287	.3741	-.0249	-.1210	.9939		90.00	.9783	.2977	-.0524	-.2977	.9783
	80.00	.9054	.3277	-.0269	-.1655	.9485		95.00	.9320	.2393	-.0550	-.3196	.9076
	85.00	.8955	.2735	-.0264	-.1944	.9159		100.00	.8807	.1754	-.0552	-.3256	.8368
	90.00	.8794	.2177	-.0236	-.2177	.8794		105.00	.8162	.0627	-.0570	-.2718	.7722
	95.00	.8600	.1493	-.0178	-.2237	.8437		110.00	.7523	-.0970	-.0605	-.1662	.7401
	100.00	.8336	.0647	-.0113	-.2085	.8097		115.00	.6759	-.2816	-.0583	-.0304	.7316
	103.00	.8145	.0114	-.0032	-.1943	.7910		118.00	.6229	-.4073	-.0570	-.0672	.7412
3223	61.00	.9223	.3707	-.0279	-.1366	.9846	121.00	.5365	-.5089	-.0627	.1599	.7220	
	65.00	.9110	.3260	-.0292	-.1628	.9538	125.00	.4643	-.6941	-.0465	.3023	.7784	
	70.00	.8992	.2747	-.0275	-.1958	.9147	130.00	.3686	-.9425	-.0337	.4851	.8882	
	75.00	.8779	.2220	-.0235	-.2220	.8779	135.00	.2701	-.11621	-.0197	.6307	1.0127	
	80.00	.8573	.1477	-.0188	-.2218	.8411	140.00	.1799	-.3529	-.0051	.7318	1.1520	
	85.00	.8240	.0603	-.0118	-.2028	.8030	145.00	.1043	-.5017	-.0051	.7759	1.2899	
	90.00	.7859	-.0437	-.0003	-.1612	.7704	150.00	.0505	-.5980	-.0065	.7553	1.4092	
	95.00	.7439	-.1782	-.0107	-.0869	.7599	155.00	.0235	-.6772	-.0072	.6875	1.5300	
	100.00	.6989	-.3150	-.0213	-.0660	.7583	160.00	.0632	-.7392	-.0064	.5918	1.6354	
	103.00	.6437	-.4039	-.0277	-.0544	.7580	163.00	-.0170	-.7745	-.0031	.5351	1.6920	
1321	61.00	.5915	-.4238	-.0386	-.0587	.7253	151.00	.0894	-.5672	-.0168	.6816	.4140	
	65.00	.5179	-.5444	-.0484	-.1488	.7365	155.00	.0705	-.6019	-.0220	.6131	.4816	
	70.00	.4284	-.6994	-.0560	-.2604	.7778	160.00	.0516	-.6604	-.0231	.5194	.5779	
	75.00	.3478	-.8411	-.0629	-.3489	.8407	165.00	.0298	-.7111	-.0203	.4141	.6605	
	80.00	.2734	-.9804	-.0642	-.4208	.9267	170.00	.0194	-.7369	-.0134	.2923	.7121	
	85.00	.2079	-.1100	-.0593	-.4664	1.0285	175.00	-.0035	-.7508	-.002	.1561	.17438	
	90.00	.1622	-.12358	-.0527	-.4774	1.1513	177.00	-.0101	-.7508	-.0030	.1017	.17479	
	95.00	.1297	-.13344	-.0485	-.4664	1.2642	179.00	-.0065	-.7655	-.0006	.0373	.17651	
	100.00	.0993	-.14166	-.0415	-.3912	1.3652	180.00	-.0104	-.7918	-.0022	.0104	.17918	
	103.00	.0793	-.14679	-.0350	-.3608	1.4251	181.00	-.0117	-.7671	-.0038	.0191	.17670	
	121.00	-.0185	-.17622	-.0125	-.0185	1.751	183.00	-.0158	-.7670	-.0084	.0767	.17654	
1322	61.00	.9299	.5114	-.0175	.0035	1.0612	185.00	-.17622	-.0123	-.1252	-.17571		
	65.00	.9374	.4723	-.0200	-.0319	1.0492							
	70.00	.9340	.4242	-.0258	-.0792	1.0228							
	75.00	.9291	.3631	-.0325	-.1295	.9966							
	80.00	.9119	.3383	-.0404	-.1748	.9567							
	85.00	.8953	.2852	-.0491	-.2061	.9168							
	90.00	.8753	.2354	-.0537	-.2354	.8753							
	95.00	.8443	.1840	-.0572	-.2569	.8251							
	100.00	.8214	.1081	-.0691	-.2491	.7901							
	103.00	.8051	.0355	-.0844	-.2157	.7765							
1323	61.00	1.1244	.5000	-.0188	.1078	1.2258	1321	61.00	1.1244	.5000	-.0188	.1078	1.2258
	65.00	1.1283	.4833	-.0229	.0388	1.2269							
	70.00	1.1194	.4548	-.0281	.0445	1.2075							
	75.00	1.0969	.4227	-.0316	.1244	1.1689							
	80.00	1.0754	.3952	-.0366	.1926	1.1260							
	85.00	1.0577	.3349	-.0415	.2144	1.0829							
	90.00	1.0243	.2780	-.0415	.2780	1.0243							
	95.00	.9924	.2013	-.0406	.2870	1.0243							
	100.00	.9490	.1182	-.0356	.2812	1.0243							
	103.00	.9125	.0494	-.0307	.2534	1.0243							
1324	76.00	1.0647	.4566	-.0352	.1369	1.1315	1321	76.00	1.0647	.4566	-.0352	.1369	1.1315
	80.00	1.0480	.3749	-.0377	.1872	1.0972							
	85.00	1.0226	.3244	-.0414	.2341	1.0470							
	90.00	.9959	.2701	-.0410	.2701	.9959							
	95.00	.9563	.1943	-.0399	.2770	.9358							
	100.00	.9150	.1116	-.0344	.2688	.8817							
	105.00	.8620	-.0020	-.0272	.2212	.8331							
	110.00	.8134	-.1296	-.0160	.1564	.8086							
	115.00	.7423	-.2776	-.0059	.0621	.7901							
	118.00	.6945	-.3676	-.0017	.0014	.7858							
1325	121.00	.6550	-.3932	-.0115	.0004	.7639	1321	121.00	.6550	-.3932	-.0115	.0004	.7639
	125.00	.5929	-.5141	-.0316	.0688	.7724							
	130.00	.4878	-.6635	-.0441	.1947	.8002							
	135.00	.3887	-.8158	-.0493	.3020	.8518							
	140.00	.2953	-.9658	-.0500	.3943	.9293							
	145.00	.2199	-.1095	-.0467	.4506	1.0268							
	150.00	.1730	-.2176	-.0439	.4590	1.1410							
	155.00	.1349	-.3212	-.0399	.4362	1.2546							
	160.00	.1033	-.4096	-.0353	.3850	1.3599							
	163.00	.0901	-.4514	-.0333	.3381	1.4143							
1326	151.00	.1567	-.12943	-.0394	.4908	1.2080	1321	151.00	.1567	-.12943	-.0394	.4908	1.2080
	155.00	.1337	-.13826	-.0380	.4631	1.3096							
	160.00	.1023	-.14268	-.0338	.3919	1.3757							
	165.00	.0640	-.15494	-.0249	.3381	1.5089							
	170.00	.0385	-.15776	-.0193	.2361	1.5603							
	175.00	.0150	-.16096	-.0106	.1273	1.6046							
	177.00	-.0114	-.16228	-.0049	.0735	.6212							
	179.00	-.0062	-.16202	-.0011	.0285	.6200							
	180.00	-.0040	-.16175	-.0002	.0040	.6175							
	181.00	-.0092	-.16257	-.0027	-.0192	.6257							
	183.00	-.0170	-.16257	-.0056	-.0681	.6244							
	185.00	-.0261	-.16196	-.0120	-.1152	.6157							
1327	61.00	1.1211	.5022	-.0187	.1043	1.2240	1321	65.00	1.1251	.4881	-.0228	.0331	1.2260
	70.00	1.1139	.4652	-.0283	.0561	1.2058							
	75.00	1.0941	.4310	-.0395	.1331	1.1684							
	80.00	1.0733	.3920	-.0516	.1993	1.1271							
	85.00	1.0524	.3468	-.0626	.2538	1.0766							
	90.00	1.0176	.2940	-.0712	.2940	1.0176							
	95.00	.9729	.2369	-.0796	.3208	.9486							
	100.00	.9268	.1548	-.0928	.5133	.8858							
	105.00	.9051	.0753	-.1112	.2770	.8650							

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
1323	76.00	1.0710	.4219	-.0406	-.1503	1.1413	1325	120.00	.7132	-.3158	-.0523	-.0831	.7755
80.00	1.0575	.3837	-.0527	-.1943	1.1020		125.00	.6184	-.4645	-.0322	.0258	.7730	
85.00	1.0279	.3321	-.0651	-.2412	1.0529		130.00	.5396	-.6109	-.0058	.1218	.8061	
90.00	.9949	.2859	-.0722	-.2859	.9949		135.00	.4363	-.7389	-.0106	.2140	.8310	
95.00	.9536	.2245	-.0799	-.3065	.9305		140.00	.3574	-.8812	-.0078	.2926	.9047	
100.00	.9025	.1509	-.0914	-.3053	.8626		145.00	.2960	-.10046	-.0160	.3330	.9932	
105.00	.8621	-.0073	-.1259	-.2160	.8346		150.00	.2575	-.11088	.0329	.3314	1.0890	
110.00	.8342	-.2392	-.1763	-.0605	.8657		155.00	.2240	-.12146	.0332	.3103	1.1955	
115.00	.7770	-.4700	-.2019	-.0976	.9028		160.00	.1809	-.12998	.0275	.2746	1.2833	
118.00	.7523	-.6934	-.2394	-.2502	.9850		150.00	.2609	-.10845	.0327	.3164	1.0697	
121.00	.7219	-.7284	-.2258	-.2526	.9940		155.00	.2215	-.11729	.0332	.2950	1.1566	
125.00	.6424	-.9159	-.2058	-.3810	1.0515		160.00	.1803	-.12547	.0311	.2597	1.2407	
130.00	.5263	-.1402	-.1694	-.5351	1.1361		165.00	.1414	-.13255	.0261	.2065	1.3169	
135.00	.4010	-.1308	-.1103	-.6426	1.2098		170.00	.1018	-.13793	.0205	.1392	1.3760	
140.00	.2833	-.14535	-.0512	.7173	1.2955		175.00	.0705	-.14149	.0152	.0531	1.4156	
145.00	.1720	-.15062	-.0110	.7230	1.3325		177.00	.0555	-.14247	.0124	.0192	1.4256	
150.00	.1043	-.15565	.0254	.6880	1.4002		179.00	.0393	-.14304	.0071	-.0143	1.4309	
155.00	.0672	-.15993	.0279	.6150	1.4779		180.00	.0327	-.14313	.0081	-.0327	1.4313	
160.00	.0496	-.16323	.0323	.5117	1.5509		181.00	.0241	-.14330	.0046	-.0491	1.4324	
163.00	.0321	-.16572	.0300	.4538	1.5942		183.00	.0100	-.14292	.0028	-.0848	1.4267	
151.00	.0742	-.16410	.0199	.7307	1.4713		185.00	-.0052	-.14213	-.0004	-.1187	1.4164	
155.00	.0531	-.16681	.0258	.6569	1.5342								
160.00	.0392	-.17041	.0289	.5460	1.6147								
165.00	.0163	-.17460	.0262	.4362	1.6907								
170.00	.0007	-.17621	.0184	.3053	1.7354								
175.00	-.0111	-.17815	.0101	.1664	1.7737								
177.00	-.0165	-.17813	.0035	.1097	1.7780								
179.00	-.0154	-.18060	-.0005	.0469	1.8054								
180.00	-.0116	-.18092	-.0015	.0116	1.8092								
161.00	-.0104	-.18092	-.0030	-.0212	1.8091								
183.00	-.0120	-.18060	-.0086	-.0285	1.8041								
185.00	-.0121	-.18061	-.0120	-.1453	1.8003								
1324	60.00	1.0718	.5013	-.0136	-.1018	1.1789	1326	60.00	1.0967	.4688	-.0262	.1424	1.1842
65.00	1.0866	.4698	-.0190	.0334	1.1033		65.00	1.1230	.4375	-.0311	.0781	1.2027	
70.00	1.0815	.4408	-.0224	-.0463	1.1671		70.00	1.1256	.3987	-.0359	.0103	1.1941	
75.00	1.0694	.4041	-.0254	-.1135	1.1376		75.00	1.1293	.3888	-.0419	.0446	1.1811	
80.00	1.0711	.3583	-.0298	-.1669	1.1170		80.00	1.1444	.2843	-.0505	.0813	1.1764	
85.00	1.0476	.3164	-.0309	-.2239	1.0712		85.00	1.1429	.2182	-.0577	.1178	1.1576	
90.00	1.0246	.2580	-.0324	-.2580	1.0246		95.00	1.1471	.0451	-.0708	.1449	1.1388	
95.00	.9999	.1794	-.0309	-.2659	.9805		100.00	1.1375	-.0444	-.0730	.1538	1.1279	
100.00	.9707	.0920	-.0234	-.2592	.9100		80.00	1.1776	.2913	-.0503	.0824	1.2103	
105.00	.0957	.3494	-.0417	-.1538	1.1398		85.00	1.1846	.2111	-.0609	-.1071	1.1985	
80.00	1.0957	.3494	-.0417	-.1538	1.1398		90.00	1.1921	.1246	-.0682	.1246	1.1921	
85.00	1.0744	.2951	-.0451	-.2004	1.0960		95.00	1.1944	.0335	-.0726	.1375	1.1870	
90.00	1.0470	.2364	-.0459	-.2364	1.0470		100.00	1.1794	-.0538	-.0748	.1518	1.1708	
95.00	1.0166	.1586	-.0430	-.2466	.9989		105.00	1.1430	.1448	-.0762	.1559	1.1416	
100.00	.9844	.0635	-.0369	-.2334	.9584		110.00	1.0902	.2305	-.0739	.1563	1.1033	
105.00	.9410	-.0442	-.0270	-.2008	.9203		115.00	1.0298	.2978	-.0709	.1653	1.0592	
110.00	.8993	-.1692	-.0174	-.1486	.9930		120.00	.9219	.3967	-.0618	-.1189	-.9994	
115.00	.8289	-.2937	-.0120	-.0841	.8753		125.00	.8693	-.3504	-.1198	-.1312	.9280	
120.00	.7601	-.4107	-.0057	-.0244	.8637		130.00	.7735	-.4560	-.1036	-.0702	.8952	
125.00	.7030	-.3693	-.0576	-.0317	.7935		135.00	.6897	-.5548	-.0859	-.0183	.8849	
130.00	.6116	.5120	-.0242	.0686	.7947		140.00	.5992	-.6108	-.0727	-.0294	.8768	
135.00	.4715	.7718	-.0067	.2505	.8409		145.00	.5177	-.7417	-.0658	.0802	.9010	
140.00	.3312	.9143	-.0055	.3340	.9133		150.00	.4173	.9009	-.0388	.0891	.9889	
145.00	.2649	-.10458	-.0164	.3828	1.0086		155.00	.3623	-.9876	-.0312	.0890	1.0482	
150.00	.2165	-.11727	-.0250	.3989	1.1239		160.00	.2973	-.10867	-.0287	.0923	1.1224	
155.00	.1781	-.13076	-.0251	.3912	1.2604		165.00	.3970	-.8867	-.0426	.0906	.9508	
160.00	.1321	-.14291	-.0161	.3647	1.3881		170.00	.3415	-.9486	-.0363	.0914	1.0040	
165.00	.1236	-.14558	-.0351	.3671	1.1111		175.00	.2086	-.10443	-.0293	.0991	1.0753	
170.00	.1049	-.12612	-.0323	.3581	1.2246		180.00	.2474	-.11423	-.0245	.0942	1.1574	
175.00	.1133	-.13766	-.0270	.3299	1.3449		185.00	.0846	-.12837	-.0080	.0276	1.2862	
180.00	.0809	-.14814	-.0220	.2740	1.4602		190.00	.0554	-.12935	-.0047	.0124	1.2946	
185.00	.0591	-.15447	-.0200	.1885	1.5352		195.00	.0294	-.13018	-.0021	.0067	1.3021	
190.00	.0538	-.15754	-.0146	.0784	1.5746		200.00	.0142	-.13004	-.0017	.0142	1.3004	
195.00	.0439	-.15832	-.0125	.0929	1.5838		205.00	.0022	-.13014	-.0002	.0249	1.3012	
200.00	.0418	-.15919	-.0107	.0418	1.5919		210.00	-.0335	-.13024	-.0002	.0347	1.3024	
205.00	.0309	-.15902	-.0075	.0586	1.5895		215.00	-.0574	-.12919	-.0079	-.0554	1.2920	
210.00	.0256	-.15915	-.0064	.1089	1.5880								
215.00	.0222	-.15830	-.0039	.1601	1.5751								
1325	60.00	1.0577	.5178	-.0196	.0805	1.1749	2321	-5.00	-.0746	.4394	-.0003	.0360	.4442
65.00	1.0701	.4881	-.0249	.0098	1.1741		-3.00	-.0437	.4550	-.0051	-.0208	4.367	
70.00	1.0683	.4584	-.0267	-.0654	1.1607		-1.00	-.0049	.4354	-.0062	.0027	.4354	
75.00	1.0518	.4190	-.0305	-.1309	1.1302		.05	.0190	.4746	-.0041	.0100	.4346	
80.00	1.0570	.3669	-.0350	-.1778	1.1046		1.00	.0262	.4336	-.0033	.0166	.4340	
85.00	1.0447	.3218	-.0347	-.2295	1.0687		3.00	.0623	.4325	-.0015	.0396	.4352	
90.00	1.0269	.2558	-.0349	-.2550	1.0269		5.00	.0970	.4347	-.0028	.0587	.4415	
95.00	1.0096	.1783	-.0314	-.2655	.9897		10.00	.1973	.4466	-.0042	.1167	.4741	
100.00	.9829	.0903	-.0273	-.2596	.9523		15.00	.3230	.4687	-.0109	.1907	.5363	
105.00	.9481	.0238	-.0142	-.1213	.9461		20.00	.4600	.5051	-.0165	.2595	.6319	
110.00	.8727	-.2731	-.0142	.1818	1.1311		25.00	.5978	.5282	-.0211	.3186	.7313	
115.00	.7862	-.3895	-.0046	.0558	.8757		30.00	.3492	.4777	-.0071	.2040	.5555	
120.00	1.0703	.1308	-.0431	-.2236	1.0548		35.00	.4598	.4997	-.0119	.2612	.6269	
100.00	1.0478	.0427	-.0377	-.2241	1.0245		40.00	.5896	.5205	-.0110	.3144	.7209	
105.00	.9963	-.0564	-.0317	-.2034	.9770		45.00	.7156	.5386	-.0143	.3504	.8242	
110.00	.9481	-.1613	-.0238	.1727	.9461		50.00	.1196	.5263	-.0215	.2111	.12190	
115.00	.8727	-.2731	-.0142	.1213	.9063		60.00	.1452	.4989	-.0215	.1105	.12413	
120.00	.7862	-.3895	-.0046	.0558	.8757		65.00	.1432	.5044	-.0003	.1682	.12357	
100.00	1.0703	.1308	-.0431	-.2236	1.0548		70.00	.1354	.4671	-.0074	-.0506	1.2267	
75.00	1.1106	.4408	-.0135	.1386	1.1869		75.00	.1040	.4021	-.0212	-.2105	1.1512	
80.00	1.0972	.4072	-.0212	.1048	1.1849		85.00	.1096	.3641	-.0264	.2695	.10972	
85.00	.10418	.3194	-.0292	.1311	1.0418		90.00	.9940	.2646	-.0322	.3502	.9671	
90.00	.9315	.1919	-.0344	.1308	1.0548		100.00	.9315	.1919	-.0344	.3508	.8841	
1													

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
2321	16.00	1.1071	.4221	-.0173	-.1418	1.1763	3321	16.00	.3549	.4950	-.0113	.2048	.5736
	80.00	1.0901	.3894	-.0253	-.1942	1.1411		20.00	.4660	.5176	-.0147	.2609	.6458
	85.00	1.0647	.3526	-.0279	-.2585	1.0914		25.00	.5994	.5390	-.0137	.3154	.7418
	90.00	1.0321	.3028	-.0311	-.3028	1.0321		30.00	.7244	.5606	-.0131	.3470	.8477
	95.00	.9812	.2463	-.0333	-.3309	.9560		35.00	.8411	.5685	-.0131	.3629	.9481
	100.00	.9270	.1784	-.0336	-.3367	.8819		40.00	.9455	.5746	-.0154	.3550	1.0480
	105.00	.8612	.0682	-.0391	-.2888	.8142		45.00	1.0301	.5671	-.0150	.3274	1.1294
	110.00	.7947	-.0915	-.0416	-.1858	.7781		50.00	1.0965	.5557	-.0158	.2791	1.1972
	115.00	.7121	-.2778	-.0414	-.0491	.7628		55.00	1.1344	.5277	-.0152	.2184	1.2319
	118.00	.6574	-.3993	-.0389	.0440	.7680		60.00	1.1533	.0951	-.0153	.1179	1.2464
	120.00	.6237	-.3986	-.0602	.0333	.7394		61.00	1.1579	.4994	-.0102	.1246	1.2548
	125.00	.5212	-.6451	-.0415	.2295	.7969		65.00	1.1679	.4797	-.0077	.0588	1.2612
	130.00	.4630	-.8943	-.0461	.3875	.9295		70.00	1.1674	.4545	-.0030	.0278	1.2524
	135.00	.3378	-.1160	-.0237	.5502	1.0280		75.00	1.1508	.4313	-.0024	.1187	1.2232
	140.00	.2685	-.3114	-.0049	.6373	1.1772		80.00	1.1343	.3960	-.0097	.1930	1.1859
	145.00	.1821	-.4541	-.0001	.6848	1.2955		85.00	1.1124	.3525	-.0142	.2542	1.1389
	150.00	.1142	-.5565	-.0070	.6839	1.4129		90.00	1.0827	.3091	-.0169	.3091	1.0827
	155.00	.0845	-.6441	-.0137	.6182	1.5258		95.00	1.0253	.2570	-.0185	.3454	.9990
	160.00	.0611	-.17036	-.0147	.5253	1.6218		100.00	.9758	.1825	-.0214	.3491	.9293
	103.00	.9483	-.0556	-.02575		.9138		105.00	.9427	.1248	-.0240	.3337	.8904
2322	61.00	1.1493	.4976	-.0001	.1220	1.2464	3322	77.00	1.1336	.4164	-.0072	.1298	1.2006
	65.00	1.1501	.4762	-.0029	.0546	1.2439		80.00	1.1172	.3843	-.0139	.1845	1.1669
	70.00	1.1411	.4468	-.0085	.0296	1.2251		85.00	1.0924	.3442	-.0168	.2477	1.1182
	75.00	1.1243	.4174	-.0117	.1122	1.1940		90.00	1.0615	.2964	-.0197	.2964	1.0615
	80.00	1.1076	.3792	-.0153	.1811	1.1566		95.00	1.0170	.2393	-.0214	.3270	.9922
	85.00	1.0896	.3351	-.0182	.2388	1.1147		100.00	.9597	.1745	-.0220	.3385	.9148
	90.00	1.0664	.2795	-.0186	.2795	1.0664		105.00	.8873	.0688	-.0272	.2962	.8393
	95.00	1.0215	.2139	-.0160	.3021	.9990		110.00	.8143	-.0897	-.0313	.1942	.7959
	100.00	.9864	.1104	-.0196	.2800	.9522		115.00	.7327	-.2752	-.0313	.0603	.7804
	103.00	.9483	.0545	-.02575		.9138		118.00	.6795	-.4021	-.0317	.0360	.7888
	76.00	1.1193	.4020	-.0158	-.1193	1.1834		125.00	.6473	-.4125	-.0616	.0337	.7666
	80.00	1.1053	.3682	-.0189	-.1707	1.1524		125.00	.5430	-.6601	-.0545	.2292	.8234
	85.00	1.0820	.3253	-.0196	-.2298	1.1063		130.00	.4489	-.9041	-.0431	.4041	.9250
	90.00	1.0575	.2665	-.0220	-.2665	1.0575		135.00	.3525	-.1209	-.0297	.5433	1.0419
	95.00	1.0182	.1987	-.0176	.2866	.9970		140.00	.2611	-.13136	-.0168	.6444	1.1741
	100.00	.9707	.1117	-.0127	.2786	.9366		145.00	.1859	-.4557	-.0063	.6827	1.2990
	105.00	.9142	.0028	-.0043	.2307	.8824		150.00	.1178	-.5179	-.0101	.6840	1.4202
	110.00	.8624	-.1367	-.0025	.1665	.8572		155.00	.0878	-.6510	-.0132	.6181	1.5333
	115.00	.7881	-.2807	-.0108	.0787	.8329		160.00	.0624	-.17091	-.0136	.5259	1.6273
	118.00	.7370	-.3629	-.0174	.0256	.8211							
2323	72.00	.7024	-.3353	-.0014	-.0626	.7750	3322	61.00	1.1612	.4972	-.0107	.1281	1.2566
	75.00	.6226	.5042	-.0342	.0559	.7992		65.00	1.1678	.4755	-.0082	.0625	1.2594
	80.00	.5040	-.6731	-.0150	.1916	.8188		70.00	1.1691	.4461	-.0047	.0193	1.2512
	85.00	.4022	-.8384	-.0325	.3084	.8772		75.00	1.1574	.4192	-.0011	.1053	1.2265
	90.00	.3283	-.16031	-.0241	.3933	.9794		80.00	1.1408	.3783	-.0027	.1745	1.1892
	95.00	.2417	-.1483	-.0388	.4606	1.0792		85.00	1.1256	.3352	-.0030	.2356	1.1505
	100.00	.1928	-.12825	-.0348	.4763	1.2071		90.00	1.1039	.2804	-.0044	.2864	1.1089
	105.00	.1489	-.13904	-.0305	.4527	1.3230		95.00	1.0674	.2074	-.0020	.2996	1.0452
	110.00	.1174	-.14901	-.0274	.3993	1.4494		100.00	1.0176	.1105	-.0034	.2853	.9831
	115.00	.7645	-.6755	-.0221	-.1357	1.1869		105.00	.9804	.0598	-.0070	.2753	.9488
	120.00	.7024	-.3353	-.0014	-.0626	.7750		110.00	.1367	.4074	-.0035	.1203	1.2015
	125.00	.6226	.5042	-.0342	.0559	.7992		120.00	1.1267	.3778	-.0046	.1764	1.1752
	130.00	.5040	-.6731	-.0150	.1916	.8188		125.00	.1376	.3273	-.0078	.2296	1.1319
	135.00	.4022	-.8384	-.0325	.3084	.8772		130.00	1.1762	.2702	-.0074	.2702	1.0762
	140.00	.3283	-.16031	-.0241	.3933	.9794		135.00	1.1048	.2032	-.0049	.2934	1.0221
	145.00	.2417	-.1483	-.0388	.4606	1.0792		140.00	.9998	.1135	-.0004	.2845	.9600
	150.00	.1928	-.12825	-.0348	.4763	1.2071		145.00	.9385	.0908	-.0064	.2437	.9063
	155.00	.1489	-.13904	-.0305	.4527	1.3230		150.00	.8817	-.1284	-.0135	.1802	.8724
	160.00	.1174	-.14901	-.0274	.3993	1.4494		155.00	.8026	-.2902	-.0196	.6853	.8458
	165.00	.7645	-.6755	-.0221	-.1357	1.1869		160.00	.7452	-.3618	-.0257	.0303	.8279
3323	76.00	1.1188	.3621	-.0328	.1644	1.1549	3323	61.00	1.1631	.5016	-.0102	.1281	1.2565
	80.00	1.1053	.3332	-.0445	.2375	1.1076		65.00	1.1650	.4818	-.0075	.0557	1.2595
	85.00	1.0829	.3332	-.0445	.2375	1.1076		70.00	1.1669	.4587	-.0018	.0301	1.2527
	90.00	1.0484	.2821	-.0525	.2821	1.0484		75.00	1.1527	.4255	-.0049	.1127	1.2235
	95.00	1.0073	.2259	-.0587	.3128	.9838		80.00	1.1485	.3879	-.0174	.1826	1.1985
	100.00	.9530	.1543	-.0704	.3175	.9117		85.00	1.1273	.3463	-.0280	.2464	1.1532
	105.00	.9095	-.0012	-.1058	.2342	.8788		90.00	1.0990	.2967	-.0360	.2967	1.0990
	110.00	.8765	-.2430	-.1596	.0715	.9067		95.00	1.0515	.2396	-.0430	.3303	1.0266
	115.00	.8146	-.4712	-.1849	.0828	.9374		100.00	1.0069	.1611	-.0590	.3335	.9636
	120.00	.7658	-.6877	-.2450	.2127	1.0071		105.00	.9819	.0850	-.0775	.3037	.9376
	125.00	.6512	-.9651	-.2278	.4171	1.0870		110.00	1.1491	.4151	-.0109	.1248	1.2154
	130.00	.5687	-.12028	-.1932	.5558	1.2087		115.00	1.1399	.3820	-.0200	.1783	1.1889
	135.00	.4189	-.13076	-.1349	.6850	1.2774		120.00	.8500	1.1168	.3340	-.0316	.2354
	140.00	.3142	-.15391	-.0700	.7486	1.3810		125.00	1.0859	.2847	-.0389	.1417	1.0859
	145.00	.1991	-.5937	-.0074	.7510	1.4197		130.00	1.0432	.2261	-.0464	.3161	1.0195
	150.00	.1179	-.16486	-.0144	.7222	1.4867		135.00	.9892	.1587	-.0593	.3242	.9473
	155.00	.0825	-.17017	-.0221	.6444	1.5772		140.00	.9392	.0096	-.0926	.2524	.9047
	160.00	.0583	-.17444	-.0262	.5418	1.6591		145.00	.9117	.4827	-.0257	.4022	1.4317
	165.00	-.0697	.4441	-.0067	-.0307	.4485							
3321	-5.00	-.0697	.4441	-.0067	-.0138	.4431	3323	76.00	1.1491	.4151	-.0109	.1248	1.2154
	-3.00	-.0370	.4418	-.0066	-.0138	.4431		80.00	1.1399	.3820	-.0200	.1783	1.1889</td

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_{\infty} = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
3323	120.00	.7966	-.6877	-.2471	.1973	1.0332	3324	60.00	1.1198	.4825	.0042	.1520	1.2284
	125.00	.6940	-.9637	-.2490	.3971	1.1131		65.00	1.1663	.4427	-.0002	.0917	1.2441
	130.00	.5529	-1.1942	-.1918	.5594	1.1911		70.00	1.1787	.4049	-.0036	.0226	1.2461
	135.00	.3987	-1.3093	-.1061	.6839	1.2077		75.00	1.1689	.3551	-.0087	-.0353	1.2403
	140.00	.3071	-1.5074	-.0730	.7336	1.3521		80.00	1.2361	.2961	-.0143	-.0822	1.2392
	145.00	.2058	-1.5675	-.0048	.7305	1.4020		85.00	1.2070	.2264	-.0222	-.1201	1.2241
	150.00	.1165	-1.6275	.0170	.7129	1.4677		90.00	1.2187	.1529	-.0256	-.1529	1.2187
	155.00	.0821	-1.6789	.0210	.6351	1.5563		95.00	1.2238	.0630	-.0312	-.1695	1.2136
	160.00	.0543	-1.7203	.0224	.5374	1.6351		100.00	1.2109	.0258	-.0351	-.1849	1.1970
	100.00	1.1157	.5038	.0083	.1216	1.2181		105.00	1.2327	.2796	-.0188	-.0613	1.2626
3324	65.00	1.1385	.4734	.0048	.0522	1.2319	3325	35.00	1.2451	.2050	.0275	-.0957	1.2583
	70.00	1.1342	.4434	.0047	.0288	1.2175		40.00	1.2537	.1217	-.0332	-.1217	1.2537
	75.00	1.1297	.4039	.0311	.0977	1.1957		45.00	1.2536	.0343	-.0361	-.1435	1.2458
	80.00	1.1286	.3649	.0019	.1634	1.1749		50.00	1.2400	-.0533	-.0401	-.1628	1.2305
	85.00	1.1103	.3237	.0009	.2257	1.1343		55.00	1.2177	-.2224	-.0425	-.1797	1.1875
	90.00	1.0892	.2663	-.0057	.2663	1.0892		60.00	1.0613	.3949	-.0423	-.1722	1.0908
	95.00	1.0655	.1904	.0033	.2826	1.0449		65.00	.9707	.3861	-.0380	-.1515	1.0337
	100.00	1.0362	.0948	.0074	.2733	1.0040		70.00	.9173	.3450	-.0791	-.1749	.9929
	105.00	1.1764	.3430	-.0394	.1355	1.2181		75.00	.8308	.4491	-.0652	-.1132	.9447
	110.00	1.1583	.2898	-.0130	.1877	1.1792		80.00	.7352	.5435	-.0544	-.0563	.9126
3325	95.00	1.1356	.2359	-.0114	.2359	1.1356	3326	85.00	.6414	.6488	-.0524	-.0533	.9123
	100.00	1.1114	.1580	-.0087	.2594	1.0934		90.00	.5498	.7418	-.0463	-.0556	.9216
	105.00	1.0793	.0780	-.0042	.2642	1.0494		95.00	.4679	.8242	-.0491	-.0730	.9549
	110.00	1.0297	-.0276	.0027	.2398	1.0017		100.00	.4296	.9018	-.0483	-.0789	.9958
	115.00	.9815	-.1492	.0191	.1955	.9733		105.00	.3654	.9907	-.0381	-.0875	1.0523
	120.00	.9143	-.2712	.0179	.1406	.9432		110.00	.2954	-.0888	-.0339	-.0948	1.1241
	125.00	.8075	-.4139	.0283	.0454	.9063		115.00	.3938	.9727	-.0242	-.0542	1.0480
	130.00	.8099	-.3669	-.0166	.0828	.8771		120.00	.3354	-.10626	-.0170	-.0501	1.1125
	135.00	.6826	-.5043	.0009	.0216	.8485		125.00	.2687	-.1601	-.0139	-.0408	1.1901
	140.00	.5758	-.6407	.0144	.1207	.8529		130.00	.2167	-.2377	-.0035	-.0015	1.2565
3326	145.00	.3839	-.9102	.0298	.2910	.9440	3327	135.00	.1508	.12979	-.0041	-.0371	1.3041
	150.00	.2965	-.10457	.0273	.3569	1.0267		140.00	.1297	.1508	-.0055	-.0504	1.3138
	155.00	.2381	-.1733	.0216	.3805	1.1352		145.00	.0887	.13142	-.0073	-.0658	1.3155
	160.00	.1836	-.3104	.0185	.3874	1.2652		150.00	.0734	.13177	-.0094	-.0734	1.3177
	165.00	.1440	-.4264	.0124	.3626	1.3881		155.00	.0560	.13163	-.0108	-.0790	1.3151
	170.00	.10571	-.3573	.0373	.3630	1.1286		160.00	.0288	.13102	-.0126	-.0974	1.3069
	175.00	.2053	-.2773	.0356	.3537	1.2444		165.00	-.0106	-.13033	-.0155	-.1130	1.2981
	180.00	.1642	-.3876	.0288	.3203	1.3601		170.00	-.0155	-.1130	-.0155	-.1130	1.2981
	185.00	.1279	-.4969	.0216	.2639	1.4790		175.00	-.0155	-.1130	-.0155	-.1130	1.2981
	190.00	.0986	.15610	.0201	.1740	1.5544		180.00	-.0155	-.1130	-.0155	-.1130	1.2981
3327	195.00	.0791	-.15999	.0154	.0598	1.5908	3328	5.00	.0062	.7988	-.0017	-.0062	.7988
	200.00	.0704	-.15962	.0155	.15977	1.5977		10.00	.0220	.7957	-.0047	-.0081	.7960
	205.00	.0504	-.60114	.0114	.0261	1.6021		15.00	.0537	.7942	-.0103	-.0120	.7959
	210.00	.0508	-.5999	.0097	.0558	1.5999		20.00	.0851	.7933	-.0156	-.0157	.7977
	215.00	.0453	-.5994	.0089	.0732	1.5994		25.00	.1594	.7840	-.0286	-.0209	.7998
	220.00	.0344	-.5981	.0071	.1180	1.5981		30.00	.2364	.7751	-.0427	-.0277	.8099
	225.00	.0246	-.5956	.0066	.1636	1.5874		35.00	.3140	.7778	-.0591	-.0291	.8383
	230.00	-.0151	-.5070	.0070	.1183	1.2189		40.00	.3849	.7653	-.0743	-.0273	.8571
	235.00	-.0162	-.4742	.0056	.0506	1.2300		45.00	.2528	.7730	-.0468	-.0299	.8128
	240.00	-.0186	-.4406	.0028	.0246	1.2204		50.00	.3157	.7571	-.0589	-.0378	.8194
3328	245.00	-.0141	-.4012	.0018	.0924	1.2051	3329	55.00	.0463	.7473	-.0715	-.0305	.8383
	250.00	-.01415	-.3537	-.0001	.1501	1.1856		60.00	.3509	.4994	-.0939	-.0208	.8666
	255.00	-.01243	-.3102	-.0009	.2110	1.1470		65.00	.4033	.5451	-.1044	-.0182	.8698
	260.00	-.01086	-.2466	-.0005	.2466	1.1086		70.00	.4503	.5649	-.1077	-.0574	.8562
	265.00	-.00935	-.1725	-.0030	.2671	1.0743		75.00	.5030	.5739	-.1110	-.0945	.8284
	270.00	-.00664	-.0812	-.0055	.2652	1.0361		80.00	.5500	.5748	-.1132	-.1313	.7936
	275.00	-.01673	-.2787	-.0001	.1759	1.1872		85.00	.5718	.5144	-.1143	-.1596	.7524
	280.00	-.01516	-.2143	-.0057	.2143	1.1516		90.00	.5777	.5356	-.0999	-.1883	.7650
	285.00	-.01321	-.1376	-.0033	.2358	1.1158		95.00	.5687	.4977	-.1000	-.2108	.7257
	290.00	-.00951	-.0515	-.0013	.2409	1.0696		100.00	.5515	.4474	-.0992	-.2318	.6712
3329	295.00	-.00454	-.0438	.0042	.2283	1.0211	3330	10.00	.5269	.3958	-.0976	-.2459	.6113
	300.00	-.0103	-.0184	.0072	.1963	.9731		15.00	.5035	.3458	-.0935	-.2531	.5559
	305.00	-.01949	-.2563	.0145	.1501	.9284		20.00	.4791	.2908	-.0887	-.2479	.5026
	310.00	-.00875	-.3716	.0230	.0820	.8851		25.00	.4889	.2315	-.0833	-.2315	.4489
	315.00	-.01940	-.3192	.0113	.1206	.8472		30.00	.4230	.1708	-.0779	-.2071	.4065
	320.00	-.01680	-.4576	.0015	.0199	.8262		35.00	.3910	.0877	-.0740	-.1543	.3699
	325.00	-.01582	-.5832	.0108	.0671	.8335		40.00	.3693	.0148	-.0720	-.0972	.3556
	330.00	-.01487	-.7423	.0103	.1829	.8669		45.00	.5201	.3740	-.0960	-.2474	.5909
	335.00	-.01390	-.5990	.0290	.2620	.9329		50.00	.5351	.3444	-.0934	-.2515	.5572
	340.00	-.01271	-.4326	.0224	.1826	1.3266		55.00	.4796	.2983	-.0888	-.2454	.5029
3330	345.00	-.01063	-.5236	.0262	.3121	1.0099	3331	60.00	.4465	.2343	-.0831	-.2343	.4465
	350.00	-.01214	-.2714	.0260	.3219	1.1033		65.00	.4171	.1725	-.0775	-.2382	.4005
	355.00	-.01216	-.2250	.0250	.3103	1.1977		70.00	.3863	.1863	-.0710	-.1616	.3637
	360.00	-.01309	-.2035	.0230	.2758	1.2868		75.00	.3532	.0246	-.0699	-.0676	.3476
	365.00	-.010892	-.2436	.0301	.2971	1.0862		80.00	.3173	.1808	-.0630	-.0618	.3660
	370.00	-.011823	-.2436	.0290	.2789	1.1745		85.00	.2764	.3749	-.0536	-.2230	.4089
	375.00	-.012612	-.2036	.0267	.2373	1.2558		90.00	.2477	.4990	-.0462	-.3243	.4530
	380.00	-.0113287	-.1670	.0224	.1826	1.3266		95.00	.2260	.5692	-.0385	.3715	.4869
	385.00	-.013920	-.13920	.0155	.1153	1.3932		100.00	.1959	.7421	-.0275	.5013	.5780
	390.00	-.011138	-.1474	.0093	.0285	1.4226		105.00	.1374	.9580	-.0150	.6956	.7211
3331	395.00	-.014262	-.0793	.0064	.0046	1.4284</td							

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued

 $M_\infty = 6.0$

Configuration	α , deg	c_N	c_A	c_m	c_L	c_D	Configuration	α , deg	c_N	c_A	c_m	c_L	c_D
1131	153.00	.0162	-1.5992	.0249	.7116	1.4323	1232	76.00	.8248	.4139	-.0793	-.2064	.8829
	155.00	.0111	-1.6197	.0249	.6744	1.4727		80.00	.7860	.3764	-.0786	-.2342	.8395
	160.00	.0011	-1.6822	.0237	.5743	1.5811		85.00	.7626	.3214	-.0778	-.2537	.7877
	165.00	-.0079	-1.7223	.0189	.4534	1.6616		90.00	.7265	.2636	-.0726	-.2636	.7265
	170.00	-.0056	-1.7415	.0142	.3079	1.7140		95.00	.7006	.1850	-.0643	-.2454	.6818
	175.00	-.0086	-1.7526	.0054	.1614	1.7452		100.00	.6677	.0877	-.0532	-.2023	.6424
	177.00	-.0087	-1.7613	.0024	.1010	1.7614		105.00	.6246	-.0256	-.0375	-.1370	.6099
	179.00	-.0089	-1.7905	-.0017	.0401	1.7900		110.00	.5853	-.1656	-.0204	-.0446	.6066
	180.00	-.0090	-1.7935	-.0040	.0090	1.7935		115.00	.5273	-.3134	-.0041	.0612	.6103
	181.00	-.0078	-1.7904	-.0049	-.0234	1.7902		118.00	.4860	-.4080	-.0048	.1320	.6206
	183.00	-.0093	-1.7968	-.0089	-.0847	1.7948		121.00	.4348	-.4421	.0139	.1551	.6004
	185.00	-.0094	-1.7905	-.0115	-.1467	1.7845		125.00	.3791	-.5641	.0313	.2447	.6341
								130.00	.3069	-.7171	.0150	.3520	.6940
								135.00	.2410	-.8599	.0506	.4376	.7784
								140.00	.1913	-.9995	.0555	.4960	.8887
								145.00	.1569	-1.1255	.0551	.5171	1.0120
								150.00	.1307	-1.2404	.0533	.5070	1.396
								155.00	.1024	-1.3441	.0478	.4752	1.2615
								160.00	.0774	-1.4352	.0417	.4182	1.3751
								162.70	.0642	-1.4700	.0373	.3758	1.4226
								151.00	.1160	-1.2942	.0482	.5259	1.1881
								155.00	.0954	-1.3750	.0431	.4946	1.2865
								160.00	.0697	-1.4295	.0369	.4234	1.3671
								165.00	.0440	-1.5499	.0278	.3586	1.5085
								170.00	.0234	-1.5812	.0196	.2516	1.5613
								175.00	.0054	-1.6211	.0100	.1359	1.6154
								177.00	-.0011	-1.6242	.0051	.0861	1.6219
								179.00	-.0052	-1.6305	-.0018	.0337	1.6302
								180.00	-.0028	-1.6323	-.0022	.0208	1.6323
								181.00	-.0015	-1.6323	-.0024	.0270	1.6321
								183.00	-.0029	-1.6319	-.0056	.0825	1.6299
								185.00	-.0121	-1.6269	-.0112	.1297	1.6218
1231	-5.00	-.0936	.5342	.0085	-.0466	.5004	1233	61.00	.8462	.5217	-.0708	-.0461	.9930
	-3.00	-.0532	.5339	.0038	-.0252	.5260		65.00	.8401	.4998	-.0745	-.0980	.9726
	-1.00	-.0193	.5289	.0023	-.0101	.5291		70.00	.8284	.4665	-.0798	-.1551	.9380
	1.00	-.0003	.5333	.0009	-.0003	.5333		75.00	.8251	.4261	-.0857	-.1980	.9073
	3.00	.0174	.5335	.0002	.0081	.5337		80.00	.7922	.3834	-.0932	-.2404	.8448
	5.00	.0567	.5283	-.0040	.0289	.5306		85.00	.7620	.3337	-.0990	-.2660	.7882
	7.00	.0997	.5326	-.0086	.0529	.5393		90.00	.7303	.2831	-.1009	-.2833	.7303
	10.00	.1951	.5411	-.0169	.0981	.5668		95.00	.6911	.2282	-.1042	-.2875	.6668
	15.00	.3002	.5519	-.0279	.1472	.6108		100.00	.6638	.1381	-.1170	-.2513	.6297
	20.00	.4147	.5727	-.0426	.1938	.6800		105.00	.6337	-.1362	-.1797	-.6191	
	25.00	.5187	.5932	-.0551	.2194	.7568		110.00	.8084	.4204	-.0898	-.2128	.8841
	16.00	.3309	.5520	-.0339	.1659	.6218		115.00	.7906	.3814	-.0951	-.2383	.8448
	20.00	.4158	.5596	-.0427	.1993	.6681		120.00	.8500	.3521	-.1008	-.2645	.7861
	25.00	.5139	.5726	-.0512	.2238	.7362		125.00	.7601	.2874	-.1016	-.2874	.7231
	30.00	.4090	.5856	-.0602	.2346	.8116		130.00	.6882	.2235	-.1045	-.2827	.6661
	35.00	.6874	.5862	-.0679	.2249	.8745		135.00	.6559	.1234	-.1192	-.2354	.6245
	40.00	.7629	.5912	-.0784	.2044	.9433		140.00	.6263	-.0497	-.1506	-.1141	.6179
	45.00	.7999	.5765	-.0783	.1580	.9732		145.00	.6055	-.2885	-.1864	.0640	.6677
	50.00	.8256	.5585	-.0820	.1029	.9914		150.00	.5525	-.5142	-.1983	.2325	.7180
	55.00	.8343	.5409	-.0866	.0354	.9936		155.00	.5462	-.7293	-.2363	.3075	.8247
	60.00	.8399	.5142	-.0917	.0253	.9845		160.00	.4969	-.7994	-.2276	.4293	.8376
	61.00	.8436	.5220	-.0695	.0476	.9909		165.00	.4881	-.9976	-.1998	.5659	.9311
	65.00	.8360	.4989	-.0740	.0989	.9685		170.00	.3502	-1.2124	.1605	.7036	1.0476
	70.00	.8228	.4685	-.0770	.1588	.9334		175.00	.2382	-1.3468	.0910	.7839	1.1207
	75.00	.8082	.4259	-.0827	.2022	.8909		180.00	.1554	-1.5113	-.0844	.8544	1.2599
	80.00	.7748	.3921	-.0835	.2516	.8311		185.00	.0818	-1.5589	.0133	.8272	1.3239
	85.00	.7468	.3454	-.0839	.2790	.7741		190.00	.0484	-1.5965	.0274	.7564	1.4068
	90.00	.7111	.2971	-.0825	.2971	.7111		195.00	.0345	-1.6378	.0333	.6609	1.4990
	95.00	.6755	.2401	-.0801	.2981	.6520		200.00	.0182	-1.6721	.0348	.5548	1.5775
	100.00	.6314	.1656	-.0790	.2727	.5930		205.00	.0147	-1.6917	.0351	.4891	1.6196
	103.00	.5994	.1915	-.0766	.2337	.5612		210.00	.0299	-1.6473	.0213	.7724	1.4553
	76.00	.8074	.4241	-.0853	.2162	.8860		215.00	.0228	-1.6664	.0277	.6828	1.5182
	80.00	.7852	.3881	-.0888	.2459	.8407		220.00	.0115	-1.7055	.0297	.5725	1.6065
	85.00	.7549	.3476	-.0864	.2806	.7814		225.00	-.0066	-1.7453	.0233	.4581	1.6841
	90.00	.7143	.2953	-.0852	.2953	.7143		230.00	-.0146	-1.7622	.0151	.3204	1.7329
	95.00	.6792	.2380	-.0813	.2963	.6559		235.00	-.0162	-1.7947	.0059	.1725	1.7865
	100.00	.6342	.1561	-.0805	.2638	.5975		240.00	-.0190	-1.7916	.0011	.1128	1.7881
	105.00	.5770	.0359	-.0777	.1840	.5480		245.00	-.0141	-1.7885	-.0039	.0453	1.7880
	110.00	.5229	-.1242	-.0712	.0621	.5339		250.00	-.0078	-1.7916	-.0023	.0078	1.7916
	115.00	.4649	-.3249	-.0647	.0980	.5586		255.00	-.0040	-1.7917	-.0037	.0273	1.7915
	116.00	.4212	-.4496	-.0593	.1989	.5836		260.00	-.0016	-1.7947	-.0061	-.0923	1.7925
	121.00	.3623	-.5157	-.0534	.2554	.5762		265.00	-.0031	-1.7948	-.0096	-.1533	1.7883
	125.00	.3075	.6913	-.0343	.3899	.6484		270.00	-.0010	-1.7976	-.0150		
	130.00	.2439	.9193	-.0157	.5174	.7777		275.00	-.0045	-1.8000	-.0213		
	135.00	.1751	-.1289	-.0045	.6745	.9221		280.00	-.0084	-1.8044	-.0277		
	140.00	.1218	-.12943	-.0121	.7387	1.0698		285.00	-.0133	-1.8081	-.0345		
	145.00	.0822	-.14711	-.0213	.7455	1.2079		290.00	-.0166	-1.8045	-.0424		
	150.00	.0589	-.15111	-.0258	.7046	1.3381		295.00	-.0162	-1.8378	-.0533		
	155.00	.0474	-.15764	-.0297	.6232	1.4487		300.00	-.0182	-1.6721	-.0348		
	160.00	.0286	-.16346	-.0282	.5322	1.5458		305.00	-.0147	-1.6917	-.0351		
	162.70	.0202	-.16563	-.0267	.4732	1.5874		310.00	-.0299	-1.6473	-.0213		
	151.00	.0421	-.15774	-.0174	.7279	1.4000		315.00	-.0228	-1.6664	-.0277		
	155.00	.0337	-.16108	-.0246	.6503	1.4741		320.00	-.0115	-1.7055	-.0297		
	160.00	.0224	-.16643	-.0244	.5482	1.5716		325.00	-.0066	-1.7453	-.0233		
	165.00	.0072	-.17210	-.0210	.4384	1.6643		330.00	-.0146	-1.7622	-.0151		
	170.00	-.0083	-.17455	-.0128	.3113	1.7176		335.00	-.0162	-1.7947	-.0059		
	175.00	-.0111	-.17465	-.0061	.1649	1.7568		340.00	-.0190	-1.7916	.0011		
	177.00	-.0151	-.17706	-.0016	.1078	1.7674		345.00	-.0141	-1.7885	-.0039	.0453	1.7880
	179.00	-.0102	-.17675	-.0012	.0410	1.7670		350.00	-.0078	-1.7916	-.0023	.0078	1.7916
	180.00	-.0116	-.17706	-.0034	.0116	1.7706		355.00	-.0040	-1.7917	-.0037	.0273	1.7915
	181.00	-.0053	-.17739	-.0039	.0260	1.7937		360.00	-.0016	-1.7947	-.0061	-.0923	1.7925
	183.00	-.0054	-.17970	-.0065	.0887	1.7948		365.00	-.0031	-1.7948	-.0096	-.1533	1.7883
	185.00	-.0094	-.17970	-.01									

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Continued


 $M_\infty = 6.0$

Configuration	α , deg	C_N	C_A	C_m	C_L	C_D	Configuration	α , deg	C_N	C_A	C_m	C_L	C_D
2231	16.00	.3407	.5507	-.0345	.1757	.6233	2233	120.00	.5193	-.7590	-.2548	.3976	.8292
	20.00	.4324	.5692	-.0416	.2116	.6828		125.00	.4389	-1.0259	-.2304	.5887	.9479
	25.00	.5333	.5821	-.0471	.2373	.7530		130.00	.3497	-1.2576	-.1751	.7386	1.0763
	30.00	.6272	.6003	-.0541	.2430	.8335		135.00	.2370	-1.3888	-.0994	.8144	1.1496
	35.00	.7113	.6100	-.0613	.2328	.9077		140.00	.1540	-1.5709	-.0623	.8918	1.3024
	40.00	.7787	.6045	-.0661	.2079	.9636		145.00	.0757	-1.6222	-.0016	.8685	1.3722
	45.00	.8229	.5908	-.0686	.1641	.9997		150.00	.0372	-1.6612	.0089	.7984	1.4572
	50.00	.8498	.5641	-.0720	.1141	1.0136		155.00	.0237	-1.7083	.0136	.7005	1.5582
	55.00	.8577	.5390	-.0739	.0505	1.0118		160.00	.0077	-1.7440	.0156	.5893	1.6414
	60.00	.8627	.5104	-.0760	.0106	1.0023							
	61.00	.8714	.5174	-.0563	.0300	1.0129							
	65.00	.8693	.4928	-.0599	.0792	.9962							
	70.00	.8576	.4609	-.0633	.1398	.9635							
	75.00	.8506	.4219	-.0687	.1873	.9308							
	80.00	.8176	.3876	-.0704	.2397	.8725							
	85.00	.7886	.3414	-.0714	.2714	.8154							
	90.00	.7532	.3026	-.0686	.3026	.7532							
	95.00	.7228	.2457	-.0670	.3078	.6987							
	100.00	.6746	.1716	-.0648	.2861	.6346							
	103.00	.6448	.1070	-.0648	.2493	.6042							
	76.00	.8368	.4266	-.0692	.2115	.9151							
	80.00	.8168	.3917	-.0724	.2440	.8724							
	85.00	.7857	.3489	-.0719	.2791	.8131							
	90.00	.7564	.2980	-.0715	.2980	.7564							
	95.00	.7167	.2424	-.0665	.3040	.6929							
	100.00	.6703	.1629	-.0658	.2768	.6318							
	105.00	.6118	.0431	-.0654	.1999	.5798							
	110.00	.5625	-.1214	-.0601	.0783	.5701							
	115.00	.4873	-.3149	-.0524	.0795	.5747							
	118.00	.4457	-.4381	-.0485	.1776	.5992							
	123.00	.3729	-.4580	-.0828	.2101	.5515							
	125.00	.3268	-.6986	-.0506	.3849	.6684							
	130.00	.2412	-.9411	-.0518	.5659	.7897							
	135.00	.1759	-.11651	-.0258	.6995	.9483							
	140.00	.1076	-.13453	-.0145	.7823	1.0989							
	145.00	.0725	-.14772	-.0007	.7879	1.2516							
	150.00	.0463	-.15702	-.0040	.7450	1.3830							
	155.00	.0338	-.16428	-.0078	.6637	1.5032							
	160.00	.0112	-.16990	-.0066	.5678	1.6014							
2232	61.00	.8763	.5169	-.0575	.0273	1.0170	2232	61.00	.6676	.1722	-.0558	.2855	.6276
	65.00	.8729	.4893	-.0598	.0746	.9979		65.00	.6341	.1047	-.0557	.2446	.5942
	70.00	.8663	.4530	-.0615	.1294	.9690		70.00	.6104	.4997	-.0484	.0146	1.0043
	75.00	.8563	.4078	-.0640	.1723	.9326		75.00	.5862	.4755	-.0515	.0665	.9826
	80.00	.8283	.3713	-.0629	.2219	.8802		80.00	.5439	.5812	-.0412	.2140	.6963
	85.00	.8054	.3217	-.0612	.2503	.8303		85.00	.5427	.6036	-.0472	.2368	.7764
	90.00	.7804	.2656	-.0571	.2656	.7804		90.00	.6350	.6209	-.0511	.2394	.8552
	95.00	.7551	.1957	-.0499	.2608	.7351		95.00	.7214	.6289	-.0589	.2302	.9290
	100.00	.7207	.1012	-.0396	.2248	.6922		100.00	.7660	.6284	-.0631	.1982	.9866
	103.00	.6938	.0313	-.0300	.1866	.6690		105.00	.8304	.6064	-.0645	.1584	1.0160
	76.00	.8506	.4048	-.0674	.1870	.9232		110.00	.8606	.5750	-.0675	.1127	.10289
	80.00	.8355	.3677	-.0672	.2170	.8867		115.00	.8684	.5467	-.0683	.0503	.10249
	85.00	.8100	.3223	-.0636	.2505	.8350		120.00	.8776	.5079	-.0738	.0011	.10140
	90.00	.7822	.2613	-.0590	.2613	.7822		125.00	.8712	.4997	-.0484	.0146	1.0043
	95.00	.7499	.1905	-.0496	.2552	.7305		130.00	.8480	.4412	-.0561	.1246	.9478
	100.00	.7165	.0946	-.0389	.2176	.6892		135.00	.8256	.4098	-.0591	.1821	.9036
	105.00	.6688	-.0227	-.0254	.1512	.6519		140.00	.8080	.3730	-.0606	.2270	.8605
	110.00	.6269	-.1625	-.0095	.0617	.6447		145.00	.7825	.3330	-.0618	.2355	.8085
	115.00	.5592	-.3150	-.0068	.0492	.6399		150.00	.7538	.2783	-.0622	.2783	.7538
	118.00	.5228	-.4033	-.0152	.1107	.6509		155.00	.7187	.2468	-.0561	.3085	.6945
	120.00	.4588	-.4005	-.0122	.1174	.5976		160.00	.6676	.1722	-.0558	.2855	.6276
	125.00	.3842	-.5681	-.0126	.2450	.6406		165.00	.6341	.1047	-.0557	.2446	.5942
	130.00	.3235	.7400	-.0298	.3590	.7235		170.00	.6104	.3968	-.0603	.1889	.8823
	135.00	.2455	-.8903	-.0225	.4559	.8031		175.00	.5793	.3734	-.0609	.2299	.8463
	140.00	.1905	-.10341	-.0232	.5188	.9147		180.00	.5373	.3324	-.0606	.2442	.7938
	145.00	.1507	-.1730	-.0385	.5494	1.0473		185.00	.7364	.2945	-.0586	.2845	.7364
	150.00	.1219	-.2015	-.0380	.5402	1.1795		190.00	.7619	.2354	-.0553	.2957	.6787
	155.00	.0920	-.13973	-.0332	.5064	1.3056		195.00	.8558	.1597	-.0548	.2712	.6181
	160.00	.0672	-.14097	-.0271	.4464	1.4229		200.00	.6014	.6014	-.0560	.1926	.5710
2233	61.00	.8813	.5186	-.0561	.0263	1.0222	2233	61.00	.8825	.5016	-.0500	.0109	1.0151
	65.00	.8792	.4961	-.0597	.0780	1.0065		65.00	.8705	.4713	-.0536	.0592	.9881
	70.00	.8691	.4576	-.0659	.1328	.9732		70.00	.8611	.4355	-.0549	.1147	.9581
	75.00	.8641	.4209	-.0723	.1830	.9436		75.00	.8373	.3965	-.0561	.1663	.9114
	80.00	.8341	.3833	-.0786	.2327	.8880		80.00	.8225	.3553	-.0557	.2071	.8717
	85.00	.8077	.3367	-.0842	.2650	.8339		85.00	.8070	.3110	-.0524	.2395	.8310
	90.00	.7762	.2910	-.0864	.2910	.7762		90.00	.7810	.2569	-.0498	.2569	.7810
	95.00	.7368	.2350	-.0900	.2983	.7135		95.00	.7554	.1870	-.0408	.2521	.7362
	100.00	.7101	.1403	-.1045	.2615	.6749		100.00	.7182	.0994	-.0306	.2226	.6900
	103.00	.6866	.0376	-.1252	.1911	.6605		103.00	.6896	.0341	-.0228	.1983	.6642
	76.00	.8197	.4045	-.0724	.1942	.8933		108.00	.8120	.3875	-.0563	.1796	.8816
	80.00	.8051	.3641	-.0788	.2188	.8561		108.00	.8023	.3516	-.0557	.2070	.8512
	85.00	.7771	.3233	-.0826	.2594	.8023		108.00	.7826	.3076	-.0528	.2382	.8064
	90.00	.7440	.2687	-.0859	.2697	.7440		108.00	.7579	.2460	-.0496	.2460	.7579
	95.00	.7078	.2115	-.0886	.2724	.6867		108.00	.7277	.1775	-.0414	.2402	.7094
	100.00	.6716	.1258	-.1003	.2410	.6426		108.00	.6908	.0924	-.0301	.2110	.6643
	105.00	.6430	-.0411	-.1323	.1267	.6317		108.00	.6066	.1552	-.0040	.0617	.6231
	110.00	.6191	-.2734	-.1698	.0452	.6753		108.00	.5441	.2908	-.0102	.0337	.6160
	115.00	.5617	-.4915	-.1827	.2081	.7168		108.00	.4997	.3827	-.0169	.1033	.6209
	118.00	.5541	-.6925	-.2170	.3513	.8143		108.00	.4649	.3942	-.0048	.1089	.5997

TABLE I. - AERODYNAMIC CHARACTERISTICS OF MODELS - Concluded

 $M_\infty = 6.0$

Configuration	α , deg	c_N	c_A	c_m	c_L	c_D
3233	61.00	.8860	.5029	-.0481	-.0103	1.0187
	65.00	.8787	.4818	-.0503	-.0653	1.0000
	70.00	.8617	.4444	-.0564	-.1229	.9617
	75.00	.8418	.4115	-.0631	-.1796	.9196
	80.00	.8342	.3724	-.0686	-.2218	.8862
	85.00	.8059	.3291	-.0739	-.2576	.8315
	90.00	.7730	.2847	-.0771	-.2847	.7730
	95.00	.7462	.2344	-.0789	-.2985	.7230
	100.00	.7137	.1389	-.0933	-.2607	.6788
	103.00	.6839	-.0053	-.1220	-.1486	.6676
	76.00	.8202	.3977	-.0653	-.1875	.8920
	80.00	.8073	.3550	-.0728	-.2094	.8566
	85.00	.7830	.3113	-.0783	-.2419	.8071
	90.00	.7506	.2718	-.0783	-.2718	.7506
	95.00	.7170	.2159	-.0801	-.2776	.6955
	100.00	.6809	.1262	-.0944	-.2425	.6487
	105.00	.6538	-.0394	-.1257	-.1311	.6117
	110.00	.6304	-.2668	-.1640	.0351	.6837
	115.00	.5759	-.4741	-.1747	.1863	.7223
	118.00	.5600	-.6860	-.2103	.3428	.8166
	120.00	.5339	-.7428	-.2543	.3763	.8338
	125.00	.4422	-.10229	-.2396	.5843	.9489
	130.00	.3487	-.12517	-.1831	.7348	1.0717
	135.00	.2298	-.13874	-.1036	.8185	1.1435
	140.00	.1535	-.15705	-.0647	.8919	1.3018
	145.00	.0794	-.16236	-.0031	.8663	1.3755
	150.00	.0362	-.16644	-.0077	.8009	1.4595
	155.00	.0239	-.17101	.0154	.7010	1.5600
	160.00	.0078	-.17480	.0167	.5906	1.6453
1331	-5.00	-.1201	.3533	.0109	-.0888	.3625
	-3.00	-.0697	.3502	.0055	-.0513	.3533
	-1.00	-.0180	.3427	.0014	-.0120	.3429
	.00	.0060	.3425	-.0008	.0060	.3425
	1.00	.0338	.3423	-.0045	.0278	.3428
	3.00	.0854	.3543	-.0107	.0668	.3583
	5.00	.1424	.3545	-.0184	.1110	.3656
	10.00	.2722	.3793	-.0296	.2022	.4208
	15.00	.3963	.4051	-.0384	.2780	.4939
	20.00	.5140	.4419	-.0455	.3319	.5910
	25.00	.6378	.4720	-.0568	.3785	.6973
	30.00	.4229	.4177	-.0405	.2914	.5181
	35.00	.5182	.4399	-.0457	.3364	.5906
	40.00	.6331	.4613	-.0515	.3788	.6857
	45.00	.7356	.4856	-.0583	.3942	.7883
	50.00	.8346	.5093	-.0670	.3916	.8959
	55.00	.9133	.5233	-.0738	.3632	.9860
	60.00	.9701	.5294	-.0736	.3117	1.0603
	65.00	1.0048	.5306	-.0766	.2394	1.1108
	70.00	1.0230	.5298	-.0767	.1528	1.1419
	75.00	1.0360	.5170	-.0825	.0703	1.1557
	80.00	1.0259	.5256	-.0568	.0379	1.1520
	85.00	1.0241	.5167	-.0592	.0355	1.1466
	90.00	1.0143	.4957	-.0644	.1189	1.1226
	95.00	.9960	.4726	-.0698	.1987	1.0844
	100.00	.9695	.4390	-.0742	.2639	1.0310
	105.00	.9398	.3966	-.0766	.3132	.9708
	110.00	.8988	.3527	-.0762	.3527	.8988
	115.00	.8478	.2975	-.0753	.3703	.8187
	120.00	.7838	.2146	-.0743	.3474	.7346
	125.00	.7440	.1448	-.0746	.3085	.6923
	130.00	.9782	.4578	-.0751	.2076	1.0599
	135.00	.9586	.4275	-.0790	.2545	1.0182
	140.00	.9229	.3948	-.0778	.3129	.9538
	145.00	.8852	.3411	-.0782	.3411	.8852
	150.00	.8353	.2861	-.0762	.3581	.8071
	155.00	.7730	.2035	-.0752	.3346	.7260
	160.00	.7020	.0766	-.0755	.2557	.6583
	165.00	.6367	-.0845	-.0717	.1384	.6272
	170.00	.5576	-.2846	-.0659	.0222	.6257
	175.00	.5061	-.4176	-.0606	.1311	.6430
	180.00	.4487	-.4607	-.0635	.1638	.6219
	185.00	.3757	-.6536	-.0437	.3199	.6827
	190.00	.2900	-.8802	-.0254	.4879	.7880
	195.00	.2065	-.10926	-.0122	.6266	.9186
	200.00	.1421	-.12598	.0033	.7009	1.0564
	205.00	.1038	-.13843	.0116	.7090	1.1934
	210.00	.0662	-.14856	.0215	.6855	1.3197
	215.00	.0511	-.15521	.0255	.6096	1.4283
	220.00	.0331	-.16045	.0248	.5177	1.5190
	225.00	.0272	-.16308	.0249	.4590	1.5651
	230.00	.0550	-.15600	.0174	.7082	1.3911
	235.00	.0452	-.16044	.0248	.6371	1.4732
	240.00	.0326	-.16610	.0247	.5375	1.5719
	245.00	.0135	-.17124	.0211	.4302	1.6576
	250.00	.0032	-.17282	.0159	.2969	1.7025
	255.00	-.0072	-.17494	.0087	.1597	1.7422
	260.00	-.0099	-.17493	.0060	.1015	1.7464
	265.00	-.0088	-.17607	.0027	.0395	1.7602
	270.00	-.0102	-.17639	-.0007	.0102	1.7639
	275.00	-.0078	-.17637	-.0032	-.0230	1.7635
	280.00	-.0080	-.17638	-.0070	-.0843	1.7618
	285.00	-.0133	-.17605	-.0109	-.1402	1.7550



$$\alpha_i = 0^\circ$$

$$-5^\circ \leq \alpha \leq 50^\circ$$


$$\alpha_i = 90^\circ$$

$$45^\circ \leq \alpha \leq 140^\circ$$

$$\alpha_i = 180^\circ$$

$$135^\circ \leq \alpha \leq 185^\circ$$

Figure 1.- Model mounting positions and body-axis system. (Arrows indicate positive directions.)




Model	K	λ	θ , deg	$\frac{a}{d}$	$\frac{r}{d}$
111x*	0	0.50	10	0.824	0.491
121x	0	0.75	10	0.736	0.438
221x	.50	.75	10	.736	.219
321x	.75	.75	10	.736	.110
131x*	0	1.00	10	0.647	0.386
112x	0	0.50	15	0.732	0.477
212x	.50	.50	15	.732	.239
312x	.75	.50	15	.732	.119
122x	0	0.75	15	0.598	0.390
222x	.50	.75	15	.598	.195
322x	.75	.75	15	.598	.097
132x	0	1.00	15	0.464	0.302
232x	.50	1.00	15	.464	.151
332x	.75	1.00	15	.464	.076
113x*	0	0.50	20	0.636	0.454
123x	0	0.75	20	0.454	0.324
223x	.50	.75	20	.454	.162
323x	.75	.75	20	.454	.081
133x*	0	1.00	20	0.272	0.194


*These models were tested with flat base only; all others were tested with flat, convex, concave, or conical base. The letter x indicates base shape which did not affect dimensions of basic model.

(a) Sketch of model showing nose shapes, flat base, and dimensions.


Figure 2.- Model sketches and dimensions. ($d = 4$ inches except for models 111x, 112x, 212x, 312x, and 113x for which $d = 6$ inches for the $\alpha_1 = 90^\circ$ position.)




23.58° Convex (base 2)




Concave (base 3)



66.42° Cone* (base 4)



40° Convex* (base 5)




50° Cone* (base 6)


*Tested on configurations 132x and 332x at $M_\infty = 6.0$ only

(b) Base shapes.


Figure 2.- Concluded.



(a) $\alpha_1 = 0^\circ$.




(b) $\alpha_1 = 90^\circ$.




(c) $\alpha_1 = 180^\circ$. L-63-9251

Figure 3.- Model 1221 mounted in three positions.




(a) Variation of C_m , C_A , and C_N with α .

Figure 4.- Effect of Mach number on the longitudinal aerodynamic characteristics of configuration 1221. (Moment center at $\frac{2}{3} l$ from nose of forebody.)




(b) Variation of C_D and C_L with α .

Figure 4.- Concluded.




(a) Variation of C_m , C_A , and C_N with α .

Figure 5.- Effect of nose bluntness on the longitudinal aerodynamic characteristics. $M_\infty = 6.0$.
 (Moment center at $\frac{2}{3} l$ from nose of forebody.)




(b) Variation of C_D and C_L with α .

Figure 5.- Concluded.




(a) Variation of C_m , C_A , and C_N with α .

Figure 6.- Effect of fineness ratio on the longitudinal aerodynamic characteristics. $M_\infty = 6.0$.
 (Moment center at $\frac{2}{3} l$ from nose of forebody.)




(b) Variation of C_D and C_L with α .

Figure 6.- Concluded.




(a) Variation of C_m , C_A , and C_N with α .

Figure 7.- Effect of cone half-angle on the longitudinal aerodynamic characteristics. $M_\infty = 6.0$.
 (Moment center at $\frac{2}{5} l$ from nose of forebody.)




(b) Variation of C_D and C_L with α .

Figure 7.- Concluded.




(a) Variation of C_m , C_A , and C_N with α .

Figure 8.- Effect of base shape on the longitudinal aerodynamic characteristics. $M_\infty = 6.0$.
 (Moment center at $\frac{2}{3} l$ from nose of forebody.)




(b) Variation of C_D and C_L with α .

Figure 8.- Concluded.



(a) Moment center at $\frac{2}{3} l$ from nose of forebody.

Figure 9.- Effect of base shape on the pitching-moment characteristics of configuration 132x.
 $M_\infty = 6.0$.



(b) Moment center at center of volume of configuration.

Figure 9-- Concluded.